

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21004653/BBS3Q2**Date:** 02/07/2021REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SLV3187S	Insured Vehicle No :	SLL3149E
Date of Loss:	10/04/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0001665

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV3187S	Engine No:	G4FGHU835953
Make & Model:	HYUNDAI ELANTRA, 1.6 AD GLS (A)	Chassis No:	KMHD841CMJU592399
Reg. Date:	28/12/2017 (Man. Year: 2017)	Odometer:	77519 km
Colour:	Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,937.16	7,133.08	6,804.08	48.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,830.00	2,050.00	2,780.00	57.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,767.16	9,183.08	9,584.08	51.07
Approved Total (Overridden) (S\$)		6,750.00		

	(S\$)	18,767.16	6,750.00	12,017.16	64.03
+ GST 7.00/7.00% (S\$)		1,313.70	472.50	841.20	64.03
Nett Amount (S\$)		20,080.86	7,222.50	12,858.36	64.03
+ Loss of Use (7.0 x S\$60.00/day) (S\$)			420.00		
+ Doc/Search Fee (S\$)			7.45		
Nett Liability (S\$)			7,649.95		

INSPECTION

Date of Assignment: 13/04/2021

Date Inspected: 14/04/2021

Inspected At:

Bifrost Auto Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 7.0 days

Adjuster: Lim Teow Guan**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 Jun 2021)
Parts: 143	HYUNDAI ELANTRA 1.6 AD GLS (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLV3187S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	474.40 FL	*474.40 FL
2	1		*FRONT BUMPER CENTRE RUBBER SEAL	No such part	28.40 FL	*- FL
3	1		*BONNET	Not Damaged	1,749.70 FL	*- FL
4	1		*FRONT BUMPER NUMBER PLATE GARNISH	Not Damaged	74.10 FL	*- FL
5	1		*FRONT BUMPER RH SIDE RETAINER	Necessary	28.00 FL	*28.00 FL
6	1		*FRONT BUMPER LH SIDE RETAINER	Necessary	28.00 FL	*28.00 FL
7	1		*FRONT BUMPER INNER SPONGE	Broken	100.70 FL	*100.70 FL
8	1		*FRONT BUMPER UPPER REINFORCEMENT	No such part	695.80 FL	*- FL
9	1		*FRONT BUMPER LOWER REINFORCEMENT	No such part	85.10 FL	*- FL
10	1		*FRONT BUMPER RH FOG LAMP COVER	Not Damaged	115.40 FL	*- FL
11	1		*FRONT BUMPER RH FOG LAMP	Not Damaged	265.10 FL	*- FL
12	1		*FRONT BUMPER LH FOG LAMP COVER	Not Damaged	115.40 FL	*- FL
13	1		*FRONT BUMPER LH FOG LAMP	Not Damaged	265.10 FL	*- FL
14	1		*FRONT BLACK GRILLE RH SENSOR	No such part	202.20 FL	*- FL
15	1		*FRONT BLACK GRILLE LH SENSOR	No such part	202.20 FL	*- FL
16	1		*SUPPORT PANEL	No such part	949.30 FL	*- FL
17	1		*AIRCON CONDENSER	No such part	745.10 FL	*- FL
18	1		*RH HEADLAMP	Broken	1,198.80 FL	*1,198.80 FL
19	1		*RH HEADLAMP SUPPORT BRACKET	No such part	24.00 FL	*- FL
20	1		*LH HEADLAMP	Broken	1,198.80 FL	*1,198.80 FL
21	1		*LH HEADLAMP SUPPORT BRACKET	No such part	24.00 FL	*- FL
22	1		*REAR BUMPER	Broken	520.40 FL	*489.40 FL
23	1		*REAR BUMPER RH SIDE RETAINER	Necessary	44.30 FL	*44.30 FL
24	1		*REAR BUMPER RH SPLASH SHIELD	Broken	42.10 FL	*42.10 FL
25	1		*REAR WINDSCREEN GLASS RUBBER SEAL	Necessary	79.20 FL	*79.20 FL
26	1		*RH REAR FENDER	Dented	1,768.30 FL	*1,768.30 FL
27	1		*RH REAR FENDER TRANSPARENT STICKER	No such part	24.80 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*RH TAILLAMP	Broken	362.60 FL	*362.60 FL
29	1		*RH REAR KNUCKLE ARM	Bent	387.05 FL	*387.05 FL
30	1		*RH REAR WHEEL BEARING	Jammed	452.00 FL	*302.00 FL
31	1		*RH REAR SHOCK ABSORBER	Bent	341.90 FL	*341.90 FL
32	1		*RH REAR LOWER ARM	Bent	401.00 FL	*387.00 FL
33	1		*RH REAR UPPER ARM	Bent	162.30 FL	*162.30 FL
34	1		*RH REAR TRAILING ARM	Bent	278.40 FL	*209.00 FL
35	1		*SET FRONT BUMPER CLIPS	Necessary	70.00 FS	*30.00 FS
36	1		*FRONT NUMBER PLATE	Not Damaged	70.00 FS	*- FS
37	1		*FRONT BUMPER LOWER SPOILER	Not Damaged	900.00 FS	*- FS
38	1		*FRONT BLACK GRILLE	Cut	750.00 FS	*750.00 FS
39	1		*SET FRONT BLACK GRILLE CLIPS	No such part	60.00 FS	*- FS
40	1		*SET REAR BUMPER CLIPS	Necessary	70.00 FS	*30.00 FS
41	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	70.00 FS	*40.00 FS
42	1		*REAR WINDSCREEN GLASS INNER SEAL	Repeated	50.00 FS	*- FS
43	1		*RH REAR SPORT RIM	Not Damaged	800.00 FS	*- FS
44	1		*RH REAR TYRE	Punctured	350.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,623.95	8,653.85
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,686.79	1,520.77
Total Parts (\$\$)	13,937.16	7,133.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE CHECK ,REPLACE AND REINSTALL DAMAGES BODYPARTS TO PANEL BEATING ,CUT/WELD AND REALIGN ALL AFFECTED PANELS (FRONT PORTION)	New	800.00	200.00
2	SPRAY PAINTING ON AFFECTED PANELS (FRONT PORTION)	New	700.00	250.00
3	LABOUR CHARGES TO REMOVE ,CHECK ,REPLACE AND REINSTALL DAMAGES BODYPARTS ,TO PANEL BEATING ,CUT/WELD AND RE-ALIGN ALL AFFECTED PANELS (REAR PORTION)	New	1,000.00	600.00
4	SPRAY PAINTING ON AFFECTED PANELS (REAR PORTION)	New	1,000.00	600.00
5	CHECK WIRING AND LIGHTING SYSTEM (FRONT AND REAR)	New	100.00	30.00
6	APPLY RUST COATING ON AFFECTED AREAS	New	80.00	30.00
7	REMOVE AND REPLACE AIRCON CONDENSER AND PIPES TO FACILITATE REPAIRS .TO REFILL AIRCON GAS	New	180.00	0.00
8	REMOVE AND REPLACE RADIATOR HOSES AND FAN ASSY TO FACILITATE REPAIRS .TO REFILL RADIATOR COOLANT	New	180.00	0.00
9	REMOVE AND REINSTALL REAR WINDSCREEN GLASS TO FACILITATE REPAIRS	New	180.00	120.00
10	REMOVE AND REINSTALL REAR INNER TRIMS ,GARNISH ,ROOF LINING AND SEATS TO FACILITATE REPAIRS	New	250.00	0.00
11	REMOVE AND REINSTALL REAR BUMPER REVERSE SENSORS TO FACILITATE REPAIRS	New	40.00	40.00
12	CONDUCT TEST DRIVE AND ADJUST WHEEL ALIGNMENT SYSTEM	New	100.00	60.00
13	REMOVE AND REPLACE REAR UNDERCARRIAGE PARTS TO FACILITATE REPAIRS	New	220.00	120.00
Gross Labour Cost (S\$)			4,830.00	2,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >