

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21004657/AVCN2**Date:** 07/09/2021**REFERENCE**

Insured/Claimant:	THAM CHING HIONG	Policy No:	1900247537	
Date of Loss:	08/04/2021	Nature of Claim:	OD	Claim No: 7853903361SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ5039M		
Make & Model:	AUDI Q3, 1.4 TFSI (A)	Engine No:	CZD884429
Reg. Date:	21/11/2019 (Man. Year: 2019)	Chassis No:	WAUZZZF39L1021914
Colour:	Grey	Odometer:	16804 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$135,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55R18	Rear Tyre Size:	235/55R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,391.00	654.80	5,736.20	89.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,632.00	3,022.00	4,610.00	60.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,023.00	3,676.80	10,346.20	73.78
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	13,223.00	2,876.80	10,346.20	78.24
+ GST 7.00/7.00% (S\$)	925.61	201.38	724.23	78.24
Nett Amount (S\$)	14,148.61	3,078.18	11,070.43	78.24

INSPECTION

Date of Assignment:	13/04/2021		
Date Inspected:	13/04/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR-LH	Repair	2,909.00 FS	*- FS
2	1		*REAR DOOR OUTER SEAL-LH	Not Necessary	135.00 FS	*- FS
3	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	311.00 FS	*- FS
4	1		*REAR DOOR CATCH	Not Necessary	120.00 FS	*- FS
5	1		*REAR DOOR ARCH COVER-LH	Cut	257.00 FS	*205.20 FS
6	1		*REAR WHEEL ARCH COVER-LH/RH	N/s Cut	536.00 FS	*214.40 FS
7	1		*REAR BUMPER UPPER GUIDE SECTION-LH	Not Necessary	63.00 FS	*- FS
8	1		*REAR WHEEL RIM	Not Necessary	1,566.00 FS	*- FS
9	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS
10	1		*FRONT DOOR COVER-LH (Supplementary)	Cut	268.00 FS	*214.40 FS
11	1		*WHEEL ARCH TRIM GROMMET (Suplementary)	Necessary	26.00 FS	*20.80 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					6,391.00	654.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION	New	360.00	0.00
2	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES	New	400.00	400.00
3	TO DISMANTLE AND REINSTALL REAR BUMPER.TO RENEW LHS REAR DOOR.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,400.00	500.00
4	TO RESPRAY REAR BUMPER,LHS REAR FENDER AND LHS REAR DOOR	New	3,000.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
6	TO RESPRAY LHS FRONT DOOR (Supplementary)	New	1,000.00	550.00
7	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM.TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY FOR LHS FRONT DOOR (Supplementary)	New	280.00	280.00
Gross Labour Cost (\$\$)			7,632.00	3,022.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >