



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 5422P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER (CONSISTENT)	TO REPAIR SEE LABOUR	1,156.00	-
1	FRONT BUMPER BRACKET L/H (CONSISTENT)	SERVICEABLE	70.20	-
8	FRONT BUMPER CLIP @\$7.60 (CONSISTENT)	NOT NECESSARY	60.80	-
1	FRONT BUMPER SIDE RETAINER L/H (CONSISTENT)	SERVICEABLE	132.00	-
1	FRONT FENDER L/H (CONSISTENT)	TO REPAIR SEE LABOUR	599.70	-
1	FRONT FENDER INNER SHIELD L/H (CONSISTENT)	SERVICEABLE	201.40	-
1	FRONT SHOCK ABSORBER L/H (CONSISTENT)	BENT	265.90	220.60
1	FRONT WHEEL BEARING L/H (CONSISTENT)	NECESSARY	286.00	286.00
1	FRONT LOWER ARM L/H (CONSISTENT)	BENT	411.80	311.60
	LESS 15% DISCOUNT		-477.57	-122.73
			2,706.23	695.47
<b><u>LABOUR</u></b>				
	COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	120.00	60.00
	RUST PROOFING TREATMENT .		100.00	-
	SPRAY PAINT DAMAGED AREA AFFECTED .		900.00	400.00
	REMOVE & REINSTALL FRONT SUSPENSION L/H.		250.00	160.00
	TO KNOCK & STRAIGHTEN L/H FRONT CHASSIS FRAME AND ALL NECESSARY PARTS.INCLUSIVE OF THE REPAIR OF FRONT BUMPER AND FRONT FENDER L/H .		1,100.00	100.00
			2,470.00	720.00
<b>GRAND TOTAL</b>			<b>5,176.23</b>	<b>1,415.47</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,100.00</b>

Report Ref No. CC4/ASM21004660/Kga3q2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.