



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YN 367Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAIL LAMP, RH	BROKEN	150.00	150.00
	LESS 25% DISCOUNT		-37.50	-37.50
			112.50	112.50
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER (SN)	BENT	280.00	250.00
1	STAINLESS STEEL FRAME, RH (SN)	BUCKLED	500.00	450.00
1	ALUMINIUM CORNER FRAME, RH (SN)	CRACKED	160.00	160.00
1	PANEL C/W GRP, RH (SN)	DEFORMED	400.00	350.00
1	BOTTOM PANEL C/W ALUMINIUM CHECKER PLATE, RH (SN)	CRACKED	160.00	160.00
1	RUBBER BUFFER (SN)	CUT	105.00	105.00
1	BOTTOM STAINLESS STEEL FRAME, RH (SN)	BENT	600.00	500.00
			2,205.00	1,975.00
	<u>LABOUR</u>			
	REMOVE & RENEW REAR BUMPER.		240.00	200.00
	REPAIR EXHAUST PIPE.		160.00	100.00
	REMOVE & RENEW STAINLESS STEEL FRAME, ALUMINIUM CORNER FRAME, GRP PANEL, BOTTOM PANEL C/W ALUMINIUM CHECKER PLATE, RUBBER BUFFER & BOTTOM STAINLESS STEEL FRAME.		800.00	600.00
	SPRAY PAINT REAR BUMPER & EXHAUST PIPE.		400.00	200.00
			1,600.00	1,100.00
GRAND TOTAL			3,917.50	3,187.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,550.00

Report Ref No. CS/SMR21004663/R1uf3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.