

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURAN	NCE BHD		Ref:	CS3/LPC21004664/T1vf3e2	
	300 BEACH ROAD CONCOURSESING			Date:	19/04/2021	
				Code:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	XD 7965P	Veh. Inspected		SMY 9699P	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	20/21/21/VC05/024444	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		13/04/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	B.M.W. 420I COUPE	c.c		1997	
	Engine No.	HIDDEN	Year of Reg.		2014	
	Chassis No.	WBA3N12050F994916	Colour		GREY	
	Odometer	157826 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	245/35 R19	MICHELIN		6 mm	
	L/H Front Tyre	245/35 R19	MICHELIN		6 mm	
	R/H Rear Tyre	245/35 R19	MICHELIN		6 mm	
	L/H Rear Tyre	245/35 R19	MICHELIN		6 mm	
4. Description of Damages						
	THE VEHICLE SUS	STAINED DAMAGES AT THE FRONT N/S PORTION.				
5.	General Information					
	Accident Date	12/04/2021	Inspect Date /	Time	13/04/2021 (05:12 PM)	
	Survey held at	GFORCE AUTOTECH PTD LTD				
		10 KAKI BUKIT ROAD 2 #01-34 FIRST EAST CENTRE SINGAPORE 417868				
5a.		Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC21004664/T1vf3e2

Inspected By

MOHAMAD TAUFIKH M.MATAI, AMSAE-A K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor