

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21004666/AGA3Q2**Date:** 28/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800087814
Claimant Vehicle No :	SKN8892K	Insured Vehicle No :	SMC8208X
Date of Loss:	12/04/2021	Nature of Claim:	TP
		Claim No:	7040880506SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKN8892K	Engine No:	CVK056499
Make & Model:	AUDI A4, 2.0 TFSI S-TRONIC (A)	Chassis No:	WAUZZZF45JA124687
Reg. Date:	26/04/2018 (Man. Year: 2018)	Odometer:	66432 km
Colour:	White		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,446.00	1,943.60	2,502.40	56.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,502.00	1,602.00	900.00	35.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,948.00	3,545.60	3,402.40	48.97
+ GST 7.00/7.00% (S\$)	486.36	248.19	238.17	48.97
Nett Amount (S\$)	7,434.36	3,793.79	3,640.57	48.97
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,975.79		

INSPECTION

Date of Assignment:	14/04/2021		
Date Inspected:	14/04/2021	Inspected At:	Premium Automobiles Pte Ltd (HQ) 55 UBI ROAD 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,181.00 FS	*1,744.80 FS
2	1		*REAR BUMPER FIXING PARTS (NPA)	Not Necessary	0.00 FS	*- FS
3	1		*REAR BUMPER SECURING STRIP	Not Necessary	223.00 FS	*- FS
4	1		*REAR BUMPER SPOILER	Cut	249.00 FS	*198.80 FS
5	2		*REAR LIGHT REFLECTOR -LH/RH	Not Necessary	82.00 FS	*- FS
6	1		*REAR BUMPER CARRIER	Not Necessary	940.00 FS	*- FS
7	2		*REAR BUMPER SEAL	Not Necessary	28.00 FS	*- FS
8	2		*REAR BUMPER GUIDE SECTION -LH/RH	Not Necessary	46.00 FS	*- FS
9	2		*REAR BUMPER PARKING AID SENSOR -INNER -OUTER	Not Necessary	488.00 FS	*- FS
10	4		*REAR BUMPER PARKING AID SENSOR SEAL RING	Not Necessary	9.00 FS	*- FS
11	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS
					Total Parts (S\$)	4,446.00 1,943.60

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR PARKING AID REAR LID KICK SENSOR CHECK FUNCTION	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
3	TO RESPRAY REAR BUMPER	New	900.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			2,502.00	1,602.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >