

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG21004667/ATCE2**Date:** 02/11/2021**REFERENCE**

Insured/Claimant: YAO SISI Policy No: 7210019451  
Date of Loss: 09/04/2021 Nature of Claim: OD Claim No: 4151523138SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SMY2622G**  
Make & Model: AUDI Q3, 1.4 TFSI (A) Engine No: CZDC18829  
Reg. Date: 25/02/2021 (Man. Year: 2020) Chassis No: WAUZZZF3XM1046161  
Colour: Black Odometer: 1644 km  
Engine Capacity: 1395 cc  
Market Value/New Car Price: S\$155,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 215/65 R17 Rear Tyre Size: 215/65 R17  
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm  
Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	14,377.00	4,859.00	9,518.00	66.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,152.00	4,232.00	2,920.00	40.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>21,529.00</b>	<b>9,091.00</b>	<b>12,438.00</b>	<b>57.77</b>
<b>- Excess (S\$)</b>	<b>3,800.00</b>	<b>3,800.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>17,729.00</b>	<b>5,291.00</b>	<b>12,438.00</b>	<b>70.16</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,241.03</b>	<b>370.37</b>	<b>870.66</b>	<b>70.16</b>
<b>Nett Amount (S\$)</b>	<b>18,970.03</b>	<b>5,661.37</b>	<b>13,308.66</b>	<b>70.16</b>

**INSPECTION**

Date of Assignment: 13/04/2021  
Date Inspected: 12/04/2021 Inspected At: Premium Automobiles Pte Ltd (UBI)  
55 Ubi Road 1  
Singapore 408699  
Estimated Period of Repair: 6.0 days

**Adjuster:** ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$480.00 NETT)

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,008.00 FS	*1,008.00 FS
2	1		*FRONT BUMPER CONNECTING PIECE	Not Necessary	145.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT - LH	Not Necessary	59.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	217.00 FS	*- FS
5	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Missing	153.00 FS	*153.00 FS
6	1		*FRONT BUMPER LOWER GRILLE - LH	* Check	110.00 FS	*- FS
7	1		*FRONT BUMPER SPOILER - LH	Cut	383.00 FS	*383.00 FS
8	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	190.00 FS	*- FS
9	1		*FRONT RADIATOR GRILLE	Cut	1,433.00 FS	*1,433.00 FS
10	1		*FRONT RADIATOR STRIKER PLATE	Not Necessary	244.00 FS	*- FS
11	1		*FRONT PARKING AID SENSOR	Not Necessary	244.00 FS	*- FS
12	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS
13	1		*HIGH TONE SIGNAL HORN - LH	Not Necessary	137.00 FS	*- FS
14	1		*HIGH TONE SIGNAL HORN SPRING SHACKLE - LH	Not Necessary	22.00 FS	*- FS
15	1		*FRONT FENDER - LH	Dented	1,286.00 FS	*1,286.00 FS
16	1		*FRONT FENDER ATTACHMENT PARTS - LH	Not Necessary	63.00 FS	*- FS
17	1		*FRONT FENDER BRACE - LH	* Check	88.00 FS	*- FS
18	1		*FRONT FENDER BRACKET - LH	* Check	32.00 FS	*- FS
19	1		*HEADLIGHT MOUNTING BEAM - LH	Not Necessary	118.00 FS	*- FS
20	1		*HEADLIGHT - LH	Not Necessary	5,589.00 FS	*- FS
21	1		*HEADLIGHT LIFT CYLINDER - LH	Not Necessary	210.00 FS	*- FS
22	1		*HEADLIGHT LIFT CYLINDER HOSE - LH	Not Necessary	80.00 FS	*- FS
23	1		*HEADLIGHT LIFT CYLINDER WATER RESERVOIR - LH	Not Necessary	220.00 FS	*- FS
24	1		*FRONT WHEEL COVER ARCH - LH / RH	N/S Cut / O/S Necessary	536.00 FS	*536.00 FS
25	1		*OUTER WINDOW SLOT SEAL - LH	Not Necessary	224.00 FS	*- FS
26	1		*FRONT ALUMINIUM RIM - LH	Not Necessary	1,262.00 FS	*- FS
27	1		*FRONT NUMBER PLATE	Necessary	60.00 FS	*60.00 FS
28	1		*SUNDRIES	* Check	250.00 FS	*- FS

F=Franchise part. S=SpcNett.

**Total Parts (\$)** **14,377.00**      **4,859.00**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTSS CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF THE LHS FRONT DOOR	New	400.00	360.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,400.00	1,000.00
5	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER & LHS FRONT DOOR	New	3,000.00	2,200.00
6	TO RENEW LHS FRONT RIM. TO CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
7	TO CARRY OUT DIASNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>7,152.00</b>	<b>4,232.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >