

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21004670/BGS3Q2
Date: 05/11/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SMS3676B	Insured Vehicle No :	SLM6993J
Date of Loss:	10/04/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0001682

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS3676B		
Make & Model:	TOYOTA SIENTA, 1.5 (A)	Engine No:	2NRX530255
Reg. Date:	24/02/2020 (Man. Year: 2019)	Chassis No:	MHFZ28H3X00067563
Colour:	Silver	Odometer:	16961 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/50 R16	Rear Tyre Size:	195/50 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,595.13	2,017.30	5,577.83	73.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,650.00	1,050.00	1,600.00	60.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,245.13	3,067.30	7,177.83	70.06
Approved Total (Overridden) (S\$)		2,450.00		

(S\$)	10,245.13	2,450.00	7,795.13	76.09
+ GST 7.00/7.00% (S\$)	717.16	171.50	545.66	76.09
Nett Amount (S\$)	10,962.29	2,621.50	8,340.79	76.09
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,128.95		
Global Sum Settlement (S\$)		3,100.00		

INSPECTION

Date of Assignment: 13/04/2021

Date Inspected: 13/04/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Bifrost Auto Pte Ltd (Kaki Bukit)
 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
 Singapore 415875

Adjuster: Lim Teow Guan**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Jul 2021)
Parts:	M1-MPV	TOYOTA SIENTA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMS3676B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH SLIDING DOOR	Dented	1,217.45 FL	*1,180.00 FL
2	1		*RH SLIDING DOOR LOWER PROTECTOR	Cut	561.60 FL	*198.60 FL
3	1		*RH SLIDING DOOR BLACK FRAME GARNISH STICKER (FRONT)	No such part	274.70 FL	*- FL
4	1		*RH SLIDING DOOR BLACK FRAME GARNISH STICKER (REAR)	No such part	274.45 FL	*- FL
5	1		*RH SLIDING DOOR INNER TRIM BOARD	Not Damaged	781.90 FL	*- FL
6	1		*RH SLIDING DOOR LOWER ROLLER	Not Damaged	289.90 FL	*- FL
7	1		*RH REAR FENDER LOWER PROTECTOR	Cut	371.45 FL	*198.60 FL
8	1		*RH REAR FENDER	Dented	1,345.21 FL	*1,072.54 FL
9	1		*RH REAR WHEEL BEARING	Not Damaged	715.00 FL	*- FL
10	1		*REAR AXLE BEAM	Not Damaged	2,721.85 FL	*- FL
11	1		*RH REAR SPORT RIM	Not Damaged	700.00 FS	*- FS
12	1		*RH REAR TYRE	Not Damaged	300.00 FS	*- FS
13	1		*RH REAR FENDER GLASS SEALANT	Not Necessary	50.00 FS	*- FS
14	1		*SET REAR BUMPER CLIPS	Necessary	70.00 FS	*30.00 FS
15	1		*SET RH SLIDING DOOR INNER TRIM BOARD CLIPS	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,733.51	2,679.74
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,138.38	662.44
Total Parts (\$\$)	7,595.13	2,017.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES TO REMOVE ,CHECK ,REPLACE AND REINSTALL DAMAGES BODYPARTS ,TO PANEL BEATING ,CUT/WELD AND RE-ALIGN ALL AFFECTED PANELS	New	1,000.00	600.00
2	SPRAY PAINTING ON AFFECTED PANELS	New	1,000.00	400.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	50.00	0.00
4	APPLY RUST COATING ON AFFECTED AREAS	New	80.00	0.00
5	REMOVE AND REINSTALL RH SIDE INNER TRIMS,GARNISH ,BOARD AND ALL ATTACHMENTS TO FACILITATE TO REPAIRS	New	220.00	0.00
6	REMOVE AND REINSTALL RH REAR FENDER GLASS TO FACILITATE REPAIR	New	100.00	0.00
7	TRANSFER RH SLIDING DOOR INNER MECHANISM TO NEW DOOR	New	100.00	50.00
8	CONDUCT TEST DRIVE AND ADJUST WHEEL ALIGNMENT SYSTEM	New	100.00	0.00
Gross Labour Cost (\$\$)			2,650.00	1,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >