

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21004671/ETF3E2**Date:** 17/05/2021**REFERENCE**

Insured/Claimant:	HAAWAYZ	Policy No:	1700019216	
Date of Loss:	12/04/2021	Nature of Claim:	OD	Claim No: 4391867154SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP5231R		
Make & Model:	KIA NIRO, 1.6 HYBRID GDI DCT SUNROOF (A)	Engine No:	G4LEHS186824
Reg. Date:	08/06/2017 (Man. Year: 2017)	Chassis No:	KNACC81CVH5062458
Colour:	Black	Odometer:	81350 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	S\$72,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Cinturato 5 mm	Rear Left Side:	Cinturato 5 mm
Front Right Side:	Cinturato 5 mm	Rear Right Side:	Cinturato 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,126.00	8,727.20	398.80	4.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,980.00	2,990.00	1,990.00	39.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,106.00	11,717.20	2,388.80	16.93
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	13,106.00	10,717.20	2,388.80	18.23
+ GST 7.00/7.00% (S\$)	917.42	750.20	167.22	18.23
Nett Amount (S\$)	14,023.42	11,467.40	2,556.02	18.23

INSPECTION

Date of Assignment:	13/04/2021	
Date Inspected:	13/04/2021	Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	9.0 days	

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER-FR BUMPER UPR	Dented	632.00 FL	*632.00 FL
2	1		*COVER ASSY-FR BUMPER LWR	Cut	346.00 FL	*346.00 FL
3	1		*LOGO ASSY-KIA SUB	Necessary	51.00 FL	*51.00 FL
4	1		*CAP-FRONT HOOK	Crushed	7.00 FL	*7.00 FL
5	1		*BRACKET-FR BUMPER UPR SIDE MTG	Not Necessary	12.00 FL	*- FL
6	1		*BRACKET-FR BUMPER UPR SIDE MTG	Not Necessary	12.00 FL	*- FL
7	1		*PIECE-FRT BUMPER GUARD LWR, LH	Cut	16.00 FL	*16.00 FL
8	1		*PIECE-FRT BUMPER GUARD LWR, RH	Cut	16.00 FL	*16.00 FL
9	1		*DUCT ASSY-AIR CURTAIN, LH	Not Necessary	32.00 FL	*- FL
10	1		*DUCT ASSY-AIR CURTAIN, RH	Not Necessary	32.00 FL	*- FL
11	1		*AIR DUCT-FR BUMPER, LH	Not Necessary	39.00 FL	*- FL
12	1		*AIR DUCT-FR BUMPER, RH	Not Necessary	39.00 FL	*- FL
13	1		*COVER ASSY-RADIATOR GRILLE UPR	Crushed	40.00 FL	*40.00 FL
14	1		*GRILLE ASSY-RADIATOR	Cut	441.00 FL	*441.00 FL
15	1		*ABSORBER-FRONT BUMPER ENERGY	Broken	68.00 FL	*68.00 FL
16	1		*GRILLE-FRONT BUMPER	Broken	232.00 FL	*232.00 FL
17	1		*LAMP ASSY-FRONT FOG & DRL, LH	Broken	638.00 FL	*638.00 FL
18	1		*LAMP ASSY-FRONT FOG & DRL, RH	Broken	638.00 FL	*638.00 FL
19	1		*WIRING HARNESS-FR BUMPER	Not Necessary	134.00 FL	*- FL
20	1		*STIFFNER-FR BPR LWR	Not Necessary	116.00 FL	*- FL
21	1		*FLAP ASSY-ACTIVE AIR, LWR	Broken	328.00 FL	*328.00 FL
22	1		*BRACKET-FR BUMPER SIDE, LH	Broken	12.00 FL	*12.00 FL
23	1		*BRACKET-FR BUMPER SIDE, RH	Broken	12.00 FL	*12.00 FL
24	1		*PANEL ASSY-HOOD	Dented	1,222.00 FL	*1,222.00 FL
25	1		*HINGE ASSY-HOOD, LH	Bent	40.00 FL	*40.00 FL
26	1		*HINGE ASSY-HOOD, RH	Bent	40.00 FL	*40.00 FL
27	12		*CLIP-HOOD INSULATING PAD MTG	Necessary	12.00 FL	*12.00 FL
28	1		*LATCH ASSY-HOOD	Bent	123.00 FL	*123.00 FL
29	1		*CARRIER ASSY-FRONT END MODULE	Broken	675.00 FL	*675.00 FL
30	1		*BEAM COMPLETE-FR BUMPER	Bent	551.00 FL	*551.00 FL
31	1		*LAMP ASSY-HEAD, LH	Broken	904.00 FL	*904.00 FL
32	1		*LAMP ASSY-HEAD, RH	Broken	904.00 FL	*904.00 FL
33	1		*SPEAKER ASSY-VESS	Broken	149.00 FL	*149.00 FL
34	1		*CONDENSER ASSY-COOLER	Bent	639.00 FL	*639.00 FL
35	1		*RADIATOR ASSY-INVERTER	Bent	768.00 FL	*768.00 FL
36	1		*RADIATOR ASSY	Bent	492.00 FL	*492.00 FL
37	1		*GUARD-AIR, LH	Broken	29.00 FL	*29.00 FL
38	1		*GUARD-AIR, RH	Broken	29.00 FL	*29.00 FL
39	1		*GUARD-AIR RADIATOR, UPR	Not Necessary	15.00 FL	*- FL
40	1		*BLOWER ASSY	Broken	546.00 FL	*546.00 FL
41	1		*DAM-AIR	Not Necessary	27.00 FL	*- FL
42	1		*SUNDRIES	Necessary	30.00 FS	*20.00 FS
43	1		*STRIP ASSY-FR BUMPER UPR	Not Necessary	28.00 FL	*- FL
44	1		*CLIP-HOOD STAY ROD (Supplementary)	Necessary	2.00 FL	*2.00 FL
45	1		*COOLANT (4L) (Supplementary)	Necessary	26.00 FL	*26.00 FL
46	10		*RETAINER ASSY-BUMPER COVER MTG (Supplementary)	Necessary	20.00 FL	*20.00 FL
47	1		*DUCT ASSY-ACTIVE AIR (Supplementary)	Broken	78.00 FL	*78.00 FL
48	1		*HORN ASSY-LOW PITCH (Supplementary)	Shorted	79.00 FL	*79.00 FL
49	1		*HORN ASSY-HIGH PITCH (Supplementary)	Shorted	79.00 FL	*79.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$) **11,400.00** **10,904.00**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 20.00/20.00% (S\$)					2,274.00	2,176.80
Total Parts (S\$)					9,126.00	8,727.20
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER, BONNET & FRT SUPPORT. REPAIR LHF FENDER & RHF FENDER	New	2,400.00	800.00
2	RESPRAY FRT BUMPER, BONNET, LHF FENDER & RHF FENDER	New	1,400.00	1,050.00
3	RENEW AIRCON CONDENSER & RADIATOR	New	100.00	100.00
4	TOP UP AIRCON GAS	New	80.00	80.00
5	CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
7	SUPPLY FRT NUMBER PLATE WITH CASING	New	50.00	50.00
8	APPLY ANTI CORROSION ON AFFECTED AREAS	New	80.00	80.00
9	SUPPLY BODY PNL SEALANT	New	80.00	40.00
10	DISCONNECT MAIN BATTERY CABLE TO FACILITATE REPAIR	New	120.00	120.00
11	BLEED ON ENGINE COOLANT SYSTEM AFTER REPAIR (Supplementary)	New	120.00	120.00
12	REPLACE FRONT SUPPORT PANEL (Supplementary)	New	400.00	400.00
Gross Labour Cost (\$\$)			4,980.00	2,990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >