



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV13404/MR HAAWAYZ Reg No/Reg Date SLP5231R / 08/06/201 Date In/Mileage / 81350 Chassis No KNACC81CVH5062458 Engine No G4LEHS186824 Make/Model KIA/NIRO 1.6 A Colour/Trim ABP AURORA BLACK / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	13/04/2021/ 13:22	BLE	261 / Edwin Caina	31881		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRT BUMPER, BONNET & FRT SUPPORT 2 X 400 REPAIR LHF FENDER & RH FENDER							8M 2400.00
E PNT98000 RESPRAY FRT BUMPER, BONNET, LHF FENDER & RH FENDER 3 X 350							1950 1400.00
E PNT88000 RENEW AIRCON CONDENSER & RADIATOR							100.00
M SUNDRY TOP UP AIRCON GAS							80.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM							30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							120.00
M SUNDRY SUPPLY FRT NUMBER PLATE WITH CASING							50.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS							80.00
M SUNDRY SUPPLY BODY PNL SEALANT							40 80.00
M SUNDRY Sundries							20 30.00
A 54900099 DISCONNECT MAIN BATTERY CABLE TO FACILITATE REPAIR							120.00
M COVER-FR BUMPER UPR DO				1.00	632.00	20.00	505.60
M COVER ASSY-FR BUMPER LWR CR CUT				1.00	346.00	20.00	276.80
M LOGO ASSY-KIA SUB TRC				1.00	51.00	20.00	40.80
M CAP-FRONT HOOK CRU				1.00	7.00	20.00	5.60
M STRIP ASSY-FR BUMPER UPR 1 X NM				1.00	28.00	20.00	22.40
M BRACKET-FR BUMPER UPR SIDE MTG 1 X NM				1.00	12.00	20.00	9.60
M BRACKET-FR BUMPER UPR SIDE MTG 1 X NM				1.00	12.00	20.00	9.60
M PIECE-FRT BUMPER GUARD LWR,LH CUT				1.00	16.00	20.00	12.80
M PIECE-FRT BUMPER GUARD LWR,RH CUT				1.00	16.00	20.00	12.80

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV13404/MR HAAWAYZ Reg No/Reg Date SLP5231R / 08/06/201 Date In/Mileage / 81350 Chassis No KNACC81CVH5062458 Engine No G4LEHS186824 Make/Model KIA/NIRO 1.6 A Colour/Trim ABP AURORA BLACK / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	13/04/2021/ 13:22	BLE	261 / Edwin Caina	31881			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	DUCT ASSY-AIR CURTAIN,LH	?	X NM		1.00	32.00	20.00	25.60
M	DUCT ASSY-AIR CURTAIN,RH	?	X NM		1.00	32.00	20.00	25.60
M	AIR DUCT-FR BUMPER,LH	?	X NM		1.00	39.00	20.00	31.20
M	AIR DUCT-FR BUMPER,RH	?	X NM		1.00	39.00	20.00	31.20
M	COVER ASSY-RADIATOR GRILLE UPR	?	CRU		1.00	40.00	20.00	32.00
M	GRILLE ASSY-RADIATOR	?	CRU		1.00	441.00	20.00	352.80
M	ABSORBER-FRONT BUMPER ENERGY	?	OR		1.00	68.00	20.00	54.40
M	GRILLE-FRONT BUMPER	?	OR		1.00	232.00	20.00	185.60
M	LAMP ASSY-FRONT FOG & DRL,LH	?	OR		1.00	638.00	20.00	510.40
M	LAMP ASSY-FRONT FOG & DRL,RH	?	OR		1.00	638.00	20.00	510.40
M	WIRING HARNESS-FR BUMPER	?	X NM		1.00	134.00	20.00	107.20
M	STIFFNER-FR BPR LWR	?	X NM		1.00	116.00	20.00	92.80
M	FLAP ASSY-ACTIVE AIR,LWR	?	OR		1.00	328.00	20.00	262.40
M	BRACKET-FR BUMPER SIDE,LH	?	OR		1.00	12.00	20.00	9.60
M	BRACKET-FR BUMPER SIDE,RH	?	OR		1.00	12.00	20.00	9.60
M	PANEL ASSY-HOOD	?	OR		1.00	1222.00	20.00	977.60
M	HINGE ASSY-HOOD,LH	?	BT		1.00	40.00	20.00	32.00
M	HINGE ASSY-HOOD,RH	?	BT		1.00	40.00	20.00	32.00
M	CLIP-HOOD INSULATING PAD MTG	?	APC		12.00	1.00	20.00	9.60
M	LATCH ASSY-HOOD	?	BT		1.00	123.00	20.00	98.40
M	CARRIER ASSY-FRONT END MODULE	?	OR		1.00	675.00	20.00	540.00
M	BEAM COMPLETE-FR BUMPER	?	BT		1.00	551.00	20.00	440.80
M	LAMP ASSY-HEAD,LH	?	OR		1.00	904.00	20.00	723.20
M	LAMP ASSY-HEAD,RH	?	OR		1.00	904.00	20.00	723.20
M	SPEAKER ASSY-VESS	?	OR		1.00	149.00	20.00	119.20
M	CONDENSER ASSY-COOLER	?	BT		1.00	639.00	20.00	511.20
M	RADIATOR ASSY-INVERTER	?	BT		1.00	768.00	20.00	614.40
M	RADIATOR ASSY	?	BT		1.00	492.00	20.00	393.60
M	GUARD-AIR,LH	?	OR		1.00	29.00	20.00	23.20
M	GUARD-AIR,RH	?	OR		1.00	29.00	20.00	23.20
M	GUARD-AIR RADIATOR,UPR	?	X NM		1.00	15.00	20.00	12.00
M	BLOWER ASSY	?	OR		1.00	546.00	20.00	436.80
M	DAM-AIR	?	X NM		1.00	27.00	20.00	21.60

Estimate

Steve (LKK)
13/4/21, 2.00pm
OD- NM AL
Excess - ?
P/P

Steve (LKK)
13/4/21, 2.00pm
OD - NY AL
EXCESS - ?
P/P

My BCL SM
9 & dgs

Confirm & accepted by
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
Authorized signatory and company stamp

7% GST on Net 13,358.80
Total Payable 14,293.92

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.