

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21004672/UBS3Q2
Date: 17/06/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SGD2250C	Insured Vehicle No :	SLQ4227E
Date of Loss:	10/04/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0001709

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGD2250C		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CVT (A)	Engine No:	1ZRX521609
Reg. Date:	03/08/2015 (Man. Year: 2015)	Chassis No:	MR053REH104535960
Colour:	Silver	Odometer:	159396 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,882.22	3,305.75	2,576.47	43.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,430.00	2,230.00	1,200.00	34.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,312.22	5,535.75	3,776.47	40.55
Approved Total (Overridden) (S\$)		4,400.00		

(S\$)	9,312.22	4,400.00	4,912.22	52.75
+ GST 7.00/7.00% (S\$)	651.86	308.00	343.86	52.75
Nett Amount (S\$)	9,964.08	4,708.00	5,256.08	52.75
+ Car Rental (5.0 x S\$120.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,315.45		
Global Sum Settlement (S\$)		5,200.00		

INSPECTION

Date of Assignment: 13/04/2021

Date Inspected: 19/04/2021

Inspected At:

Hock Wah Motor Workshop Pte Ltd (Bedok)
 Blk 3011, Bedok Industrial Park E., #01-2008/2010/2012
 Singapore 489977

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 May 2021)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGD2250C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent /Buckled	793.20 FL	*793.20 FL
2	1		*BOOTLID LOCK	Twisted	399.50 FL	*399.50 FL
3	1		*BOOTLID WEATHERSTRIP	Twisted	175.80 FL	*175.80 FL
4	1		*BOOTLID EMBLEM	Necessary	50.70 FL	*50.70 FL
5	1		*BOOTLID LOGO-COROLLA	Necessary	41.00 FL	*41.00 FL
6	1		*BOOTLID LOGO-ALTIS	Necessary	45.60 FL	*45.60 FL
7	1		*BOOTLID LOWER LOCK COVER	Cracked	143.10 FL	*143.10 FL
8	1		*BOOTLID LAMP LH	Not Necessary	203.70 FL	*- FL
9	1		*BOOTLID LAMP RH	Not Necessary	203.70 FL	*- FL
10	1		*BOOTLID CHROME	Not Necessary	243.70 FL	*- FL
11	1		*END PANEL	Badly Dented	670.00 FL	*670.00 FL
12	1		*END PANEL TOP GARNISH	Twisted	241.90 FL	*241.90 FL
13	1		*TAIL LAMP RH	Cracked	391.70 FL	*391.70 FL
14	1		*TAIL LAMP LH	Not Necessary	391.70 FL	*- FL
15	4		*TAIL LAMP CLIP LH	Not Necessary	14.00 FL	*- FL
16	4		*TAIL LAMP CLIP RH	Necessary	14.00 FL	*14.00 FL
17	1		*SPARE TYRE PANELL	Repair	812.10 FL	*- FL
18	1		*SPARE TYRE PANELL TOP TRIMBOARD	Not Necessary	267.00 FL	*- FL
19	1		*REAR BUMPER	Distorted	556.40 FL	*556.40 FL
20	2		*REAR BUMPER RETAINER RH	Bent (1 PCS ONLY)	218.60 FL	*109.30 FL
21	2		*REAR BUMPER RETAINER LH	Bent (1 PCS ONLY)	218.60 FL	*109.30 FL
22	1		*REAR BUMPER BRACKET RH	Not Necessary	60.40 FL	*- FL
23	1		*REAR BUMPER BRACKET LH	Not Necessary	60.40 FL	*- FL
24	1		*REAR BUMPER REINFORCEMENT	Bent	399.50 FL	*399.50 FL
25	1		*REAR CHASSIS FRAME LH (NPA)	Not Necessary	0.00 FS	*- FS
26	1		*REAR CHASSIS FRAME RH (NPA)	Not Necessary	0.00 FS	*- FS
27	1		*TAIL LAMP PANEL RH (NPA)	Repair	0.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*TAIL LAMP PANEL LH (NPA)	Repair	0.00 FS	*- FS
29	1		*REAR FENDER RH (NPA)	Repair	0.00 FS	*- FS
30	1		*REAR FENDER LH (NPA)	Repair	0.00 FS	*- FS
31	1		*REAR DOOR RH (NPA)	Repair	0.00 FS	*- FS
32	1		*SET REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
33	1		*REVERSE CAMERA	Not Necessary	580.00 FS	*- FS
34	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	*- FS
35	1		*REAR NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	7,536.30	4,341.00
- List Item Discount on L Items 25.00/25.00% (S\$)	1,654.08	1,035.25
Total Parts (S\$)	5,882.22	3,305.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	1,500.00	1,000.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	1,500.00	1,100.00
3	ANTI-RUST COATING	New	200.00	60.00
4	WIRING	New	80.00	20.00
5	TO REMOVE & REFIT REVERSE SENSOR	New	150.00	50.00
Gross Labour Cost (S\$)			3,430.00	2,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >