

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21004675/ETF3E2

Date: 07/05/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00084252000
Claimant Vehicle No: SGQ9042Y Insured Vehicle No: GBK5708C
Date of Loss: 10/04/2021 Nature of Claim: TP Claim No: SNM21D202072/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGQ9042Y
Make & Model: TOYOTA ISIS, 1.8 (A) Engine No: 1ZZ2692213
Reg. Date: 25/01/2007 (Man. Year: 2006) Chassis No: ZNM100035666
Colour: Silver Odometer: 149524 km
Engine Capacity: 1794 cc
Market Value/New Car Price: N/A
Sum Insured (\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/50 R16 Rear Tyre Size: 205/50 R16
Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 5 mm
Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,017.57	4,020.03	6,997.54	63.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,790.00	1,500.00	3,290.00	68.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,807.57	5,520.03	10,287.54	65.08
Approved Total (Overridden) (\$\$)		2,300.00		
(\$\$)	15,807.57	2,300.00	13,507.57	85.45
+ GST 7.00/7.00% (\$\$)	1,106.53	161.00	945.53	85.45
Nett Amount (\$\$)	16,914.10	2,461.00	14,453.10	85.45

INSPECTION

Date of Assignment: 13/04/2021
Date Inspected: 14/04/2021 Inspected At: H S Automotives Pte Ltd (HQ)
BLK 2 KAKI BUKIT AVENUE 2 #01-15 KAKI
BUKIT AUOTHUB
Singapore 417921
Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 May 2021)
Parts:	144	TOYOTA ISIS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGQ9042Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	1,628.50 F	*1,628.50 FL
2	1		*REAR TAILGATE LOGO TOYOTA	Necessary	64.96 F	*64.96 FL
3	1		*REAR TAILGATE OUTER GARNISH	Broken	209.50 F	*209.50 FL
4	1		*REAR TAILGATE OUTER GARNISH CLIP	Necessary	16.00 F	*16.00 FL
5	1		*REAR TAILGATE NUMBER PLATE	Cut	50.00 F	*50.00 FL
6	2		*REAR TAILGATE NUMBER PLATE LAMP (LH & RH)	Not Necessary	56.80 F	*- FL
7	1		*REAR TAILGATE STICKER BABY ON BOARD	Necessary	20.50 F	*20.50 FL
8	1		*REAR TAILGATE WIPER BLADE (NPA)	Not Necessary	0.00 F	*- FL
9	1		*REAR TAILGATE WIPER ARM (NPA)	Not Necessary	0.00 F	*- FL
10	1		*REAR TAILGATE WIPER MOTOR (NPA)	Not Necessary	0.00 F	*- FL
11	2		*REAR TAILGATE WINDSCREEN RUBBER	Not Necessary	169.58 F	*- FL
12	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	100.00 F	*40.00 FL
13	2		*REAR TAILGATE DAMPER (LH & RH)	Not Necessary	627.00 F	*- FL
14	2		*REAR TAILGATE HINGE (LH & RH)	Not Necessary	116.00 F	*- FL
15	1		*REAR TAILGATE INNER TRIM BOARD	Broken	597.64 F	*322.00 FL
16	1		*REAR TAILGATE INNER TRIM BOARD CLIP	Necessary	28.00 F	*28.00 FL
17	1		*REAR TAILGATE INNER HANDLE (NPA)	Not Necessary	0.00 F	*- FL
18	1		*REAR TAILGATE LOCK MECHANISM	Bent	287.40 F	*287.40 FL
19	1		*REAR TAILGATE LOCK STRIKER	Not Necessary	54.00 F	*- FL
20	1		*REAR TAILLAMP (LH & RH)	N/S Cracked	878.70 F	*439.35 FL
21	2		*REAR TAILLAMP LOWER GARNISH (LH & RH)	Not Necessary	576.80 F	*- FL
22	1		*REAR TAILLAMP LOWER GARNISH CLIP	Not Necessary	58.00 F	*- FL
23	1		*REAR BUMPER	Dented	1,523.82 F	*855.00 FL
24	1		*REAR BUMPER CLIP	Necessary	38.00 F	*25.00 FL
25	2		*REAR BUMPER SIDE RETAINER (LH & RH)	Broken	137.72 F	*137.72 FL
26	1		*REAR BUMPER REVERSE CAMERA	Cracked	550.00 F	*300.00 FL
27	1		*REAR BUMPER TOW COVER	Not Necessary	57.00 F	*- FL
28	2		*REAR BUMPER REFLECTOR (LH & RH)	Not Necessary	571.00 F	*- FL
29	1		*REAR TAILGATE WEATHERSTRIP	Torn	286.16 F	*286.16 FL
30	1		*REAR END PANEL	Dented	385.65 F	*385.65 FL
31	1		*REAR END PANEL TOP GARNISH	Broken	244.30 F	*244.30 FL
32	1		*REAR END PANEL TOP GARNISH CLIP	Necessary	28.00 F	*20.00 FL
33	1		*REAR END PANEL INNER MEMBER	Repair	415.59 F	*- FL
34	1		*REAR EXHAUST	Not Necessary	749.90 F	*- FL
35	1		*REAR SPARE TYRE RACK	Not Necessary	147.65 F	*- FL
36	1		*REAR FENDER INNER TRIM BOARD	Not Necessary	285.40 F	*- FL
37	1		*REAR FENDER INNER TRIM BOARD CLIP	Not Necessary	58.00 F	*- FL
38	2		*REAR FENDER (LH & RH) (NPA)	Repair	0.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	11,017.57	5,360.04
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,340.01
Total Parts (\$\$)	11,017.57	4,020.03

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEAT & REPLACE PARTS	New	1,800.00	600.00
2	PUTTY, RESPRAY & POLISH AFFECTED PORTION	New	2,100.00	600.00
3	CHECK & RECTIFY WIRING SYSTEM	New	120.00	30.00
4	REMOVE & REFIT REAR WINDSCREEN	New	150.00	120.00
5	REMOVE & TRANSFER TAILGATE COMPONENTS	New	150.00	50.00
6	REMOVE & REFIT EXHAUST SYSTEM	New	150.00	0.00
7	REMOVE & REFIT INTERIOR GARNISH, FITTINGS ETC	New	200.00	50.00
8	REMOVE & INSTALL REVERSE CAMERA	New	120.00	50.00
Gross Labour Cost (\$)			4,790.00	1,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >