

ASS. REC. BY:

Steve

CS/CTI 2100 4675 /ETF3

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SGQ 9042Y

Yr Regn:

25/1/07

Type M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota 1515

cc

1794

Colour

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

149524

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

ZNN11000 35 666

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/50 R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

10/4/21

D.O.A.

14/4/21

Survey held at

HIS Automotive

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

NV- 6200

PV- 3850

NV- 2350

Date/Time, File Pass to?

☐
☐

: Preli. Report

: Final Report

1)

Date/Time, File Return to?

2)

Report Formed:

Lump Sum / L&amp;L:

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐
☐
☐
☐

: Site Insp (\$

: Interview (\$

: Tech. Insp (\$

: Wash &amp; Dry (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL



# HS AUTOMOTIVES PTE LTD

Blk 2 KAKI BUKIT AVE 2 @ KAKI BUKIT AUTOHUB #02-25 SINGAPORE 417921.

TEL: 6538 1368 FAX: 6538 1367 Email add: hseautomotivesp@gmail.com

Vehicle No :

Make/Model :

CHASSIS NO :

Accident Date :

Remarks :

SGR 90424

TOYOTA ISG

ZNM100035666

INDEPENDENT SURVEYOR

DIRECT SETTLEMENT

WORK SHOP REPAIRER ESTIMATES

Date:

Estimate cost of repair to the above mentioned

UNIT \$ AMOUNT (\$\$) REMARKS

| NO. | QTY | List Items                                    |      |          |  |
|-----|-----|-----------------------------------------------|------|----------|--|
| 1   |     | REAR TAILGATE / DD                            | \$ - | \$ -     |  |
| 2   |     | REAR TAILGATE LOGO 'TOYOTA' / MC              | \$ - | \$ -     |  |
| 3   |     | REAR TAILGATE OUTER GARNISH ?                 | \$ - | \$ -     |  |
| 4   |     | SN REAR TAILGATE OUTER GARNISH CLIP ?         | \$ - | \$ 16    |  |
| 5   |     | REAR TAILGATE NUMBER PLATE / MT               | \$ - | \$ -     |  |
| 6   |     | REAR TAILGATE NUMBER PLATE LAMP (LH & RH) X   | \$ - | \$ -     |  |
| 7   |     | SN REAR TAILGATE STICKER 'BABY ON BOARD' - MC | \$ - | \$ 20.50 |  |
| 8   |     | REAR TAILGATE WIPER BLADE X                   | \$ - | \$ -     |  |
| 9   |     | REAR TAILGATE WIPER ARM X                     | \$ - | \$ -     |  |
| 10  |     | REAR TAILGATE WIPER MOTOR X                   | \$ - | \$ -     |  |
| 11  |     | REAR TAILGATE WINDSCREEN RUBBER x2 # / APC    | \$ - | \$ -     |  |
| 12  |     | SN REAR TAILGATE WINDSCREEN SEALANT - MC      | \$ - | \$ 100   |  |
| 13  |     | REAR TAILGATE SAMPER (LH & RH) X              | \$ - | \$ -     |  |
| 14  |     | REAR TAILGATE MOGE (LH & RH) X                | \$ - | \$ -     |  |
| 15  |     | REAR TAILGATE INNER TRIM BOARD ?              | \$ - | \$ -     |  |
| 16  |     | SN REAR TAILGATE INNER TRIM BOARD CLIP ?      | \$ - | \$ 28    |  |
| 17  |     | REAR TAILGATE INNER HANDLE X                  | \$ - | \$ -     |  |
| 18  |     | REAR TAILGATE LOCK MECHANISM - OT             | \$ - | \$ -     |  |
| 19  |     | REAR TAILGATE LOCK STICKER X                  | \$ - | \$ -     |  |
| 20  |     | REAR TAILLAMP (LH & RH) (LH) - CRA            | \$ - | \$ -     |  |
| 21  |     | REAR TAILLAMP LOWER GARNISH (LH & RH) X       | \$ - | \$ -     |  |
| 22  |     | SN REAR TAILLAMP LOWER GARNISH CLIP X         | \$ - | \$ 56    |  |
| 23  |     | REAR BUMPER - DD                              | \$ - | \$ -     |  |
| 24  |     | SN REAR BUMPER CHIP - MC                      | \$ - | \$ 36    |  |
| 25  |     | REAR BUMPER SIDE RETAINER (LH & RH) - BR      | \$ - | \$ -     |  |
| 26  |     | SN REAR BUMPER REVERSE CAMERA - CRA           | \$ - | \$ 550   |  |
| 27  |     | REAR BUMPER TOW COVER X                       | \$ - | \$ -     |  |
| 28  |     | REAR BUMPER REFLECTOR (LH & RH) X             | \$ - | \$ -     |  |
| 29  |     | REAR TAILGATE WEATHERSTRIP - TN               | \$ - | \$ -     |  |
| 30  |     | REAR FEND PANEL ?                             | \$ - | \$ -     |  |

REMARKS:

|                         |          |
|-------------------------|----------|
| NO OF DAYS:             |          |
| AGREED FIGURE/LUMP SUM: | \$ -     |
| SURVEYOR NAME           | CONTACT: |
| EMAIL ADD:              |          |



# HS AUTOMOTIVES PTE LTD

Bik 2 KAKI BUKIT AVE 2 @ KAKI BUKIT AUTOHUB #02-25 SINGAPORE 417921

TEL: 6538 1368 FAX: 6538 1367 Email add: hsautomotivesp@gmail.com

|                      |  |
|----------------------|--|
| INDEPENDENT SURVEYOR |  |
| DIRECT SETTLEMENT    |  |

WORK SHOP REPAIRER ESTIMATES

Date: \_\_\_\_\_

Vehicle No : SGQ90424  
Make/Model : TOYOTA KLS  
CHASSIS NO : ZUM100035666  
Accident Date : \_\_\_\_\_  
Remarks : \_\_\_\_\_

Estimate cost of repair to the above mentioned

UNIT \$ AMOUNT (\$\$) REMARKS

| NO. | QTY | List Items                             |      |       |  |
|-----|-----|----------------------------------------|------|-------|--|
| 1   |     | REAR END PANEL TOP GARDEN ?            | \$ - | \$ -  |  |
| 2   |     | SN REAR END PANEL TOP GARDEN CLIP ?    | \$ - | \$ 26 |  |
| 3   |     | REAR END PANEL INNER MEMBER X R        | \$ - | \$ -  |  |
| 4   |     | REAR EXHAUST X                         | \$ - | \$ -  |  |
| 5   |     | REAR SHAFT TIRE RACK X                 | \$ - | \$ -  |  |
| 6   |     | REAR FENDER INNER TRIM BOARD X         | \$ - | \$ 58 |  |
| 7   |     | SN REAR FENDER INNER TRIM BOARD CLIP X | \$ - | \$ 26 |  |
| 8   |     | REAR FENDER (LH RH)                    | \$ - | \$ -  |  |
| 9   |     |                                        | \$ - | \$ -  |  |
| 10  |     |                                        | \$ - | \$ -  |  |
| 11  |     |                                        | \$ - | \$ -  |  |
| 12  |     |                                        | \$ - | \$ -  |  |
| 13  |     |                                        | \$ - | \$ -  |  |
| 14  |     |                                        | \$ - | \$ -  |  |
| 15  |     |                                        | \$ - | \$ -  |  |
| 16  |     |                                        | \$ - | \$ -  |  |
| 17  |     |                                        | \$ - | \$ -  |  |
| 18  |     |                                        | \$ - | \$ -  |  |
| 19  |     |                                        | \$ - | \$ -  |  |
| 20  |     |                                        | \$ - | \$ -  |  |
| 21  |     |                                        | \$ - | \$ -  |  |
| 22  |     |                                        | \$ - | \$ -  |  |
| 23  |     |                                        | \$ - | \$ -  |  |
| 24  |     |                                        | \$ - | \$ -  |  |
| 25  |     |                                        | \$ - | \$ -  |  |
| 26  |     |                                        | \$ - | \$ -  |  |
| 27  |     |                                        | \$ - | \$ -  |  |
| 28  |     |                                        | \$ - | \$ -  |  |
| 29  |     |                                        | \$ - | \$ -  |  |
| 30  |     |                                        |      |       |  |

REMARKS:

NO OF DAYS:

AGREED FIGURE/LUMP SUM:

\$ -

CONTACT:

SURVEYOR NAME

EMAIL ADD:



# HS AUTOMOTIVES PTE LTD

Blk 2 KAKI BUKIT AVE 2 @ KAKI BUKIT AUTOHUB #02-25 SINGAPORE 417921.

TEL: 6538 1368 FAX: 6538 1367 Email add: hsautomotivespl@gmail.com

Vehicle No :

Make/Model :

CHASSIS NO :

Accident Date :

Remarks :

SGR 90424

TOYOTA IS

ZNM100035666

|                      |  |
|----------------------|--|
| INDEPENDENT SURVEYOR |  |
| DIRECT SETTLEMENT    |  |

WORK SHOP REPAIRER ESTIMATES

Date: \_\_\_\_\_

Estimate cost of repair to the above mentioned

| NO. QTY | List Items                               | UNIT | AMOUNT (\$S) | REMARKS            |
|---------|------------------------------------------|------|--------------|--------------------|
| 1       | PANEL BEAT & REPLACE PARTS               | \$ - | \$1,200-     | <del>800</del> 800 |
| 2       |                                          | \$ - | \$ -         |                    |
| 3       | Putty, RESPRAY & POLISH AFFECTED PORTION | \$ - | \$2,100-     | 600                |
| 4       |                                          | \$ - | \$ -         |                    |
| 5       | CHECK & RECTIFY WIRING SYSTEM            | \$ - | \$20 -       | 30                 |
| 6       |                                          | \$ - | \$ -         |                    |
| 7       | REMOVE & REFIT REAR WINDSCREEN           | \$ - | \$150 -      | 120                |
| 8       |                                          | \$ - | \$ -         |                    |
| 9       | REMOVE & TRANSFER TAILGATE COMPONENT     | \$ - | \$150 -      | 50                 |
| 10      |                                          | \$ - | \$ -         |                    |
| 11      | REMOVE & REFIT EXHAUST SYSTEM            | \$ - | \$150 -      | X                  |
| 12      |                                          | \$ - | \$ -         |                    |
| 13      | REMOVE & REFIT INTERIOR GARNISH,         | \$ - | \$200-       | 50                 |
| 14      | FITTINGS ETC                             | \$ - | \$ -         |                    |
| 15      |                                          | \$ - | \$ -         |                    |
| 16      | REMOVE & INSTALL REVERSE CAMERA          | \$ - | \$120 -      | 50                 |
| 17      |                                          | \$ - | \$ -         |                    |
| 18      |                                          | \$ - | \$ -         |                    |
| 19      |                                          | \$ - | \$ -         |                    |
| 20      |                                          | \$ - | \$ -         |                    |
| 21      |                                          | \$ - | \$ -         |                    |
| 22      |                                          | \$ - | \$ -         |                    |
| 23      |                                          | \$ - | \$ -         |                    |
| 24      |                                          | \$ - | \$ -         |                    |
| 25      |                                          | \$ - | \$ -         |                    |
| 26      |                                          | \$ - | \$ -         |                    |
| 27      |                                          | \$ - | \$ -         |                    |
| 28      |                                          | \$ - | \$ -         |                    |
| 29      |                                          | \$ - | \$ -         |                    |
| 30      |                                          | \$ - | \$ -         |                    |

Steve (LKK) WML AIL  
83228813 14/4/21, 11.30am  
L/S  
By AL SJ  
5 days

REMARKS:

|                         |          |
|-------------------------|----------|
| NO OF DAYS:             |          |
| AGREED FIGURE/LUMP SUM: | \$ -     |
| SURVEYOR NAME           | CONTACT: |
| EMAIL ADD:              |          |

Repair limit \$2300