

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21004676/UPA3Q2
Date: 30/07/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100446329
Claimant Vehicle No :	SKC7605M	Insured Vehicle No :	SGA6543Y
Date of Loss:	08/04/2021	Nature of Claim:	TP
		Claim No:	0756729567SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKC7605M	Engine No:	15457891N52B25AF
Make & Model:	BMW 325I, 2.5 AT HID (A)	Chassis No:	WBADW32060E486926
Reg. Date:	29/09/2011 (Man. Year: 2011)	Odometer:	79265 km
Colour:	Black		
Engine Capacity:	2497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	255/40 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,544.01	2,533.86	3,010.15	54.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,090.00	1,360.00	730.00	34.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,634.01	3,893.86	3,740.15	48.99
Approved Total (Overridden) (S\$)		3,100.00		

Nett Amount (S\$)	7,634.01	3,100.00	4,534.01	59.39
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,507.45		
Global Sum Settlement (S\$)		3,500.00		

INSPECTION

Date of Assignment: 13/04/2021

Date Inspected: 13/04/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Asia Motorsports Solution Pte Ltd (HQ)

37A Everitt

Singapore 428586

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Repair	1,689.00 FL	*- FL
2	1		*REAR BOOT LID BMW BADGE	Necessary	110.20 FL	*89.20 FL
3	1		*REAR BOOT LID 325I EMBLEM	Necessary	87.50 FL	*87.50 FL
4	1		*REAR BOOT LID INNER LOCK	Not Necessary	328.00 FL	*- FL
5	1		*REAR BOOTLID INNER TRIM (NPA)	Not Necessary	0.00 FL	*- FL
6	2		*REAR BOOTLID RUBBER STOPPER	Not Necessary	84.00 FL	*- FL
7	2		*REAR BOOTLID DAMPER (NPA)	Not Necessary	0.00 FL	*- FL
8	2		*REAR BOOTLID HINGES (NPA)	Not Necessary	0.00 FL	*- FL
9	2		*REAR BOOTLID REFLECTORS (NPA)	Not Necessary	0.00 FL	*- FL
10	1		*REAR BOOTLID THIRD BRAKELIGHT (NPA)	Not Necessary	0.00 FL	*- FL
11	1		*REAR BUMPER	Deformed	1,425.00 FL	*1,425.00 FL
12	1		*REAR BUMPER TOWING COVER	Not Necessary	58.00 FL	*- FL
13	2		*REAR BUMPER SIDE HOLDER	Not Necessary	184.00 FL	*- FL
14	1		*REAR REINFORCEMENT OUTER FRAME	Cracked	140.00 FL	*140.00 FL
15	1		*REAR REINFORCEMENT OUTER FRAME LOWER	Not Necessary	120.00 FL	*- FL
16	1		*REAR END PANEL	Dented / Bent	750.00 FL	*715.00 FL
17	1		*END PANEL LOCK CATCH	Not Necessary	60.00 FL	*- FL
18	1		*BOOT WEATHERSTRIP	Not Necessary	258.00 FL	*- FL
19	1		*REAR LICENCE PLATE WITH HOLDER	Not Necessary	75.00 FS	*- FS
20	1		*SET REVERSE SENSOR	Shorted	380.00 FS	*200.00 FS
21	1		*SET REAR BOOTLID INNER TRIM CLIPS	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,808.70	2,656.70
- List Item Discount on L Items 5.00/5.00% (\$)	264.69	122.84
Total Parts (\$)	5,544.01	2,533.86

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,REPLACE DAMAGED PARTS AND COMPONENTS	New	800.00	600.00
2	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY ,RESPRAY PAINT ON PARTS REPLACED	New	600.00	600.00
3	TO REMOVE /REFIX INNER TRIMS ,FITTINGS ,GARNISH ETC AT REAR COMPARTMENT SO AS TO FACILITATE REPAIRS AT REAR	New	150.00	80.00
4	TO CLEAR FAULT CODE WITH DIAGNOSTIC COMPUTER AND RESET TO SPECIFICATION	New	350.00	0.00
5	TO REMOVE AND REPLACE REVERSE SENSORS AND CHECK FOR PROPER FUNCTION	New	100.00	50.00
6	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	90.00	30.00
Gross Labour Cost (S\$)			2,090.00	1,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >