

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 7050Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER COVER	DEFORMED	1,106.00	1,106.00
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	428.40	-
1	REAR BUMPER UNDER COVER	DEFORMED	228.00	228.00
1	REAR BUMPER REFLECTOR LAMP LH	NOT NECESSARY	32.00	-
	LESS 20% DISCOUNT		-363.28	-271.20
			1,453.12	1,084.80
	<u>NETT ITEMS</u>			
1	REAR BUMPER MAT (N)	NECESSARY	50.00	50.00
	LESS 10% DISCOUNT		-	-5.00
			50.00	45.00
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER REVERSE SENSOR (SN)	NOT NECESSARY	135.70	-
			135.70	-
	<u>LABOUR</u>			
	WIRING CHARGE.	NOT NECESSARY	60.00	-
	PANEL BEATING.		350.00	280.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	REMOVE/REFIX REVERSE SENSOR.		60.00	30.00
			770.00	560.00
	GRAND TOTAL		2,408.82	1,689.80
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			1,350.00

Report Ref No. NS/INC21004681/T1vcn2



MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.