



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2104679

INV Date 05/07/2021

Reference CC4/LPC21004682/Upa3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. GBG 6155L
Insured Veh. GBB 3337A
Claim No. 21/21/21/VC00/024446
Policy No. Z/21/VC00/109577
Accident Date 12/04/2021
Inspection Date 14/04/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CC4/LPC21004682/Upa3q2 Date: 05/07/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBB 3337A	Veh. Inspected	GBG 6155L	
Policy No.	Z/21/VC00/109577	Coverage (\$)	0.00	
Claim No.	21/21/21/VC00/024446	Excess (\$)	0.00	
Assign From	KENNY	Assign Date	13/04/2021	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN CABSTAR (M)	c.c	2953	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JN1SC2F24Z0859980	Colour	WHITE	
Odometer	256260 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/75 R15	YOKOHAMA	6 mm	
L/H Front Tyre	185/75 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	155 R13	YOKOHAMA	6 mm	
L/H Rear Tyre	155 R13	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR & FRONT PORTION. THE CHASSIS FRAME AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/04/2021	Inspection Date	14/04/2021	
Survey held at	Blk 15 Kaki Bukit Road 4, #01-53, S 417808			
Repairer	ZOOM AUTOWERKS PTE LTD			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			15 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 6155L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DISTORTED	897.00	897.00
1	FRONT BUMPER REINFORCEMENT	DISTORTED	786.50	617.00
1	FRONT GRILLE	CRACKED	475.90	438.40
1	FRONT GRILLE LOGO	NECESSARY	68.20	48.10
1	FRONT PANEL	BADLY DENTED	1,750.40	1,417.20
1	FRONT PANEL EMBLEM	NECESSARY	135.80	65.00
2	HEADLAMP @\$484.50	CRACKED	969.00	946.00
2	HEADLAMP LOWER GARNISH @\$29.40	N/S CRACKED	58.80	29.40
2	FRONT CORNER PANEL @\$425.70	N/S DENTED	851.40	389.90
2	FRONT CORNER WIPER GARNISH @\$195.60	N/S CRACKED	391.20	195.60
1	FRONT CENTRE WIPER GARNISH	BENT	487.20	487.20
1	FRONT WINDSCREEN GLASS	CRACKED	1,286.70	991.00
1	FRONT WINDSCREEN GLASS RUBBER	NECESSARY	455.80	180.00
2	FRONT INNER CABIN VISOR @\$195.80	NOT NECESSARY	391.60	-
1	SET FRONT WIPER ARM	SERVICEABLE	286.70	-
1	SET FRONT WIPER BLADE	NOT NECESSARY	48.50	-
1	WING MIRROR ARM RH	NOT NECESSARY	386.40	-
1	WING MIRROR GLASS RH	BROKEN	118.40	118.40
1	WING MIRROR ARM LH	NOT NECESSARY	545.70	-
1	WING MIRROR GLASS LH	NOT NECESSARY	145.90	-
1	WING MIRROR ANGLE GLASS LH	NOT NECESSARY	125.80	-
1	FRONT DASHBOARD	NOT NECESSARY	1,669.50	-
1	FRONT DASHBOARD COMPARTMENT COVER	NOT NECESSARY	386.70	-
1	FRONT DASHBOARD REINFORCEMENT	NOT NECESSARY	786.90	-
1	AIR CON BLOWER MOTOR	CRACKED	1,984.70	1,666.20
1	AIR CON COOLING COIL	NOT NECESSARY	1,433.10	-
1	AIR CON HEATER ASSY	CRACKED	1,270.60	1,270.60
1	AIR CON SUCTION PIPE	NOT NECESSARY	436.70	-
1	AIR CON PRESSURE PIPE	NOT NECESSARY	398.40	-
1	AIR CON CONDENSER	NOT NECESSARY	897.30	-
1	AIR CON FAN MOTOR	NOT NECESSARY	386.40	-

Report Ref No. CC4/LPC21004682/Upa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	AIR CON FAN COWLING	NOT NECESSARY	327.10	-
1	FRONT CHASSIS MEMBER	TO REPAIR SEE LABOUR	1,140.60	-
2	REAR CABIN PILLAR @\$995.20	TO REPAIR SEE LABOUR	1,990.40	-
1	REAR CENTREE CABIN PANEL	TO REPAIR SEE LABOUR	786.40	-
2	FRONT STEP PANEL GARNISH @\$376.10	N/S CRACKED	752.20	241.50
2	FRONT MUD GUARD @\$175.60	NOT NECESSARY	351.20	-
2	SIDE GATE PANEL @\$2755.40	TO REPAIR SEE LABOUR	5,510.80	-
2	SIDE GATE BEAM @\$1750.20	NOT NECESSARY	3,500.40	-
2	SIDE GATE STOPPER @\$18.50	NOT NECESSARY	74.00	-
6	SIDE GATE SUPPORT BRACKET @\$175.40	BENT	1,052.40	350.80
2	SIDE GATE MUD GUARD SIDE PANEL @\$425.80	NOT NECESSARY	851.60	-
2	SIDE GATE ALUMINIUM RAIL @\$490.50	NOT NECESSARY	981.00	-
1	REAR TAILGATE	BENT	1,786.70	1,399.20
2	TAILGATE SUPPOER BRACKET @\$197.40	NO SUCH PARTS	394.80	-
2	TAILGATE STOPPER RUBBER @\$15.50	NOT NECESSARY	31.00	-
4	TAILGATE HINGE @\$82.50	NOT NECESSARY	330.00	-
2	TAILGATE SIDE LOCK @\$62.50	TO REPAIR SEE LABOUR	125.00	-
2	TAILGATE SAFETY LOCK @\$75.40	TO REPAIR SEE LABOUR	150.80	-
1	TAILGATE STICKER (NISSAN)	NECESSARY	175.30	175.00
1	REAR END PANEL	BENT	1,786.50	545.10
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	3,115.40	-
2	TAILLAMP @\$297.50	CRACKED	595.00	416.00
2	TAILLAMP SUPPORT BRACKET @\$175.40	NOT NECESSARY	350.80	-
	LESS 10% DISCOUNT		-4,647.26	-1,288.46
			41,825.34	11,596.14
	<u>SPECIAL NETT ITEMS</u>			
1	REAR FULL CANOPY (ALUMINIUM SET) (SN)	TO REPAIR SEE LABOUR	3,800.00	-
1	REAR SAFETY BAR (SN)	BENT	1,280.00	380.00

Report Ref No. CC4/LPC21004682/Upa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR REVERSE SENSOR (SN)	CRACKED	1,400.00	200.00
1	REAR PLATE (SN)	DISTORTED	1,000.00	500.00
1	FRONT NUMBER PLATE (SN)	BENT	55.00	15.00
1	REAR NUMBER PLATE (SN)	BENT	55.00	15.00
			7,590.00	1,110.00
	LABOUR			
	TO REMOVE ,REPAIR & RENEW AFFECTED REAR ACCIDENT AREAS .INCLUSIVE OF THE REPAIR OF REAR CABIN PILLAR,REAR CENTRE CABIN PANEL, REAR FLOOR PANEL AND REAR FULL CANOPY (ALUMINIUM SET).		1,200.00	1,200.00
	TO PUTTY,SPRAY PAINT ON AFFECTED REAR ACCIDENT AREAS.		1,400.00	600.00
	TO REMOVE ,REPAIR & RENEW AFFECTED FRONT ACCIDENT AREAS .INCLUSIVE OF THE REPAIR OF FRONT CHASSIS MEMBER,SIDE GATE PANEL,TAILGATE SIDE LOCK AND TAILGATE SAFETY LOCK.		1,200.00	800.00
	TO PUTTY,SPRAY PAINT ON AFFECTED FRONT ACCIDENT AREAS.		1,200.00	1,100.00
	TO DISCHARGE & CHARGE UP GAS.		120.00	100.00
	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING.		50.00	30.00
	TO REMOVE ,REPLACE & INSTALL REAR CANOPY.	NOT NECESSARY	500.00	-
	TO REMOVE & INSTALL REAR CARGO BED TO FACILITATE REPAIRS.		850.00	300.00
	TO REMOVE & INSTALL FRONT WINDSCREEN GLASS .		150.00	80.00
	TO REMOVE & INSTALL FRONT DASHBOARD TO FACILITATE REPAIRS.		250.00	200.00
	TO REMOVE & RE-POSITION REVERSE SENSOR .		80.00	50.00
	TO RE-PROGRAMME & RESET DIAGNOSTIC .	NOT NECESSARY	250.00	-
	TO RUST PROOF AFFECTED AREAS .		100.00	100.00
			7,350.00	4,560.00
GRAND TOTAL			56,765.34	17,266.14

Report Ref No. CC4/LPC21004682/Upa3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			13,800.00
---	--	--	------------------

Report Ref No. CC4/LPC21004682/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBG 6155L

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBG 6155L

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBG 6155L

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBG 6155L

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

