

iShare Auto Pte. Ltd.

Co. Reg No: 201939376R

8 Kaki Bukit Avenue 4

#08-09 Premier @ Kaki Bukit

Singapore 415875

Tel: 6341 6789 Fax: 6341 6778

Email: ishareauto@gmail.com



DATE : 19.04.21

TO : NTUC MOTOR CLAIMS DEPTS
VEHICLE NO : SFP1515U
MODEL : TOYOTA COROLLA ALTIS
DATE OF ACCIDENT : 10.04.21
TIME OF ACCIDENT : 07:05HRS

MR2BE3BE200013099

Xiao Chan.

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Dented</i>	1	\$ 541.90	\$ 541.90
2	REAR BUMPER REFLECTOR <i>New</i>	2	\$ 59.30	\$ 118.60
3	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 100.40	\$ 200.80
4	REAR BUMPER REINFORCEMENT <i>Best</i>	1	\$ 332.70	\$ 332.70
5	REAR BUMPER LOWER INNER GARNISH <i>ton</i>	2	\$ 143.50	\$ 287.00
6	REVERSE SENSOR C/W HOLDER <i>Dented</i>	2	\$ 288.70	\$ 577.40
7	BOOTLID <i>Dented</i>	1	\$ 856.70	\$ 856.70
8	BOOTLID LOGO <i>2</i>	1	\$ 68.20	\$ 68.20
9	BOOTLID EMBLEM 'COROLLA' <i>new</i>	1	\$ 48.90	\$ 48.90
10	BOOTLID EMBLEM 'ALTIS'	1	\$ 49.90	\$ 49.90
11	BOOTLID OUTER MOULDING <i>New</i>	1	\$ 197.80	\$ 197.80
12	BOOTLID LAMP <i>New L&W</i>	2	\$ 667.20	\$ 1,334.40
13	BOOTLID TOP LOCK <i>Damaged</i>	1	\$ 399.50	\$ 399.50
14	BOOTLID LOWER LOCK <i>new</i>	1	\$ 38.90	\$ 38.90
15	BOOTLID WEATHERSTRIP <i>cut</i>	1	\$ 207.20	\$ 207.20
16	BOOTLID DETECTOR <i>Crushed</i>	1	\$ 78.60	\$ 78.60
17	REVERSE CAMERA <i>new</i>	1	\$ 769.60	\$ 769.60
18	TAILLAMP (LED) <i>new crushed</i>	2	\$ 1,032.10	\$ 2,064.20
19	TAILLAMP LOWER BARCKET <i>L&W crushed</i>	2	\$ 100.40	\$ 200.80
20	REAR FENDER INNER COWLING <i>new</i>	2	\$ 201.90	\$ 403.80
21	REAR FENDER INNER TRIM <i>new</i>	2	\$ 379.30	\$ 758.60
22	REAR END PANEL <i>Dented</i>	1	\$ 617.80	\$ 617.80
23	REAR END PANEL TOP GARNISH <i>Crushed</i>	1	\$ 270.60	\$ 270.60
24	REAR FLOOR PANEL <i>Repair</i>	1	\$ 937.20	\$ 937.20
25	REAR FLOOR PANEL TOP BOARD <i>Dented</i>	1	\$ 291.80	\$ 291.80
26	REAR SPARE TYRE BOLT <i>new</i>	1	\$ 31.30	\$ 31.30

143.50

288.70

667.20
298

1032.10
45

880

TO : NTUC MOTOR CLAIMS DEPTS
 VEHICLE NO : SFP1515U
 MODEL : TOYOTA COROLLA ALTIS
 DATE OF ACCIDENT : 10.04.21
 TIME OF ACCIDENT : 07:05HRS

27	REAR TOOL SPONGE <i>new</i>	1	\$ 148.60	\$ 148.60
----	-----------------------------	---	-----------	-----------

TOTAL PRICE \$ 11,832.80
 LESS 25% \$ 2,958.20
SUB TOTAL PRICE \$ 8,874.60

5575.3
418147

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>new</i>	1	\$ 80.00	\$ 80.00
2	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
3	REAR BUMPER LOWER INNER GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
4	BOOTLID OUTER MOULDING CLIP(SET) <i>new</i>	1	\$ 60.00	\$ 60.00
5	BOOT LID INSULATOR CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
6	TAILLAMP CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
7	REAR FENDER COWLING CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
8	REAR FENDER INNER TRIM CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
9	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
10	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00
11	REAR FLOOR PANEL INSULATION SEAL <i>new</i>	1	\$ 350.00	\$ 350.00
12	TRIANGLE BREAKDOWN SIGN <i>cracked</i>	1	\$ 180.00	\$ 180.00

210 TOTAL \$ 1,220.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00	800
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	800
3	TUFF COAT	\$ 250.00	60
4	WIRING CHECK	\$ 80.00	30
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
6	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	50
7	CONDUCT WATER LEAKAGE TEST	\$ 100.00	X
8	REAR CHASSIS ALIGNMENT	\$ 250.00	X

TO : NTUC MOTOR CLAIMS DEPTS
VEHICLE NO : SFP1515U
MODEL : TOYOTA COROLLA ALTIS
DATE OF ACCIDENT : 10.04.21
TIME OF ACCIDENT : 07:05HRS

9	TRANSFER BOOTLID MECHANISM	\$ 80.00	60
10	CONDUCT WATER LEAKAGE TEST	\$ 100.00	x
11	REMOVE AND REFIX FUEL TANK TO FACILITATE FLOOR PANEL REPLACEMENT	\$ 80.00	x
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

TOTAL \$ 4,880.00

TOTAL PARTS COST : \$ 10,094.60
TOTAL LABOUR COST : \$ 4,880.00
TOTAL REPAIR COST : \$ 14,974.60

Adrian
L/S 13/04/21.
068ups ✓

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

MICHELLE

SERVICE ADVISOR
MICHELLE
HP : 9856 4815

Wend: 6241147
L/S: SK ✓

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:
--