

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21004693/URS3Q2
Date: 18/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SLW3180E	Insured Vehicle No :	SKV244S
Date of Loss:	09/04/2021	Nature of Claim:	TP
		Claim No:	8652608196SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW3180E	Engine No:	LEB6541235
Make & Model:	HONDA SHUTTLE, 1.5 (A)	Chassis No:	GP71201018
Reg. Date:	07/02/2018 (Man. Year: 2017)	Odometer:	241729 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,198.40	4,115.20	2,083.20	33.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,500.00	1,170.00	1,330.00	53.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,698.40	5,285.20	3,413.20	39.24
Approved Total (Overridden) (S\$)		4,200.00		

Nett Amount (S\$)	8,698.40	4,200.00	4,498.40	51.72
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
(S\$)		4,700.00		
Liabe Amount (50.00%) (S\$)		2,350.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,357.45		

INSPECTION

Date of Assignment: 13/04/2021

Date Inspected: 13/04/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Asia Motorsports Solution Pte Ltd (HQ)
 37A Everitt
 Singapore 428586

Adjuster: MARCUS CHUA**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	1,249.00 FL	*1,050.00 FL
2	2		*FRONT BUMPER SIDE RETAINER L/R	Not Necessary	185.00 FL	*- FL
3	1		*FRONT BUMPER TOW COVER	Not Necessary	72.00 FL	*- FL
4	2		*FRONT BUMPER FOG LAMP (NPA)	Not Necessary	0.00 FL	*- FL
5	2		*FRONT BUMPER FOG LAMP CHROME COVER (NPA)	Not Necessary	0.00 FL	*- FL
6	1		*FRONT BUMPER LOWER CENTRE GRILLE (NPA)	Not Necessary	0.00 FL	*- FL
7	1		*RHS HEADLAMP HID	Cracked	1,425.00 FL	*1,215.00 FL
8	1		*RHS HEADLAMP LOWER BRACKET SUPPORT	Not Necessary	112.00 FL	*- FL
9	1		*RHS FRONT FENDER	Dented	798.00 FL	*485.00 FL
10	1		*RHS FRONT FENDER INNER SPLASH SHIELD	Torn	238.00 FL	*182.00 FL
11	1		*RHS FRONT FENDER HYBRID EMBLEM	Necessary	92.00 FL	*80.00 FL
12	1		*RHS SIDE SILL (ROCKER PANEL GARNISH)	Torn	582.00 FL	*582.00 FL
13	1		*RHS FRONT DOOR (NPA)	Repair	0.00 FL	*- FL
14	1		*RHS FRONT SHOCK ABSORBER	Serviceable	492.00 FL	*- FL
15	1		*RHS FRONT LOWER ARM	Bent	382.00 FL	*382.00 FL
16	1		*RHS FRONT TIE ROD	Serviceable	178.00 FL	*- FL
17	1		*RHS FRONT KNUCKLE ARM	Bent	298.00 FL	*298.00 FL
18	1		*RHS FRONT WHEEL BEARING	Damaged	245.00 FL	*245.00 FL
19	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*50.00 FS
20	1		*SET RHS FRONT FENDER INNER SHIELD CLIPS	Necessary	60.00 FS	*50.00 FS
21	1		*RHS FRONT SPORTS RIM	Bent	980.00 FS	*400.00 FS
22	1		*FRONT NUMBER PLATE W/HOLDER (NPA)	Not Necessary	0.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,468.00	5,019.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,269.60	903.80
Total Parts (\$\$)	6,198.40	4,115.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIR ,PANEL BEAT & RESHAPE THE AFFECTED AREAS,REPLACE THE DAMAGED PARTS AND COMPONENTS	New	1,000.00	300.00
2	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED & REPAIRED (RHS FRONT DOOR)	New	800.00	600.00
3	TO CHECK WIRING AT ACCIDENT DAMAGED AREAS AND FOCUS HEADLAMP BEAM	New	180.00	20.00
4	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS	New	150.00	30.00
5	TO REMOVE AND REPLACE RHS FRONT UNDERCARRIAGE PARTS (SUSPENSION SYSTEM)	New	250.00	120.00
6	TO CONDUCT COMPUTERISED WHEEL ALIGNMENT	New	120.00	100.00
Gross Labour Cost (S\$)			2,500.00	1,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >