

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21004694/KRA3Q2
Date: 27/06/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SHB9711S	Insured Vehicle No :	SKX9866C
Date of Loss:	08/04/2021	Nature of Claim:	TP
		Claim No:	3885913657SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB9711S		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2H16970
Reg. Date:	13/11/2020 (Man. Year: 2020)	Chassis No:	JTDKB3FU603092664
Colour:	Metallic Pearl White/Red	Odometer:	17074 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 8 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,270.45	3,193.25	8,077.20	71.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,380.00	890.00	3,490.00	79.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,650.45	4,083.25	11,567.20	73.91
+ GST 7.00/7.00% (S\$)	1,095.53	285.83	809.70	73.91

Nett Amount (S\$)	16,745.98	4,369.08	12,376.90	73.91
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 12/04/2021

Date Inspected: 12/04/2021

Estimated Period of Repair: 2.0 days

Inspected At: Trans-cab Auto Services Pte Ltd
No 2 Ang Mo Kio Street 63
Singapore 569111

Adjuster: KENNETH KONG

Manager: Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FRONT BUMPER	Buckled / Dented	521.00 FL	*521.00 FL
2	1		*BRACKET ,FRONT BUMPER SIDE ,RH	Serviceable	59.30 FL	*- FL
3	1		*SUPPORT ,FRONT BUMPER SIDE ,RH	Serviceable	80.10 FL	*- FL
4	1		*ABSORBER ,FRONT BUMPER ENERGY	Serviceable	80.20 FL	*- FL
5	1		*COVER ,FRONT BUMPER HOLE ,RH	Serviceable	30.20 FL	*- FL
6	1		*MOULDING ,FRONT BUMPER SIDE ,RH	Serviceable	95.60 FL	*- FL
7	1		*REINFORCEMENT SUB-ASSY ,FRONT BUMPER	Repair	716.60 FL	*- FL
8	1		*GRILLE ,RADIATOR ,LOWER NO.1	Serviceable	178.60 FL	*- FL
9	1		*UNIT ASSY ,HEADLAMP ,RH	Mtg Cracked	2,637.60 FL	*2,637.60 FL
10	1		*COMPUTER ,SUB ASSY HEADLAMP ,LH NO.	Serviceable	3,772.50 FL	*- FL
11	1		*LAMP ASSY ,FOG, RH	Serviceable	237.10 FL	*- FL
12	1		*JAR ASSY ,WINDSHIELD WASHER	Serviceable	219.10 FL	*- FL
13	1		*LINER ,FRONT FENDER ,RH	Serviceable	202.50 FL	*- FL
14	1		*FENDER SUB-ASSY ,FRONT RH	Bent	977.80 FL	*977.80 FL
15	1		*EMBLEM ,SIDE PANEL RH	Necessary	54.60 FL	*54.60 FL
16	1		*MIRROR ASSY ,OUTER REAR VIEW ,RH	Serviceable	1,436.60 FL	*- FL
17	1		*FRT BUMPER CLIP	Necessary	65.00 FS	*50.00 FS
18	1		*ENGINE UNDERCOVER CLIP	Not Necessary	60.00 FS	*- FS
19	1		*SET FRONT FENDER CLIP	Not Necessary	65.00 FS	*- FS
20	1		*SET FRONT BUMPER LINER CLIP	Not Necessary	75.00 FS	*- FS
21	1		*SET FRONT BUMPER CLIP	Not Necessary	90.00 FS	*- FS
22	1		*TYRE	Serviceable	350.00 FS	*- FS
23	1		*RIM	Serviceable	1,879.40 FS	*- FS
24	1		*HUB CAP	Serviceable	211.50 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	14,095.30	4,241.00
- List Item Discount on L Items 25.00/25.00% (S\$)	2,824.85	1,047.75
Total Parts (S\$)	11,270.45	3,193.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,600.00	400.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
3	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	30.00
4	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,600.00	440.00
6	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
7	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
Gross Labour Cost (S\$)			4,380.00	890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >