

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

**Our File No:** CC3/AIG21004695/GPS3Q2  
**Date:** 03/08/2021

**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070054687
<b>Claimant Vehicle No :</b>	SDX6690U	<b>Insured Vehicle No :</b>	SMT907A
Date of Loss:	13/04/2021	Nature of Claim:	TP
		Claim No:	7171126433SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SDX6690U</b>		
Make & Model:	AUDI Q5 SPORT, 2.0 TFSI QU S TRONIC (A)	Engine No:	DAX046620
Reg. Date:	30/11/2018 (Man. Year: 2018)	Chassis No:	WAUZZZF7J2238865
Colour:	Blue	Odometer:	54163 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	245/45Z R20	Rear Tyre Size:	245/45Z R20
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,921.00	2,944.40	6,976.60	70.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,552.00	3,102.00	2,450.00	44.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>15,473.00</b>	<b>6,046.40</b>	<b>9,426.60</b>	<b>60.92</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,083.11</b>	<b>423.25</b>	<b>659.86</b>	<b>60.92</b>

<b>Nett Amount (S\$)</b>	<b>16,556.11</b>	<b>6,469.65</b>	<b>10,086.46</b>	<b>60.92</b>
<b>+ Car Rental (4.0 x S\$150.00/day) (S\$)</b>		600.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>7,071.65</b>		

INSPECTION

Date of Assignment: 16/04/2021

Date Inspected: 16/04/2021

Estimated Period of Repair: 4.0 days

Inspected At: Premium Automobiles Pte Ltd (UBI)  
55 Ubi Road 1  
Singapore 408699

**Adjuster:** XING GUO QIANG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER -TOP	Repair	1,907.00 FS	*- FS
2	1		*REAR BUMPER -BOTTOM	Deformed	1,196.00 FS	*956.80 FS
3	1		*REAR BUMPER SPOILER	Deformed	866.00 FS	*692.80 FS
4	2		*REAR BUMPER CLOSING ELEMENT -LH/RH	Not Necessary	192.00 FS	*- FS
5	2		*REAR BUMPER CHROME TRIM-LH/RH	Not Necessary	474.00 FS	*- FS
6	2		*TAIL LIGHT-LH/RH	Not Necessary	1,398.00 FS	*- FS
7	1		*REAR BOOT LID CONTROL UNIT	Not Necessary	411.00 FS	*- FS
8	1		*REAR BUMPER CARRIER	Not Necessary	981.00 FS	*- FS
9	2		*REAR BUMPER SEAL	Not Necessary	6.00 FS	*- FS
10	1		*REAR BUMPER HOLDING STRAP	Not Necessary	168.00 FS	*- FS
11	2		*REAR PARKING AID SENSOR	Not Necessary	488.00 FS	*- FS
12	4		*REAR PARKING AID SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS
13	1		*3MM ADHESIVE	Necessary	19.00 FS	*14.88 FS
14	1		*AUDI EMBLEM	Necessary	138.00 FS	*110.00 FS
15	1		*Q5 EMBLEM	Necessary	99.00 FS	*79.04 FS
16	1		*QUATTRO EMBLEM	Necessary	99.00 FS	*79.04 FS
17	1		*TFSI EMBLEM	Necessary	99.00 FS	*79.04 FS
18	2		*REAR WHEEL ARCH COVER -LH/RH	Necessary	1,166.00 FS	*932.80 FS
19	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett.

<b>Total Parts (S\$)</b>	<b>9,921.00</b>	<b>2,944.40</b>
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR CHECK FUNCTION	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER .RE-ORGANISE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
3	TO RESPRAY REAR BUMPER ,REAR LOWER BUMPER ,REAR LID AND BOTH REAR WHEEL ARCH TRIMS	New	3,800.00	2,050.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (S\$)</b>			<b>5,552.00</b>	<b>3,102.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >