

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21004697/KGS3Q2**Date:** 15/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900247537
Claimant Vehicle No :	SMY4843Y	Insured Vehicle No :	SMQ5039M
Date of Loss:	08/04/2021	Nature of Claim:	TP
		Claim No:	7853903361SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMY4843Y	Engine No:	G4LCJU977029
Make & Model:	HYUNDAI ACCENT, 1.4 (A)	Chassis No:	KMHCU41BTJU426827
Reg. Date:	07/05/2018 (Man. Year: 2018)	Odometer:	49155 km
Colour:	White		
Engine Capacity:	1368 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,389.44	1,389.44	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,060.00	850.00	210.00	19.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,449.44	2,239.44	210.00	8.57
+ GST 7.00/7.00% (S\$)	171.46	156.76	14.70	8.57
Nett Amount (S\$)	2,620.90	2,396.20	224.70	8.57
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
Nett Liability (S\$)		2,546.20		
Global Sum Settlement (S\$)		2,500.00		

INSPECTION

Date of Assignment:	13/04/2021	
Date Inspected:	10/05/2021	Inspected At: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented / Cut	418.30 FL	*418.30 FL
2	1		*FRONT BUMPER RH SIDE RETAINER	Distorted	11.00 FL	*11.00 FL
3	6		*FRONT BUMPER CLIPS	Necessary	21.00 FL	*21.00 FL
4	1		*FRONT RH FENDER	Buckled	582.70 FL	*582.70 FL
5	1		*HEADLAMP RH	Cut	703.80 FL	*703.80 FL
					Sub Total (S\$)	1,736.80 1,736.80
					- List Item Discount on L Items 20.00/20.00% (S\$)	347.36 347.36
					Total Parts (S\$)	1,389.44 1,389.44

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX FRT BUMPER ASSY ,HEADLAMP ,FOG LAMP ,FRT RH FENDER TO KNOCK & REPAIR FRT BUMPER REINFORCEMENT & REALIGN THE SAME	New	480.00	400.00
2	PUTTY & RESPRAY ON FRT BUMPER ,FRT RH FENDER	New	550.00	420.00
3	RUSTPROOFING	New	30.00	30.00
Gross Labour Cost (\$\$)			1,060.00	850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >