

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21004699/URS3Q2
Date: 23/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900256883
Claimant Vehicle No :	SLC8367G	Insured Vehicle No :	SMR7575M
Date of Loss:	09/04/2021	Nature of Claim:	TP
		Claim No:	4403096127SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC8367G	Engine No:	3A92UDC1692
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Chassis No:	MMBSTA13AHH000409
Reg. Date:	27/05/2016 (Man. Year: 2016)	Odometer:	127873 km
Colour:	Grey		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Firestone 6 mm	Rear Left Side:	Firestone 6 mm
Front Right Side:	Firestone 6 mm	Rear Right Side:	Firestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,318.32	1,255.50	5,062.82	80.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,750.00	770.00	1,980.00	72.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,068.32	2,025.50	7,042.82	77.66
Approved Total (Overridden) (S\$)		1,600.00		

Nett Amount (S\$)	9,068.32	1,600.00	7,468.32	82.36
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		1,936.45		

INSPECTION

Date of Assignment: 13/04/2021

Date Inspected: 13/04/2021

Estimated Period of Repair: 3.0 days

Inspected At: Zoom Autowerks Pte Ltd
832 SIMS AVENUE #12-884 EUNOSVILLE
Singapore 400832

Adjuster: MARCUS CHUA**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	895.60 FL	*696.00 FL
2	1		*FRONT BUMPER BRACKET LH	Not Necessary	68.20 FL	*- FL
3	1		*FRONT BUMPER SIDE RETAINER LH	Not Necessary	47.40 FL	*- FL
4	1		*FRONT BUMPER FOG LAMP LH	Not Necessary	210.50 FL	*- FL
5	1		*FRONT BUMPER FOG LAMP GARNISH LH	Not Necessary	118.70 FL	*- FL
6	1		*FRONT BUMPER FOG LAMP CHROME GARNISH LH	Not Necessary	115.20 FL	*- FL
7	1		*SET FRONT BUMPER CLIPS	Necessary	60.00 FL	*45.00 FL
8	1		*FRONT HEADLAMP ASSY LH	Cracked	755.40 FL	*654.00 FL
9	1		*FRONT HEADLAMP BRACKET LH	Not fitted	125.60 FL	*- FL
10	1		*FRONT FENDER LH	Repair	779.60 FL	*- FL
11	1		*FRONT FENDER INNER SHIELD LH	Not Necessary	215.40 FL	*- FL
12	1		*SET FRONT FENDER INNER SHIELD CLIPS	Not Necessary	60.00 FL	*- FL
13	1		*ROCKER GARNISH LH	Not Necessary	320.80 FL	*- FL
14	1		*SET ROCKER GARNISH CLIPS	Not Necessary	30.00 FL	*- FL
15	1		*FRONT KNUCKLE ARM LH	Not Necessary	472.60 FL	*- FL
16	1		*FRONT KNUCKLE HUB LH	Not Necessary	255.70 FL	*- FL
17	1		*FRONT KNUCKLE HUB BEARING LH	Not Necessary	282.40 FL	*- FL
18	1		*FRONT LOWER ARM LH	Not Necessary	268.50 FL	*- FL
19	1		*FRONT TIE ROD END LH	Not Necessary	189.60 FL	*- FL
20	1		*FRONT TIE ROD LH	Not Necessary	315.40 FL	*- FL
21	1		*FRONT SHOCK ABSORBER LH	Not Necessary	478.20 FL	*- FL
22	1		*FRONT SPORT RIM	Not Necessary	550.00 FS	*- FS
23	1		*FRONT TYRE RH	Not Necessary	310.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,924.80	1,395.00
- List Item Discount on L Items 10.00/10.00% (\$)	606.48	139.50
Total Parts (\$)	6,318.32	1,255.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,REPAIR & RENEW AFFECTED ACCIDENT AREAS	New	900.00	300.00
2	TO PUTTY ,SPRAY PAINT ON FRONT AFFECTED ACCIDENT AREAS	New	800.00	450.00
3	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	20.00
4	TO REMOVE & INSTALL FRONT RIGHT UNDERCARRIAGE COMPONENTS	New	250.00	0.00
5	TO CONDUCT ALL WHEEL ALIGNMENT	New	200.00	0.00
6	TO TRANSFER & REPLACE FRONT RIM & TYRE	New	100.00	0.00
7	TO DIAGNOSTIC & RESET TO SPECIFICATION	New	250.00	0.00
8	TO RUST PROOF AFFECTED AREAS	New	200.00	0.00
Gross Labour Cost (S\$)			2,750.00	770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >