



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2104493

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 27/06/2021
Reference CC3/CTI21004700/Qes3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHB 616T
Insured Veh. YN 7327S
Claim No. SNM21D202006/C02
Policy No. DMCVSNA00095662000
Accident Date 07/04/2021
Inspection Date 08/04/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Ref: CC3/CTI21004700/Qes3q2 Date: 27/06/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 7327S	Veh. Inspected	SHB 616T	
Policy No.	DMCVSNA00095662000	Coverage (\$)	0.00	
Claim No.	SNM21D202006/C02	Excess (\$)	0.00	
Assign From		Assign Date	08/04/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JTDKN36U105755148	Colour	MAROON	
Odometer	484624 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	ATREZZO	6 mm	
L/H Front Tyre	195/65 R15	ATREZZO	6 mm	
R/H Rear Tyre	195/65 R15	ATREZZO	6 mm	
L/H Rear Tyre	195/65 R15	ATREZZO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/04/2021	Inspection Date	08/04/2021	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 616T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER FRT (DISC 25%)	CRUMPLED	482.00	361.50
10	BUMPER CLIPS @\$1.61 (DISC 25%)	NECESSARY	16.10	12.08
1	BUMPER SUPPORT F/RH (DISC 25%)	BROKEN	76.40	57.30
1	FENDER FRT/RH (DISC 25%)	DENTED	723.40	542.55
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.93
1	HEAD LAMP RH (DISC 10%)	CRUMPLED	945.20	850.68
1	ADVERTISEMENT STICKER (SN)	NECESSARY	148.44	148.44
1	BUMPER SUPPORT F/LH	SERVICEABLE	76.40	-
1	BUMPER ENERGY ABSORBER FRT	SERVICEABLE	78.80	-
1	BUMPER REINFORCEMENT FRT	SERVICEABLE	498.40	-
1	ARM SUB-ASSY ,FR BUMPER LH	SERVICEABLE	250.40	-
1	ARM SUB-ASSY ,FR BUMPER RH	SERVICEABLE	250.40	-
1	BUMPER GRILLE SUB-ASSY ,LOWER	SERVICEABLE	311.10	-
1	WIRE ENGINE ROOM NO.3	SERVICEABLE	242.00	-
1	LENS & BODY ,FR TURN LH	SERVICEABLE	511.80	-
1	LENS & BODY ,FR TURN RH	SERVICEABLE	511.80	-
1	FOG LAMP RH	SERVICEABLE	295.20	-
1	COVER ,RADIATOR	SERVICEABLE	122.80	-
1	GRILLE ,RADIATOR	SERVICEABLE	310.60	-
1	GRILLE ,RADIATOR LOWER NO.2	SERVICEABLE	94.60	-
1	BUMPER LIP FRT	SERVICEABLE	139.60	-
1	UNDER COVER CENTER	SERVICEABLE	448.30	-
1	HOOD HINGE LH	SERVICEABLE	55.90	-
1	HOOD HINGE RH	SERVICEABLE	55.90	-
1	SUPPORT SUB-ASSY	SERVICEABLE	1,460.40	-
1	HEAD LAMP LH	SERVICEABLE	945.20	-
1	SUPPORT RADIATOR, RH	SERVICEABLE	54.50	-
1	INLET ASSY AIR	SERVICEABLE	232.50	-
1	AIR CLEANER ASSY	SERVICEABLE	929.90	-
1	FEBNDER LINER FRT/RH	SERVICEABLE	171.70	-
1	FENDER LINER PAD ,FR WHEEL ,RH	SERVICEABLE	49.30	-

Report Ref No. CC3/CTI21004700/Qes3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FENDER APRON SUB FRT/RH	SERVICEABLE	637.80	-
1	WHEEL DISC ,FRONT	SERVICEABLE	1,484.20	-
1	TYRE	SERVICEABLE	126.74	-
1	FENDER LINER FRT/LH	SERVICEABLE	171.70	-
1	FENDER LINER PAD ,FR WHEE, LH	SERVICEABLE	49.30	-
1	HOOD PANEL	TO REPAIR SEE LABOUR	748.10	-
			13,758.78	2,011.48
	LABOUR			
	PANEL BEATING & BODY WORK .INCLUSIVE OF THE REPAIR OF HOOD PANEL .		976.00	550.00
	SPRAY PAINT .		2,034.00	700.00
	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE).	NOT NECESSARY	120.00	-
	TO DO WHEEL ALIGNMENT /TYRE BALANCING .	NOT NECESSARY	120.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO CHECK WIRING AND SYSTEM FUNCTION .		80.00	20.00
	TO WASH AND VACUUM .	NOT NECESSARY	60.00	-
			3,490.00	1,270.00
GRAND TOTAL			17,248.78	3,281.48
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,900.00

Report Ref No. CC3/CTI21004700/Qes3q2

OI SUN PIN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHB 616T

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHB 616T

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

