



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2105697

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 13/08/2021
Reference CC6/CTI21004701/Aes3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SMF 4133M
Insured Veh. SLB 4117T
Claim No. SNM21D202075/C02
Policy No. DMPCSNW00135952001
Accident Date 10/04/2021
Inspection Date 13/04/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21004701/Aes3q2 Date: 13/08/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLB 4117T	Veh. Inspected	SMF 4133M	
Policy No.	DMPCSNW00135952001	Coverage (\$)	0.00	
Claim No.	SNM21D202075/C02	Excess (\$)	0.00	
Assign From		Assign Date	13/04/2021	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ CLA180	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	WDD1173422N672571	Colour	BROWN	
Odometer	33130 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/40 R18	CONTINENTAL	6 mm	
L/H Front Tyre	225/40 R18	CONTINENTAL	6 mm	
R/H Rear Tyre	225/40 R18	CONTINENTAL	6 mm	
L/H Rear Tyre	225/40 R18	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/04/2021	Inspection Date	13/04/2021	
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMF 4133M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DISTORTED	1,850.00	1,584.00
1	FRONT BUMPER LOGO	NECESSARY	130.50	130.50
2	FRONT BUMPER SIDE RETAINER @\$155.30	O/S DAMAGED	310.60	95.00
1	FRONT BUMPER SPONGE	CRACKED	203.00	203.00
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	233.50	-
1	FRONT BUMPER TOWING COVER	MISSING	98.40	35.00
1	FRONT BUMPER FOGLAMP COVER	DEFORMED	250.00	250.00
1	FRONT BUMPER UNDER COVER	TORN	420.90	329.00
1	HEADLAMP RH	CUT	3,500.00	2,953.00
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	980.00	-
2	FRONT REVERSE SENSOR @\$280.60	DAMAGED (1 PCS ONLY)	561.20	280.60
1	FRONT REVERSE SENSOR GARNISH	DAMAGED	115.70	115.70
	LESS 10% DISCOUNT		-865.38	-597.58
			7,788.42	5,378.22
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	20.00	20.00
			20.00	20.00
	<u>LABOUR</u>			
	PANEL BEATING ,REMOVING AND REPLACING PARTS.INCLUSIVE OF THE REPAIR OF FRONT FENDER RH .		1,000.00	400.00
	SPRAY PAINTING TO AFFECTED AREA.		1,000.00	500.00
	TUFF COAT.		150.00	30.00
	WIRING CHECK .		80.00	30.00
	TO RE-PROGRAMME.		120.00	120.00
			2,350.00	1,080.00
	GRAND TOTAL		10,158.42	6,478.22

Report Ref No. CC6/CTI21004701/Aes3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,000.00
---	--	--	----------

Report Ref No. CC6/CTI21004701/Aes3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMF 4133M

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMF 4133M

RE-INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

