

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21004702/KPA3Q2**Date:** 20/12/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800108579
Claimant Vehicle No :	SHD813E	Insured Vehicle No :	SKC9071P
Date of Loss:	06/04/2021	Nature of Claim:	TP
		Claim No:	1967113240SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD813E		
Make & Model:	MERCEDES-BENZ E220 BLUETEC, 2.1 D (A)	Engine No:	65192432919509
Reg. Date:	16/12/2015 (Man. Year: 2015)	Chassis No:	WDD2120012B224840
Colour:	White	Odometer:	523919 km
Engine Capacity:	2143 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R16	Rear Tyre Size:	225/55 R16
Front Left Side:	Giti 9 mm	Rear Left Side:	Giti 9 mm
Front Right Side:	Giti 9 mm	Rear Right Side:	Giti 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,820.81	1,425.00	10,395.81	87.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,070.00	480.00	6,590.00	93.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,890.81	1,905.00	16,985.81	89.92
Approved Total (Overridden) (S\$)		1,500.00		
(S\$)	18,890.81	1,500.00	17,390.81	92.06
+ GST 7.00/7.00% (S\$)	1,322.36	105.00	1,217.36	92.06
Nett Amount (S\$)	20,213.17	1,605.00	18,608.17	92.06
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	12/04/2021	
Date Inspected:	12/04/2021	Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled / Dented	3,105.00 FL	*1,510.00 FL
2	1		*REAR BUMPER LOWER	Serviceable	1,080.00 FL	*- FL
3	1		*REAR BUMPER CENTRE PAD	Serviceable	307.83 FL	*- FL
4	1		*REAR BUMPER SIDE PAD	Serviceable	186.33 FL	*- FL
5	1		*REAR BUMPER TOW HOOK COVER	Serviceable	63.00 FL	*- FL
6	1		*REAR BUMPER BRACKET	Repair	22.50 FL	*- FL
7	1		*REAR BUMPER SIDE RETAINER BRACKET	Serviceable	132.00 FL	*- FL
8	1		*REAR BUMPER INNER FRAME	Serviceable	297.00 FL	*- FL
9	1		*REAR BUMPER BOTTOM BRACKET	Serviceable	60.00 FL	*- FL
10	1		*REAR BUMPER TOP BRACKET	Serviceable	129.00 FL	*- FL
11	1		*REAR BUMPER SIDE HOLDER BRACKET	Serviceable	135.00 FL	*- FL
12	1		*REAR BUMPER INNER BRACKET LH	Repair	198.00 FL	*- FL
13	1		*REAR BUMPER INNER BRACKET RH	Repair	198.00 FL	*- FL
14	1		*REAR BUMPER BEAM	Repair	1,215.00 FL	*- FL
15	1		*REAR BUMPER BEAM BRACKET LH	Repair	307.50 FL	*- FL
16	1		*REAR BUMPER BEAM BRACKET RH	Repair	307.50 FL	*- FL
17	1		*REAR BUMPER BRACKET CENTRE	Serviceable	461.75 FL	*- FL
18	1		*REAR BUMPER RETAINER BRACKET LH	Repair	202.50 FL	*- FL
19	1		*REAR BUMPER RETAINER BRACKET RH	Repair	202.50 FL	*- FL
20	1		*REAR END PANEL OUTER	Repair	1,971.00 FL	*- FL
21	1		*REAR END PANEL INNER TRIM	Serviceable	630.00 FL	*- FL
22	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
23	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
24	1		*SET RIM	Serviceable	650.00 FS	*- FS
25	1		*SET BUMPER BRACKET CTR CLIP	Not Necessary	33.00 FS	*- FS
26	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
27	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
28	1		*SET FENDER CLIP	Not Necessary	60.00 FS	*- FS
29	1		*SET REAR END PANEL INNER TRIM CLIP	Not Necessary	90.00 FS	*- FS
30	1		*SET REAR BUMPER FASTENER CLIP	Not Necessary	101.54 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	12,941.95	1,576.00
- List Item Discount on L Items 10.00/10.00% (\$)	1,121.14	151.00
Total Parts (\$)	11,820.81	1,425.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	220.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	3,000.00	200.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
6	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
7	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
Gross Labour Cost (\$\$)			7,070.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >