



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKG 7376C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	645.30	645.30
1	REAR BUMPER LOWER	DEFORMED	245.90	245.90
2	REAR BUMPER SIDE RETAINER @\$92.30	NOT NECESSARY	184.60	-
1	REAR NUMBER PLATE GARNISH	NOT NECESSARY	68.00	-
1	REAR BUMPER LOWER COVER LH	NOT NECESSARY	197.80	-
1	REAR BUMPER LOWER COVER RH	NOT NECESSARY	205.60	-
1	REAR BUMPER REVERSE LAMP LH	CUT	202.50	202.50
1	REAR BUMPER REVERSE LAMP RH	NOT NECESSARY	202.50	-
1	REAR BUMPER REINFORCEMENT	CRACKED	387.90	387.90
2	REAR BUMPER REINFORCEMENT BRACKET-TOP @ \$64.80	NOT NECESSARY	129.60	-
3	REAR BUMPER REINFORCEMENT BRACKET-BOTTOM @ \$64.80	NOT NECESSARY	194.40	-
2	REAR BUMPER REINFORCEMENT BRACKET-METAL @ \$198.80	NOT NECESSARY	397.60	-
	LESS 20% DISCOUNT		-612.34	-296.32
			2,449.36	1,185.28
<u>SPECIAL NETT ITEMS</u>				
1	REAR NUMBER PLATE W CASING (SN)	NOT NECESSARY	50.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	SET REAR BUMPER LOWER CLIPS (SN)	NECESSARY	30.00	30.00
1	SET REVERSE CAMERA (SN)	NOT NECESSARY	250.00	-
1	SET REVERSE SENSOR (SN)	DAMAGED	250.00	200.00
			610.00	260.00
<u>LABOUR</u>				
	TO PANEL BEAT/STRAIGHTEN/REALIGN ACCIDENT AFFECTED AREAS.		1,000.00	250.00
	TO SPRAY PAINT ON AFFECTED AREAS.		1,000.00	250.00
	TO APPLY TUFF COAT ON AFFECTED AREAS.	NOT NECESSARY	100.00	-
	TO REMOVE/REFIX REAR INTERIOR UPHOLSTERY.	NOT NECESSARY	100.00	-
	TO CONDUCT WIRING/WIRE CONNECTOR CHECK AND REPAIR.		100.00	30.00

Report Ref No. CS/AGI21004705/Aqf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REPLACE/REFIX REAR REVERSE SENSOR AND DISTANCE SETTING.	NOT NECESSARY	150.00	50.00
	TO REMOVE/REFIX/REPLACE REVERSE CAMERA.		150.00	-
			2,600.00	580.00
GRAND TOTAL			5,659.36	2,025.28

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,600.00
--	--	--	--	----------

Report Ref No. CS/AGI21004705/Aqf3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.