

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21004711/APS3Q2  
**Date:** 25/10/2021**REFERENCE**

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 1700019216   |
| <b>Claimant Vehicle No :</b> | SLC9766G                             | <b>Insured Vehicle No :</b> | SLP5231R     |
| Date of Loss:                | 12/04/2021                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 4391867154SG |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SLC9766G</b>                   |             |                   |
| Make & Model:               | CHEVROLET CRUZE NB, 1.6 D 6AT (A) | Engine No:  | F16D4160880284    |
| Reg. Date:                  | 31/05/2016 (Man. Year: 2016)      | Chassis No: | KL1JA69E9GK341727 |
| Colour:                     | Blue                              | Odometer:   | 62069 km          |
| Engine Capacity:            | 1598 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |     |                         |     |                          |     |
|--------------------------|-----|-------------------------|-----|--------------------------|-----|
| General Condition:       |     | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification:    | No  | Pre-accident Condition:  |     |

**CONDITION OF TYRES**

|                   |             |                  |             |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size:  | 205/60 R16  | Rear Tyre Size:  | 205/60 R16  |
| Front Left Side:  | Dunlop 6 mm | Rear Left Side:  | Dunlop 6 mm |
| Front Right Side: | Dunlop 6 mm | Rear Right Side: | Dunlop 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 23,341.00         | 12,516.00         | 10,825.00         | 46.38         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 5,250.00          | 4,120.00          | 1,130.00          | 21.52         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>28,591.00</b>  | <b>16,636.00</b>  | <b>11,955.00</b>  | <b>41.81</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>10,000.00</b>  |                   |               |

|                                                  |                  |                  |                  |              |
|--------------------------------------------------|------------------|------------------|------------------|--------------|
| (S\$)                                            | 28,591.00        | 10,000.00        | 18,591.00        | 65.02        |
| <b>+ GST 7.00/7.00% (S\$)</b>                    | 2,001.37         | 700.00           | 1,301.37         | 65.02        |
| <b>Nett Amount (S\$)</b>                         | <b>30,592.37</b> | <b>10,700.00</b> | <b>19,892.37</b> | <b>65.02</b> |
| <b>+ Car Rental (11.0 x S\$100.00/day) (S\$)</b> |                  | 1,100.00         |                  |              |
| <b>+ Doc/Search Fee (S\$)</b>                    |                  | 7.45             |                  |              |
| <b>Nett Liability (S\$)</b>                      |                  | <b>11,807.45</b> |                  |              |
| <b>Global Sum Settlement (S\$)</b>               |                  | <b>11,800.00</b> |                  |              |

INSPECTION

Date of Assignment: 14/04/2021

Date Inspected: 14/04/2021

Estimated Period of Repair: 14.0 days

Inspected At:

Cas Garage Pte Ltd (HQ)  
 No.1, Kaki Bukit Ave 6, #02-22 Autobay  
 Singapore 417883

**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                              | Condition            | Repairer's  | Amount       |
|-----|-----|----------|------------------------------------------|----------------------|-------------|--------------|
| 1   | 1   |          | *FRONT BONNET                            | Dented               | 1,344.00 FL | *1,344.00 FL |
| 2   | 1   |          | *FRONT BUMPER                            | Deformed             | 1,326.00 FL | *1,326.00 FL |
| 3   | 1   |          | *FRONT BUMPER TOP GRILLE                 | Cracked              | 384.00 FL   | *384.00 FL   |
| 4   | 1   |          | *FRONT BUMPER CENTER GRILLE              | Cracked              | 496.00 FL   | *496.00 FL   |
| 5   | 1   |          | *FRONT BUMPER LOWER GRILLE               | Cracked              | 116.00 FL   | *116.00 FL   |
| 6   | 1   |          | *FRONT BUMPER LOWER GRILLE -LH           | Not Necessary        | 92.00 FL    | *- FL        |
| 7   | 1   |          | *FRONT BUMPER LOWER GRILLE -RH           | Not Necessary        | 92.00 FL    | *- FL        |
| 8   | 1   |          | *FRONT BUMPER LOGO                       | Necessary            | 83.00 FL    | *83.00 FL    |
| 9   | 1   |          | *FRONT BUMPER NUMBER PLATE GARNISH       | Deformed             | 63.00 FL    | *63.00 FL    |
| 10  | 2   |          | *FRONT BUMPER SIDE RETAINERS             | Necessary            | 72.00 FL    | *72.00 FL    |
| 11  | 2   |          | *FRONT BUMPER FOG LAMP                   | Not Necessary        | 768.00 FL   | *- FL        |
| 12  | 2   |          | *FRONT BUMPER FOG LAMP COVER             | Not Necessary        | 850.00 FL   | *- FL        |
| 13  | 1   |          | *FRONT BUMPER REINFORCEMENT              | Bent                 | 480.00 FL   | *480.00 FL   |
| 14  | 1   |          | *FRONT BUMPER REINFORCEMENT SPONGE       | Cracked              | 144.00 FL   | *144.00 FL   |
| 15  | 1   |          | *FRONT SUPPORT PANEL                     | Repair               | 352.00 FL   | *- FL        |
| 16  | 1   |          | *FRONT SUPPORT PANEL TOP GARNISH         | Cracked              | 147.00 FL   | *147.00 FL   |
| 17  | 1   |          | *RADIATOR ASSY                           | Not Necessary        | 915.00 FL   | *- FL        |
| 18  | 1   |          | *RADIATOR FAN MOTOR W BLADE              | Not Necessary        | 653.00 FL   | *- FL        |
| 19  | 1   |          | *RADIATOR FAN COWLING                    | Not Necessary        | 316.00 FL   | *- FL        |
| 20  | 1   |          | *AC CONDENSER                            | Dented               | 877.00 FL   | *877.00 FL   |
| 21  | 1   |          | *HEADLAMP LH                             | Not Necessary        | 2,252.00 FL | *- FL        |
| 22  | 1   |          | *HEADLAMP BRACKET LH                     | Not Necessary        | 38.00 FL    | *- FL        |
| 23  | 1   |          | *HEADLAMP RH                             | Not Necessary        | 2,252.00 FL | *- FL        |
| 24  | 1   |          | *HEADLAMP BRACKET RH                     | Not Necessary        | 38.00 FL    | *- FL        |
| 25  | 1   |          | *REAR BUMPER                             | Distorted            | 1,436.00 FL | *1,436.00 FL |
| 26  | 1   |          | *REAR BUMPER CHROME MOULDING LH          | Necessary            | 82.00 FL    | *82.00 FL    |
| 27  | 1   |          | *REAR BUMPER CHROME MOULDING RH          | Necessary            | 82.00 FL    | *82.00 FL    |
| 28  | 1   |          | *REAR BUMPER CHROME MOULDING CENTER      | Cracked              | 155.00 FL   | *155.00 FL   |
| 29  | 2   |          | *REAR BUMPER SIDE RETAINER -INNER        | Not Necessary        | 72.00 FL    | *- FL        |
| 30  | 2   |          | *REAR BUMPER SIDE RETAINER -OUTER        | Necessary            | 72.00 FL    | *72.00 FL    |
| 31  | 1   |          | *REAR BUMPER CENTER RETAINER             | Cracked              | 44.00 FL    | *44.00 FL    |
| 32  | 4   |          | *REAR BUMPER REVERSE SENSOR              | Damaged (2 PCS ONLY) | 768.00 FL   | *384.00 FL   |
| 33  | 4   |          | *REAR BUMPER REVERSE SENSOR RUBBER SEAL  | Necessary            | 48.00 FL    | *48.00 FL    |
| 34  | 1   |          | *REAR BUMPER REVERSE SENSOR WIRE HARNESS | Not Necessary        | 129.00 FL   | *- FL        |
| 35  | 1   |          | *REAR BUMPER TOW COVER                   | Deformed             | 46.00 FL    | *46.00 FL    |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                          | Condition             | Repairer's  | Amount       |
|-----|-----|----------|--------------------------------------|-----------------------|-------------|--------------|
| 36  | 1   |          | *REAR BUMPER REINFORCEMENT           | Distorted             | 320.00 FL   | *320.00 FL   |
| 37  | 2   |          | *REAR NUMBER PLATE LAMP              | Not Necessary         | 108.00 FL   | *- FL        |
| 38  | 1   |          | *BOOTLID                             | Dented                | 421.00 FL   | *421.00 FL   |
| 39  | 1   |          | *BOOTLID LOGO                        | Necessary             | 72.00 FL    | *72.00 FL    |
| 40  | 1   |          | *BOOTLID CHEVROLET EMBLEM            | Necessary             | 32.00 FL    | *32.00 FL    |
| 41  | 1   |          | *BOOTLID CRUZE LS EMBLEM             | Necessary             | 42.00 FL    | *42.00 FL    |
| 42  | 1   |          | *BOOTLID LOCK                        | Damaged               | 86.00 FL    | *86.00 FL    |
| 43  | 1   |          | *BOOTLID LOCK KEYLESS SENSOR         | Cracked               | 127.00 FL   | *127.00 FL   |
| 44  | 2   |          | *BOOTLID HINGES                      | Not Necessary         | 110.00 FL   | *- FL        |
| 45  | 1   |          | *BOOTLID INSULATOR                   | Not Necessary         | 145.00 FL   | *- FL        |
| 46  | 1   |          | *BOOTLID WEATHERSTRIP                | Cut                   | 183.00 FL   | *183.00 FL   |
| 47  | 2   |          | *BOOTLID LAMP                        | N/S Cut / O/S Cracked | 796.00 FL   | *796.00 FL   |
| 48  | 2   |          | *TAILLAMPS                           | Cracked               | 1,042.00 FL | *1,042.00 FL |
| 49  | 2   |          | *REAR FENDER                         | Repair                | 1,788.00 FL | *- FL        |
| 50  | 2   |          | *REAR FENDER INNER COWLING           | Not Necessary         | 240.00 FL   | *- FL        |
| 51  | 2   |          | *REAR FENDER INNER TRIM              | Not Necessary         | 256.00 FL   | *- FL        |
| 52  | 1   |          | *END PANEL                           | Distorted             | 978.00 FL   | *978.00 FL   |
| 53  | 1   |          | *END PANEL TOP GARNISH               | Deformed              | 124.00 FL   | *124.00 FL   |
| 54  | 1   |          | *SPARE TYRE PANEL                    | Distorted             | 898.00 FL   | *898.00 FL   |
| 55  | 1   |          | *SPARE TYRE PANEL TOP BOARD          | Deformed              | 238.00 FL   | *238.00 FL   |
| 56  | 1   |          | *FRONT NUMBER PLATE W CASING         | Cracked               | 70.00 FS    | *50.00 FS    |
| 57  | 1   |          | *REAR NUMBER PLATE W CASING          | Cracked               | 70.00 FS    | *50.00 FS    |
| 58  | 1   |          | *SET FRONT NUMBER CLIPS              | Necessary             | 30.00 FS    | *30.00 FS    |
| 59  | 1   |          | *SET SUPPORT PANEL TOP GARNISH CLIPS | Necessary             | 30.00 FS    | *30.00 FS    |
| 60  | 1   |          | *SET REAR BUMPER CLIPS               | Necessary             | 30.00 FS    | *30.00 FS    |
| 61  | 1   |          | *SET BOOTLID INNER TRIM CLIPS        | Not Necessary         | 30.00 FS    | *- FS        |
| 62  | 1   |          | *SET REAR FENDER INNER TRIM CLIPS    | Not Necessary         | 30.00 FS    | *- FS        |
| 63  | 1   |          | *SET REAR FENDER INNER COWLING CLIPS | Not Necessary         | 30.00 FS    | *- FS        |
| 64  | 1   |          | *END PANEL SEALANT                   | Necessary             | 80.00 FS    | *60.00 FS    |
| 65  | 1   |          | *SET END PANEL TOP GARNISH CLIPS     | Necessary             | 30.00 FS    | *20.00 FS    |
| 66  | 1   |          | *SPARE TYRE SEALANT                  | Necessary             | 80.00 FS    | *80.00 FS    |
| 67  | 1   |          | *SET REVERSE CAMERA                  | Damaged               | 250.00 FS   | *250.00 FS   |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                  |                  |
|------------------------------------------------------------|------------------|------------------|
| <b>Sub Total (\$\$)</b>                                    | <b>25,850.00</b> | <b>13,840.00</b> |
| <b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b> | 2,509.00         | 1,324.00         |
| <b>Total Parts (\$\$)</b>                                  | <b>23,341.00</b> | <b>12,516.00</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                                | Lab.Type | Repairer's      | Amount          |
|--------------------------------|------------------------------------------------------------|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>     |                                                            |          |                 |                 |
| 1                              | TO PANEL BEAT /STRAIGHTEN /REALIGN ACCIDENT AFFECTED AREAS | New      | 2,000.00        | 1,800.00        |
| 2                              | TO SPRAY PAINT ON AFFECTED AREAS                           | New      | 2,000.00        | 1,800.00        |
| 3                              | TO APPLY TUFF COAT ON AFFECTED AREAS                       | New      | 100.00          | 60.00           |
| 4                              | TO APPLY UNDERCOATING ON AFFECTED AREAS                    | New      | 100.00          | 60.00           |
| 5                              | TO REPLACE /TRANSFER BOOTLID COMPONENTS                    | New      | 150.00          | 80.00           |
| 6                              | TO REMOVE/REFIX FUEL TANK                                  | New      | 200.00          | 80.00           |
| 7                              | TO REMOVE /REFIX REAR INTERIOR UPHOLSTERY                  | New      | 150.00          | 80.00           |
| 8                              | TO CONDUCT WIRING /WIRE CONNECTOR CHECK AND REPAIR         | New      | 100.00          | 60.00           |
| 9                              | TO STRAIGHTEN EXHAUST PIPE                                 | New      | 150.00          | 0.00            |
| 10                             | TO REPLACE /REFIX REAR REVERSE SENSOR AND DISTANCE SETTING | New      | 150.00          | 50.00           |
| 11                             | TO REMOVE /REFIX /REPLACE REVERSE CAMERA                   | New      | 150.00          | 50.00           |
| <b>Gross Labour Cost (S\$)</b> |                                                            |          | <b>5,250.00</b> | <b>4,120.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >