

LCL APPRAISER PTE LTD

24 Peshurst Place, Singapore 556440

Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783

Reg No: 20100228E

VEHICLE INSPECTION REPORT

To: Hey Dingdong Pte Ltd
C/o: Sheng Li Lai
2 Kaki Bukit Avenue 2
#01-36 Kaki Bukit Autohub, Singapore 417921

Date : 3 February 2021
Our ref : SLL/01/2101/TP

Accident Date : 20 January 2021
Inspection Date : 22 January 2021
Repairer Name : Sheng Li Lai
2 Kaki Bukit Avenue 2
#01-36 Kaki Bukit Autohub, Singapore 417921

Type of Survey : Third Party

PARTICULARS OF VEHICLE

Registration No	: GR 60 Z	Year / Capacity	: 2016 / 2982 cc
Make / Model	: Toyota Hiace	Colour	: Silver
Chassis No	: KDH2015022277	Mileage	: 124594
Engine No	: 1KD2614273		

CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front Nearside	: Westlake	195 R15	5 mm	Normal
Front Offside	: Westlake	195 R15	5 mm	Normal
Rear Nearside	: Westlake	195 R15	5 mm	Normal
Rear Offside	: Westlake	195 R15	5 mm	Normal

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the n/s rear portion.
(Details refer to the photographs attached)

Enclosed number of photographs: 45 copies

REMARKS

This inspection was conducted entirely on a "**WITHOUT PREJUDICE**" basis and we have not given authorization and instruction to the repairer to proceed with the repair.

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a Lump Sum of \$3,900.00 on a contractual basis.

Under normal circumstances, the repair period would be about 5 (Five) working days.

SCL APPRAISER PTE LTD

Vehicle Registration No.: GR 60 Z

Our Ref No.:

SLL/01/2101/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

SPARE PARTS - LIST ITEMS

1	Rear n/s taillamp lower garnish	Damage	\$ 175.00	\$ 175.00	
1	Rear end panel	Intact	\$ 887.90		
1	Rear bumper	Damage	\$ 695.20	\$ 695.20	625
1	Rear bumper clip (1 set)	Necessary	\$ 50.00	\$ 50.00	30
1	Rear bumper n/s side retainer	Necessary	\$ 66.20	\$ 66.20	
1	Rear n/s side body panel	Damage	\$ 1,765.50	\$ 1,765.50	1382
1	Rear n/s side body quarter glass inner seal	Necessary	\$ 110.00	\$ 110.00	
1	Rear n/s wheel rim cap	Damage	\$ 126.80	\$ 126.80	
			\$ 3,876.60	\$ 2,988.70	
			<i>Less 25%</i>	<i>\$ 969.15</i>	
Total Cost - List Items			\$ 2,907.45	\$ 2,241.53	2515
					1886.25

SPECIAL NETT ITEMS

1	Rear taillamp (1 set)	Damage	\$ 800.00	\$ 800.00	Xnn
1	Rear n/s side panel quarter glass sealant	Necessary	\$ 80.00	\$ 50.00	
Total Cost - Special Nett items			\$ 880.00	\$ 850.00	
					50

Total cost of parts

\$ 3,787.45 \$ 3,091.53

Vehicle Registration No.: GR 60 Z

Our Ref No.: SLL/01/2101/TP

S/No	Description	Repairer's Estimate	Revised Amount
	Total cost of parts c/f	\$ 3,787.45	\$ 3,091.53

LABOUR

1	To remove, refit, replaced damaged lamps and check up rear electrical wiring	\$ 80.00	\$ 50.00 30
2	To remove and refit inner garnishes, inner trim to assist repair.	\$ 150.00	\$ 120.00 60
3	To remove and refit quarter glass to assist repair.	\$ 150.00	\$ 120.00
4	To apply undercoating on repaired and replaced panel.	\$ 100.00	\$ 60.00 40
5	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident.	\$ 1,080.00	\$ 750.00 600
6	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 1,000.00	\$ 660.00 600

1450

GRAND TOTAL

\$ 6,347.45	\$ 4,851.53
-------------	-------------

3386.25
L/\$2700
5 days

Vehicle Registration No.: GR 60 Z

Our Ref No.: SLL/01/2101/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 3,900.00**

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be vaild.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD



Cheong K. H
Automotive Appraiser























