

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	LONPAC INSURAN	NCE BHD		Ref:	CS3/LPC21001035/T1vf3e2-1	
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555		Date:	23/04/2021	
				Code:	LPC2	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	GBB 1771S	Veh. Inspected	t	GR 60Z	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	20/21/21/VC00/024158	Excess (\$)		0.00	
	Assign From	ONG LI LI	Assign Date		14/04/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA HIACE	c.c		2982	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	KDH2015022277	Colour		SILVER	
	Odometer	124594 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195 R15	WEST LAKE		6 mm	
	L/H Front Tyre	195 R15	WEST LAKE		6 mm	
	R/H Rear Tyre	195 R15	WEST LAKE		6 mm	
	L/H Rear Tyre	195 R15	WEST LAKE		6 mm	
4.	4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	20/01/2021	Inspection Dat	te	22/01/2021	
	Survey held at	SHENG LI LAI	-			
		2 KAKI BUKIT AVE 2 #01-36 KAKI BUKIT AUTOHUB SINGAPORE 417921				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					