

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

**Our File No:** CC4/AIG21004719/KPS3Q2  
**Date:** 09/09/2021

**REFERENCE**

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 2070106444   |
| <b>Claimant Vehicle No :</b> | SKB9586B                             | <b>Insured Vehicle No :</b> | GBK3986D     |
| Date of Loss:                | 11/04/2021                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 3186539993SG |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                           |             |                   |
|-----------------------------|-------------------------------------------|-------------|-------------------|
| Reg No:                     | <b>SKB9586B</b>                           | Engine No:  | G4FGBU282370      |
| Make & Model:               | HYUNDAI ELANTRA, 1.6 ABS D/AB 2WD 4DR (A) | Chassis No: | KMHDH41CMCU219424 |
| Reg. Date:                  | 13/07/2011 (Man. Year: 2011)              | Odometer:   | 129185 km         |
| Colour:                     | Metallic Silver                           |             |                   |
| Engine Capacity:            | 1591 cc                                   |             |                   |
| Market Value/New Car Price: | N/A                                       |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b>         |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

**CONDITION OF TYRES**

|                   |              |                  |              |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size:  | 205/55 R16   | Rear Tyre Size:  | 205/55 R16   |
| Front Left Side:  | Pirelli 7 mm | Rear Left Side:  | Pirelli 7 mm |
| Front Right Side: | Pirelli 7 mm | Rear Right Side: | Pirelli 7 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 5,687.94          | 2,650.98          | 3,036.96          | 53.39         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 3,100.00          | 1,350.00          | 1,750.00          | 56.45         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>8,787.94</b>   | <b>4,000.98</b>   | <b>4,786.96</b>   | <b>54.47</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>3,200.00</b>   |                   |               |

|                                                 |                 |                 |                 |              |
|-------------------------------------------------|-----------------|-----------------|-----------------|--------------|
| (S\$)                                           | 8,787.94        | 3,200.00        | 5,587.94        | 63.59        |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 615.16          | 224.00          | 391.16          | 63.59        |
| <b>Nett Amount (S\$)</b>                        | <b>9,403.10</b> | <b>3,424.00</b> | <b>5,979.10</b> | <b>63.59</b> |
| <b>+ Loss of Use (6.0 x S\$50.00/day) (S\$)</b> |                 | 300.00          |                 |              |
| <b>+ Other Costs (S\$)</b>                      |                 | 21.40           |                 |              |
| <b>Nett Liability (S\$)</b>                     |                 | <b>3,745.40</b> |                 |              |

INSPECTION

Date of Assignment: 14/04/2021

Date Inspected: 14/04/2021

Estimated Period of Repair: 5.0 days

Inspected At: Kgc Workshop Pte Ltd (AMK)  
14 Ang Mo Kio Street 63, Blk B  
Singapore 569116

**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                 | Condition     | Repairer's  | Amount       |
|-----|-----|----------|-----------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *REAR BUMPER                | Buckled       | 635.80 FL   | *459.40 FL   |
| 2   | 1   |          | *REAR BUMPER RETAINER LHS   | Distorted     | 38.20 FL    | *38.20 FL    |
| 3   | 1   |          | *REAR BUMPER RETAINER RHS   | Serviceable   | 38.20 FL    | *- FL        |
| 4   | 1   |          | *REAR BUMPER REINFORCEMENT  | Bent          | 323.30 FL   | *323.30 FL   |
| 5   | 2   |          | *REAR BUMPER INNER BRACKET  | Serviceable   | 133.60 FL   | *- FL        |
| 6   | 1   |          | *REAR BUMPER GUARD PAD LHS  | Serviceable   | 45.20 FL    | *- FL        |
| 7   | 1   |          | *REAR BUMPER GUARD PAD RHS  | Serviceable   | 45.20 FL    | *- FL        |
| 8   | 1   |          | *REAR BUMPER REFLECTOR RHS  | Serviceable   | 65.78 FL    | *- FL        |
| 9   | 1   |          | *REAR BUMPER REFLECTOR LHS  | Cracked       | 65.78 FL    | *65.78 FL    |
| 10  | 1   |          | *BOOTLID                    | Bent          | 1,840.00 FL | *1,128.00 FL |
| 11  | 1   |          | *BOOTLID INNER TRIM         | Serviceable   | 98.20 FL    | *- FL        |
| 12  | 1   |          | *BOOTLID LOCK               | Dented        | 108.60 FL   | *108.60 FL   |
| 13  | 1   |          | *BOOTLID WEATHER STRIP      | Serviceable   | 85.80 FL    | *- FL        |
| 14  | 1   |          | *BOOTLID EMBLEM LOGO        | Necessary     | 32.50 FL    | *32.50 FL    |
| 15  | 1   |          | *BOOTLID EMBLEM HYUNDAI     | Necessary     | 42.20 FL    | *42.20 FL    |
| 16  | 1   |          | *BOOTLID EMBLEM ELANTRA     | Necessary     | 48.80 FL    | *48.80 FL    |
| 17  | 1   |          | *BOOTLID EMBLEM GLS         | Necessary     | 35.30 FL    | *35.30 FL    |
| 18  | 1   |          | *BOOTLID HINGES RHS         | Repair        | 98.30 FL    | *- FL        |
| 19  | 1   |          | *BOOTLID HINGES LHS         | Repair        | 98.30 FL    | *- FL        |
| 20  | 1   |          | *REAR END PANEL             | Repair        | 580.50 FL   | *- FL        |
| 21  | 1   |          | *REAR END PANEL INNER TRIM  | Serviceable   | 89.50 FL    | *- FL        |
| 22  | 1   |          | *REAR FENDER INNER TRIM LHS | Serviceable   | 171.70 FL   | *- FL        |
| 23  | 1   |          | *REAR FLOOR COVER           | Serviceable   | 315.27 FL   | *- FL        |
| 24  | 1   |          | *REAR AIR VENT GRILLE LHS   | Serviceable   | 35.60 FL    | *- FL        |
| 25  | 1   |          | *TAILLAMP RHS (BODY)        | Serviceable   | 388.00 FL   | *- FL        |
| 26  | 1   |          | *TAILLAMP LHS (BODY)        | Mtg Cracked   | 388.00 FL   | *388.00 FL   |
| 27  | 1   |          | *TAILLAMP RHS (BOOTLID )    | Serviceable   | 274.90 FL   | *- FL        |
| 28  | 1   |          | *TAILLAMP LHS (BOOTLID )    | Cut           | 274.90 FL   | *274.90 FL   |
| 29  | 1   |          | *SET REAR BUMPER CLIPS      | Necessary     | 50.00 FS    | *50.00 FS    |
| 30  | 1   |          | *SET REAR END PANEL CLIPS   | Not Necessary | 30.00 FS    | *- FS        |
| 31  | 1   |          | *SET REAR END PANEL SEALANT | Not Necessary | 50.00 FS    | *- FS        |
| 32  | 1   |          | *SET REVERSE SENSOR         | Dented        | 380.00 FS   | *200.00 FS   |
| 33  | 1   |          | *SET NO PLATE WITH CASING   | Necessary     | 60.00 FS    | *45.00 FS    |

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)

6,967.43

3,239.98

Report was unsubmitted during this print-out.

| No.                                                | Qty | Part No. | Particulars | Condition | Repairer's | Amount   |
|----------------------------------------------------|-----|----------|-------------|-----------|------------|----------|
| - List Item Discount on L Items 20.00/20.00% (S\$) |     |          |             |           | 1,279.49   | 589.00   |
| Total Parts (S\$)                                  |     |          |             |           | 5,687.94   | 2,650.98 |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                                                                                                          | Lab.Type | Repairer's      | Amount          |
|--------------------------------|--------------------------------------------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>     |                                                                                                                                      |          |                 |                 |
| 1                              | TO DISMANTLE ,REPLACE ,CUT ,WELD KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTION REPAIR PARTS .INCLUSIVE OF REPACEMENT PARTS | New      | 1,500.00        | 600.00          |
| 2                              | TO PUTTY AND SPRAY PAINT ON ALL ACCIDENT DAMAGE PARTS AND OTHER ACCIDENT AFFECTED AREAS                                              | New      | 1,200.00        | 600.00          |
| 3                              | TO REMOVE AND REFIT REVERSE SENSOR AND CONDUCT SAFE DISTANCE SETTING                                                                 | New      | 100.00          | 50.00           |
| 4                              | TO REMOVE AND REFIT REAR END PANEL LINING AND GARNISH TO FACILITATE REPAIR                                                           | New      | 100.00          | 50.00           |
| 5                              | TO CHECK WIRING SYSTEM TO FACILITATE REPAIR AND REFIT THE SAME                                                                       | New      | 100.00          | 20.00           |
| 6                              | APPLY RUST PROOFING ON THE ADJACENT PANELS                                                                                           | New      | 100.00          | 30.00           |
| <b>Gross Labour Cost (S\$)</b> |                                                                                                                                      |          | <b>3,100.00</b> | <b>1,350.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >