



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. JSH 1804

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	SET COVER	SCRATCHED	350.00	350.00
1	MIRROR	CRACKED	30.00	30.00
1	HANDLE BAR	BENT	75.00	75.00
1	FOOTREST	BENT	250.00	250.00
1	HEADLIGHT	SCRATCHED	85.00	85.00
1	LEVER	SERVICEABLE	25.00	-
1	FORK (FRONT)	BENT	220.00	220.00
1	FOOTREST PEDAL	SERVICEABLE	75.00	-
1	FOOTREST BRACKET (REAR)	BENT	55.00	55.00
1	GEAR LEVER	BENT	45.00	45.00
1	UNDER BRACKET	BENT	220.00	220.00
1	STEERING CONE	NECESSARY	85.00	85.00
1	METER	CRACKED	240.00	240.00
	LESS 10% DISCOUNT		-175.50	-165.50
			1,579.50	1,489.50
1	RIM (F&R) (LOCAL REPAIR) (SN)	SCRATCHED	350.00	30.00
	LESS 10% DISCOUNT		-35.00	-
			315.00	30.00
<u>SPECIAL NETT ITEMS</u>				
1	NO. PLATE (SN)	SCRATCHED	25.00	10.00
			25.00	10.00
<u>LABOUR</u>				
	TOWING FEE.		60.00	40.00
	ALIGN BODY.		200.00	150.00
	LABOUR CHARGES.		350.00	300.00
			610.00	490.00
GRAND TOTAL			2,529.50	2,019.50



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,600.00
---	--	--	-----------------

Report Ref No. CS/SMR21004720/R1uf3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.