

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21004722/EVF3E2

Date: 27/04/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100461354
Claimant Vehicle No :	FBG9549P	Insured Vehicle No :	SGJ8788Y
Date of Loss:	10/04/2021	Nature of Claim:	TP
		Claim No:	1797242931SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBG9549P	Engine No:	JA203E2000242
Make & Model:	HONDA ANF125MSS A, 125cc	Chassis No:	MLHJA2038B5000242
Reg. Date:	14/01/2013 (Man. Year: 2012)	Odometer:	0 km
Colour:	Black		
Engine Capacity:	125 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	70/80-17	Rear Tyre Size:	80/90-17
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	14/04/2021		
Date Inspected:	14/04/2021	Inspected At:	Equator Brotherhood (HQ) 25 KAKI BUKIT ROAD 4 #03-19 SYNERGY @KB SINGAPORE 417800
Estimated Period of Repair:	3.0 days		

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP FAIRING	Broken	0.00 F	*- F
2	1		*FRONT WING MIRROR	Cut	0.00 F	*- F
3	1		*STEERING CONE	Necessary	0.00 F	*- F
4	1		*HANDLE BAR	Bent	0.00 F	*- F
5	1		*HANDLE BAR BALANCER LH	Cut	0.00 F	*- F
6	1		*SIDE FAIRING (REAR)	Cut	0.00 F	*- F
7	1		*FAIRING SHIELD	Cut	0.00 F	*- F
8	1		*CENTER FAIRING	Broken	0.00 F	*- F
9	1		*FRONT FOOT REST	Torn	0.00 F	*- F
10	1		*FRONT FOOT REST BRACKET	Bent	0.00 F	*- F
11	1		*FOOT GEAR SHIFTER (LH)	Bent	0.00 F	*- F
12	1		*REAR FENDER WHEEL GUARD	Cut	0.00 F	*- F
13	1		*SWING ARM	Bent	0.00 F	*- F
14	1		*REAR TAILLAMP	Cut	0.00 F	*- F
15	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F
16	1		*REAR BOX	Cut	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
-------------------	------	------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >