

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG21004726/AQF3N2**Date:** 18/11/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900166498
Claimant Vehicle No :	SLN8137X	Insured Vehicle No :	SMP3980M
Date of Loss:	13/04/2021	Nature of Claim:	TP
		Claim No:	1881804205SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN8137X	Engine No:	2NR8724586
Make & Model:	TOYOTA SIENTA, 1.5 G CVT (A)	Chassis No:	NSP1707075638
Reg. Date:	18/05/2017 (Man. Year: 2016)	Odometer:	56469 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	31,850.30	21,983.35	9,866.95	30.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,700.00	6,340.00	1,360.00	17.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	39,550.30	28,323.35	11,226.95	28.39
Approved Total (Overridden) (S\$)		22,650.00		
Nett Amount (S\$)	39,550.30	22,650.00	16,900.30	42.73

INSPECTION

Date of Assignment:	14/04/2021	Unimotor Company - Kaki Bukit (HQ)
Date Inspected:	14/04/2021 Inspected At:	1 KAKI BUKIT AVE 6, #01-94 (AUTOBAY @ KAKI BUKIT)
Estimated Period of Repair:	24.0 days	Singapore 417883

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET ASSY	Distorted	883.20 FL	*883.20 FL
2	2		*FRONT BONNET HINGES	Bent	224.00 FL	*224.00 FL
3	1		*FRONT BONNET LOCK	Damaged	212.20 FL	*212.20 FL
4	1		*FRONT TOYOTA EMBLEM	Necessary	122.40 FL	*122.40 FL
5	1		*FRONT RADIATOR GRILLE ASSY	Cracked	848.00 FL	*596.00 FL
6	1		*FRONT RADIATOR ASSY	Dented	2,230.00 FL	*1,288.00 FL
7	2		*FRONT RADIATOR TOP BRACKET	Not Necessary	100.00 FL	*- FL
8	1		*FRONT RADIATOR TOP GARNISH	Not Necessary	198.00 FL	*- FL
9	1		*FRONT RADIATOR FAN MOTOR	Not Necessary	387.80 FL	*- FL
10	1		*FRONT RADIATOR FAN COWLING	Not Necessary	212.60 FL	*- FL
11	1		*FRONT L/H RADIATOR SIDE COVER GARNISH	Deformed	155.60 FL	*155.60 FL
12	1		*FRONT R/H RADIATOR SIDE COVER GARNISH	Deformed	211.30 FL	*211.30 FL
13	1		*FRONT AIR CON CONDENSOR	Bent	1,552.20 FL	*1,129.00 FL
14	1		*FRONT AIR CON SUCTION PIPE	Not Necessary	236.00 FL	*- FL
15	1		*FRONT AIR CON DISCHARGE PIPE	Not Necessary	168.00 FL	*- FL
16	1		*FRONT AIR CON RECEIVER PIPE	Not Necessary	314.00 FL	*- FL
17	1		*FRONT FENDER ASSY	N/s Buckled	928.00 FL	*464.00 FL
18	1		*FRONT LOWER SHIELD	Not Necessary	156.00 FL	*- FL
19	2		*FRONT HEADLAMP ASSY (LED)	Cracked	5,978.00 FL	*5,680.00 FL
20	2		*FRONT HEADLAMP LOWER BRACKETS	Not Necessary	180.00 FL	*- FL
21	1		*FRONT SUPPORT PANEL	Buckled	980.00 FL	*745.00 FL
22	1		*FRONT BRACE PANEL	Bent	187.60 FL	*187.60 FL
23	1		*FRONT BUMPER FACE	Deformed	598.00 FL	*598.00 FL
24	2		*FRONT BUMPER SIDE PROTECTOR GARNISH	Not Necessary	540.00 FL	*- FL
25	1		*FRONT BUMPER REINFORCEMENT	Dented	520.00 FL	*347.00 FL
26	1		*FRONT BUMPER INNER WHITE SPONGE	Cracked	155.80 FL	*155.80 FL
27	2		*FRONT BUMPER FOG LAMP	Not Necessary	588.00 FL	*- FL
28	1		*FRONT BUMPER FOG LAMP COVER	Not Necessary	320.00 FL	*- FL
29	2		*FRONT BUMPER SIDE RETAINER	Damaged	179.20 FL	*179.20 FL
30	2		*FRONT BUMPER CENTRE TOP BRACKET	Bent	192.00 FL	*192.00 FL
31	12		*FRONT BUMPER CLIPS	Necessary	60.00 FL	*30.00 FL
32	1		*REAR BOOT ASSY	Distorted	1,350.00 FL	*1,280.00 FL
33	1		*REAR BOOT LOCK	Jammed	285.00 FL	*285.00 FL
34	1		*REAR BOOT STRIKER	Bent	34.00 FL	*34.00 FL
35	2		*REAR BOOT HINGES	Not Necessary	98.00 FL	*- FL
36	1		*REAR BOOT FULL HANDLE	Deformed	28.00 FL	*28.00 FL
37	1		*REAR BOOT WEATHERSTRIP	Cut	296.00 FL	*296.00 FL
38	1		*REAR BOOT INNER COVER LINING	Not Necessary	233.00 FL	*- FL
39	2		*REAR BOOT STAY OPEN ABSORBER	Damaged	520.00 FL	*520.00 FL
40	1		*REAR BOOT OUTER GARNISH	Deformed	288.00 FL	*288.00 FL
41	1		*REAR BOOT KEY ANTENNA SENSOR	Cracked	185.00 FL	*185.00 FL
42	1		*REAR BOOT TOYOTA LOGO	Necessary	65.00 FL	*65.00 FL
43	1		*REAR BOOT WIPER MOTOR	Damaged	413.50 FL	*413.50 FL
44	1		*REAR BOOT WIPER ARM	Not Necessary	98.00 FL	*- FL
45	1		*REAR BOOT WIPER BLANDE	Not Necessary	32.00 FL	*- FL
46	1		*REAR BOOT WIPER ARM COVER	Not Necessary	18.00 FL	*- FL
47	2		*REAR BOOT NUMBER PLATE LAMP	Cracked	122.00 FL	*122.00 FL
48	2		*REAR BOOT LAMP ASSY	Cracked	640.00 FL	*640.00 FL
49	1		*REAR BOOT WINDSCREEN ASSY	Not Necessary	1,012.00 FL	*- FL
50	1		*REAR BOOT GLASS MOULDING	Necessary	224.00 FL	*224.00 FL
51	1		*REAR BUMPER FACE	Distorted	448.00 FL	*448.00 FL
52	1		*REAR BUMPER CENTRE GARNISH	Distorted	272.00 FL	*272.00 FL
53	2		*REAR BUMPER SIDE COVER GARNISH	Deformed	320.00 FL	*320.00 FL
54	2		*REAR BUMPER SIDE RETAINER	Necessary	160.00 FL	*160.00 FL
55	1		*REAR BUMPER REFLECTOR LAMP	O/s Cracked	242.00 FL	*121.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	12		*REAR BUMPER CLIPS	Necessary	60.00 FL	*30.00 FL
57	2		*REAR TAILLAMP PANEL	Dented	424.00 FL	*424.00 FL
58	2		*REAR TAILLAMP ASSY	Cracked	864.00 FL	*864.00 FL
59	2		*REAR FENDER PANEL ASSY	Buckled	2,024.00 FL	*2,024.00 FL
60	2		*REAR FENDER INNER PANEL (WHEEL HOUSE)	Repair	1,290.00 FL	*- FL
61	2		*REAR FENDER INNER TRIM BOARD	Deformed	1,856.00 FL	*1,398.00 FL
62	2		*REAR FENDER AIR DUCT	Not Necessary	116.00 FL	*- FL
63	2		*REAR FENDER MUD FLAP	Torn	208.00 FL	*208.00 FL
64	2		*REAR SIDE DOOR SLIDE RUNNING CHANNEL	Not Necessary	1,028.00 FL	*- FL
65	2		*REAR SIDE DOOR SLIDE RUNNING CHANNEL COVER	Cracked	890.00 FL	*890.00 FL
66	1		*REAR FLOOR PANEL	Distorted	896.00 FL	*896.00 FL
67	1		*REAR FLOOR PANEL CENTRE JOINT PANEL	Not Necessary	258.00 FL	*- FL
68	1		*REAR TAIL END PANEL (TOP)	Distorted	496.00 FL	*496.00 FL
69	1		*REAR TAIL END PANEL (LOWER)	Distorted	516.00 FL	*516.00 FL
70	1		*REAR EXHAUST BOX	Bent	980.00 FL	*822.00 FL
71	2		*REAR EXHAUST BOX MOUNTING	Not Necessary	146.00 FL	*- FL
72	1		*REAR EXHAUST HEAT SHIELD COVER	Crumpled	116.00 FL	*116.00 FL
73	1		*REAR PANEL LINING	Deformed	269.00 FL	*269.00 FL
74	1		*REAR TOOL BOX GARNISH	Deformed	608.00 FL	*419.00 FL
75	1		*REAR TOOL BOX TOP COVER	Not Necessary	287.00 FL	*- FL
76	1		*REAR FUEL TANK CHARCOAL CANISTER	Not Necessary	311.00 FL	*- FL
77	1		*REAR INNER CENTRE TOP BAR	Not Necessary	412.00 FL	*- FL
78	1		*FRONT NUMBER PLATE	Bent	50.00 FS	*50.00 FS
79	1		*REAR NUMBER PLATE	Bent	50.00 FS	*50.00 FS
80	1		*REAR REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
81	1		*REAR REVERSE CAMERA UNIT	Not Necessary	250.00 FS	*- FS
82	2		*REAR TYRE ASSY	Cut	400.00 FS	*300.00 FS
83	1		*TIN RADIATOR COOLER WATER	Necessary	28.00 FS	*28.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	42,114.40	29,101.80
- List Item Discount on L Items 25.00/25.00% (\$\$)	10,264.10	7,118.45
Total Parts (\$\$)	31,850.30	21,983.35

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TOW VEHICLE TO WORKSHOP (KING TOWING)	New	150.00	120.00
2	TO SEND VEHICLE FOR COMPUTER ALIGHMENT	New	120.00	0.00
3	TO SPRAY UNDERCOATING IN REPAIR	New	400.00	280.00
4	TO DISM/REWIRE FRONT/REAR DAMAGED	New	220.00	60.00
5	TO DISM REAR UNDERCARRIER FOR CHASSIS FRAME REPAIR	New	480.00	350.00
6	TO DISM REAR FUEL TANK FOR REPAIR WORK	New	150.00	80.00
7	TO DISM/RENEW REAR EXHAUST PIPE	New	100.00	80.00
8	TO DISM/REFIX REAR SEAT,ROOF LINING IN REPAIR	New	280.00	250.00
9	TO DISM/REFIX REAR WINDSCREEN GLASS & REAR FENDER GLASS	New	380.00	200.00
10	TO DISM/RENEW REAR REVERSE SENSOR & CAMERA	New	200.00	100.00
11	TO DISM/RENEW AIR CON UNIT AND REFILL GAS	New	220.00	120.00
12	TO PANEL BEAT DAMAGED CHASSIS FRAME PORTION & RENEW PARTS	New	3,000.00	2,800.00
13	TO PUTTY AND RESPRAY DAMAGED PORTION	New	2,000.00	1,900.00
			Gross Labour Cost (\$\$)	7,700.00
				6,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >