



友尼摩哆公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三

AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

Registration No.: 203165/00D

TP Alg. N SP 1707075638
Xiao Chen.

LKK

DATE: 10/05/2021 OUR REF: UAPL1453
REPAIR ESTIMATE TO THE TOYOTA SIENTA NO: SLN8137X

1 FRONT BONNET ASSY	Distorted	\$ 883.20	/
2 FRONT BONNET HINGES	Bent	\$ 224.00	/
1 FRONT BONNET LOCK	and.	\$ 212.20	/
1 FRONT TOYOTA EMBLEM	new	\$ 122.40	/
1 FRONT RADIATOR GRILLE ASSY	cracked	\$ 848.00	X 596
1 FRONT RADIATOR ASSY	dented	\$ 2,230.00	X 1288
2 FRONT RADIATOR TOP BRACKET	new	\$ 100.00	X
1 FRONT RADIATOR TOP GARNISH	new	\$ 198.00	X
1 FRONT RADIATOR FAN MOTOR	new nec	\$ 387.80	X
1 FRONT RADIATOR FAN COWLING	new nec	\$ 212.60	X
1 FRONT L/H RADIATOR SIDE COVER GARNISH	behind	\$ 155.60	/
1 FRONT R/H RADIATOR SIDE COVER GARNISH	behind	\$ 211.30	/
1 FRONT AIR CON CONDENSOR	bent	\$ 1,552.20	X 1129
1 FRONT AIR CON SUCTION PIPE	new nec	\$ 236.00	X
1 FRONT AIR CON DISCHARGE PIPE	new nec	\$ 168.00	X
1 FRONT AIR CON RECEIVER PIPE	new	\$ 314.00	X
2 FRONT FENDER ASSY	LH Buckled	\$ 928.00	X 464
1 FRONT LOWER SHIELD	new	\$ 156.00	X
2 FRONT HEADLAMP ASSY (LED)	cracked	\$ 5,978.00	X 5680
2 FRONT HEADLAMP LOWER BRACKETS	new	\$ 180.00	X
1 FRONT SUPPORT PANEL	Buckled	\$ 980.00	X 745
1 FRONT BRACE PANEL	bent	\$ 187.60	/
1 FRONT BUMPER FACE	behind	\$ 598.00	/
2 FRONT BUMPER SIDE PROTECTOR GARNISH	new	\$ 540.00	X
1 FRONT BUMPER REINFORCEMENT	dented	\$ 520.00	X 347
1 FRONT BUMPER INNER WHITE SPONGE	cracked	\$ 155.80	/
2 FRONT BUMPER FOG LAMP	new	\$ 588.00	X
1 FRONT BUMPER FOG LAMP COVER	new	\$ 320.00	X
2 FRONT BUMPER SIDE RETAINER	and	\$ 179.20	/
2 FRONT BUMPER CENTRE TOP BRACKET	Bent	\$ 192.00	/
12 FRONT BUMPER CLIPS	new	\$ 60.00	X 30
1 REAR BOOT ASSY	Distorted	\$ 1,350.00	X 1280
1 REAR BOOT LOCK	Jammed	\$ 285.00	/
1 REAR BOOT STRIKER	Bent	\$ 34.00	/
2 REAR BOOT HINGES	new	\$ 98.00	X
1 REAR BOOT FULL HANDLE	deformed	\$ 28.00	/
1 REAR BOOT WEATHERSTRIP	lit	\$ 296.00	/
1 REAR BOOT INNER COVER LINING	new	\$ 233.00	X
2 REAR BOOT STAY OPEN ABSORBER	Dand	\$ 520.00	/
1 REAR BOOT OUTER GARNISH	behind	\$ 288.00	/
1 REAR BOOT KEY ANTENNA SENSOR	cracked	\$ 185.00	/
1 REAR BOOT TOYOTA LOGO	new	\$ 65.00	/
1 REAR BOOT WIPER MOTOR	Dand	\$ 413.50	/
1 REAR BOOT WIPER ARM	new	\$ 98.00	X
1 REAR BOOT WIPER BLANDE	new	\$ 32.00	X



友尼摩哆公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三

AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

Registration No.: 203165/00D

1 REAR BOOT WIPER ARM COVER <i>xt New</i>	\$ 18.00 <i>x</i>	
2 REAR BOOT NUMBER PLATE LAMP <i>Cracked</i>	\$ 122.00 <i>✓</i>	
2 REAR BOOT LAMP ASSY <i>cracked</i>	\$ 640.00 <i>✓</i>	
1 REAR BOOT WINDSCREEN ASSY <i>xt New</i>	\$ 1,012.00 <i>x</i>	
1 REAR BOOT GLASS MOULDING <i>xt New</i>	\$ 224.00 <i>✓</i>	
1 REAR BUMPER FACE <i>Distorted</i>	\$ 448.00 <i>✓</i>	
1 REAR BUMPER CENTRE GARNISH <i>Distorted</i>	\$ 272.00 <i>✓</i>	
2 REAR BUMPER SIDE COVER GARNISH <i>Distorted</i>	\$ 320.00 <i>✓</i>	
2 REAR BUMPER SIDE RETAINER <i>New</i>	\$ 160.00 <i>✓</i>	
2 REAR BUMPER REFLECTOR LAMP <i>RH cracked</i>	\$ 242.00 <i>121</i>	
12 REAR BUMPER CLIPS <i>xt New</i>	\$ 60.00 <i>30</i>	
2 REAR TAILLAMP PANEL <i>Dented</i>	\$ 424.00 <i>✓</i>	
2 REAR TAILLAMP ASSY <i>cracked</i>	\$ 864.00 <i>✓</i>	
2 REAR FENDER PANEL ASSY <i>Buckled</i>	\$ 2,024.00 <i>✓</i>	
2 REAR FENDER INNER PANEL (WHEEL HOUSE) <i>Reps</i>	\$ 1,290.00 <i>x</i>	
2 REAR FENDER INNER TRIM BOARD <i>Distorted</i>	\$ 1,856.00 <i>1398</i>	
2 REAR FENDER AIR DUCT <i>xt New</i>	\$ 116.00 <i>x</i>	
2 REAR FENDER MUD FLAP <i>xt New</i>	\$ 208.00 <i>✓</i>	
2 REAR SIDE DOOR SLIDE RUNNING CHANNEL <i>xt New</i>	\$ 1,028.00 <i>x</i>	
2 REAR SIDE DOOR SLIDE RUNNING CHANNEL COVER <i>cracked</i>	\$ 890.00 <i>✓</i>	
1 REAR FLOOR PANEL <i>Distorted</i>	\$ 896.00 <i>✓</i>	
1 REAR FLOOR PANEL CENTRE JOINT PANEL <i>xt New</i>	\$ 258.00 <i>x</i>	
1 REAR TAIL END PANEL (TOP) <i>Distorted</i>	\$ 496.00 <i>✓</i>	
1 REAR TAIL END PANEL (LOWER) <i>Distorted</i>	\$ 516.00 <i>✓</i>	
1 REAR EXHAUST BOX <i>Bent</i>	\$ 980.00 <i>822</i>	
2 REAR EXHAUST BOX MOUNTING <i>xt New</i>	\$ 146.00 <i>x</i>	
1 REAR EXHAUST HEAT SHIELD COVER <i>crumpled</i>	\$ 116.00 <i>✓</i>	
1 REAR PANEL LINING <i>Distorted</i>	\$ 269.00 <i>✓</i>	
1 REAR TOOL BOX GARNISH <i>Distorted</i>	\$ 608.00 <i>419</i>	
1 REAR TOOL BOX TOP COVER <i>xt New</i>	\$ 287.00 <i>x</i>	
1 REAR FUEL TANK CHARCOAL CANISTER <i>xt New</i>	\$ 311.00 <i>x</i>	
1 REAR INNER CENTRE TOP BAR <i>xt New</i>	\$ 412.00 <i>x</i>	
	<hr/>	
	\$ 41,056.40	
	\$ 10,264.10	
	<hr/>	
	\$ 30,792.30	
		<i>28473.80</i>
		<i>21355.35</i>

LESS 25%.....

SPECIAL NETT:-

1 FRONT NUMBER PLATE <i>Bent</i>	\$ 50.00 <i>✓</i>	
1 REAR NUMBER PLATE <i>Bent</i>	\$ 50.00 <i>✓</i>	
1 REAR REVERSE SENSOR <i>Distorted</i>	\$ 280.00 <i>200</i>	
1 REAR REVERSE CAMERA UNIT <i>xt New</i>	\$ 250.00 <i>x</i>	
2 REAR TYRE ASSY <i>xt</i>	\$ 400.00 <i>300</i>	
1 TIN RADIATOR COOLER WATER <i>xt New</i>	\$ 28.00 <i>✓</i>	

628



友尼摩哆公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三

AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

Registration No.: 203165/00D

LABOUR CHARGES:-

TO TOW VEHICLE TO WORKSHOP (KING TOWING)	\$ 150.00	120.
TO SEND VEHICLE FOR COMPUTER ALIGNMENT	\$ 120.00	X
TO SPRAY UNDERCOATING IN REPAIR	\$ 400.00	280
TO DISM/REWIRE FRONT/REAR DAMAGED	\$ 220.00	60
TO DISM REAR UNDERCARRIER FOR CHASSIS FRAME REPAIR	\$ 480.00	350
TO DISM REAR FUEL TANK FOR REPAIR WORK	\$ 150.00	80
TO DISM/RENEW REAR EXHAUST PIPE	\$ 100.00	80
TO DISM/REFIX REAR SEAT, ROOF LINING IN REPAIR	\$ 280.00	250
TO DISM/REFIX REAR WINDSCREEN GLASS & REAR FENDER GLASS	\$ 380.00	200
TO DISM/RENEW REAR REVERSE SENSOR & CAMERA	\$ 200.00	100
TO DISM/RENEW AIR CON UNIT AND REFILL GAS	\$ 220.00	120
TO PANEL BEAT DAMAGED CHASSIS FRAME PORTION & RENEW PARTS	\$ 3,000.00	2800
TO PUTTY AND RESPRAY DAMAGED PORTION	\$ 2,000.00	1900.
	<u>\$ 39,550.30</u>	

6340

total: 28323.35
H/S: 22650. ✓
24 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: