

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC6/III21004729/ABA3Q2

Date:

07/07/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

D20MFL0000326_01

Claimant Vehicle No : SLE468R**Insured Vehicle No :**

SLZ1793J

Date of Loss: 13/04/2021

Nature of Claim:

TP

Claim No:

MFL2021D0001570

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SLE468R

Make & Model:

TOYOTA VIOS, 1.5 E (A)

Reg. Date:

27/12/2007 (Man. Year: 2007)

Colour:

White

Engine Capacity:

1497 cc

Market Value/New Car Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

Engine No:

1NZX666833

Chassis No:

MR053HY9305041456

Odometer:

0 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

205/55 R16

Rear Tyre Size:

205/55 R16

Front Left Side:

Yokohama 6 mm

Rear Left Side:

Yokohama 6 mm

Front Right Side:

Yokohama 6 mm

Rear Right Side:

Yokohama 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	12,872.45	4,093.06	8,779.39	68.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,510.00	3,220.00	1,290.00	28.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,382.45	7,313.06	10,069.39	57.93
Approved Total (Overridden) (S\$)		5,800.00		

(S\$)	17,382.45	5,800.00	11,582.45	66.63
+ GST 7.00/7.00% (S\$)	1,216.77	406.00	810.77	66.63
Nett Amount (S\$)	18,599.22	6,206.00	12,393.22	66.63
+ Loss of Use (9.0 x S\$80.00/day) (S\$)		720.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,933.45		
Global Sum Settlement (S\$)		6,900.00		

INSPECTION

Date of Assignment: 14/04/2021

Date Inspected: 14/04/2021

Inspected At:

Cn Motors Pte Ltd (HQ)

1 KAKI BUKIT AVENUE 6 BLK C #01-41 AUTOBAY @ KAKI BUKIT
Singapore 417883

Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Jun 2021)
Parts:	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLE468R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Buckled	590.10 F	*590.10 FL
2	2		*REAR BOOT LID HINGE	Not Necessary	246.10 F	*- FL
3	1		*REAR BOOT LID EMBLEM LOGO	Necessary	42.50 F	*42.50 FL
4	1		*REAR BOOT LID CENTRE MOULDING	Not Necessary	172.85 F	*- FL
5	1		*REAR BOOT LID NUMBER PLATE	Not Necessary	50.00 F	*- FL
6	2		*REAR BOOT LID NUMBER PLATE LAMP	Not Necessary	167.00 F	*- FL
7	1		*REAR BOOT LID INNER LOCK	Damaged	182.25 F	*182.25 FL
8	1		*REAR BOOT LID INNER RUBBER	Cut	161.40 F	*161.40 FL
9	1		*REAR BOOT LID TOP SPOILER	Not Necessary	550.00 F	*- FL
10	2		*REAR TAIL LAMP	Cracked	562.90 F	*562.90 FL
11	4		*REAR TAIL LAMP CLIP	Necessary	32.00 F	*32.00 FL
12	2		*REAR TAIL LAMP PANEL	Dented	379.80 F	*379.80 FL
13	2		*REAR TAIL LAMP LOWER BRACKET	Not Necessary	242.50 F	*- FL
14	1		*REAR BUMPER	Distorted	496.10 F	*496.10 FL
15	8		*REAR BUMPER CLIP	Necessary	52.00 F	*30.00 FL
16	2		*REAR BUMPER SIDE RETAINER	Necessary	242.50 F	*78.00 FL
17	1		*REAR BUMPER REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
18	2		*REAR BUMPER SIDE REFLECTOR	Cracked	364.50 F	*364.50 FL
19	2		*REAR BUMPER MUD SHIELD	Not Necessary	468.00 F	*- FL
20	12		*REAR BUMPER MUD SHIELD CLIP	Not Necessary	96.00 F	*- FL
21	2		*REAR FENDER	Repair	1,963.50 F	*- FL
22	2		*REAR FENDER INNER TRIM BOARD	Not Necessary	628.80 F	*- FL
23	16		*REAR FENDER INNER TRIM BOARD CLIP	Not Necessary	104.00 F	*- FL
24	1		*REAR END PANEL	Distorted	781.50 F	*781.50 FL
25	1		*REAR END PANEL TOP GARNISH	Deformed	286.50 F	*286.50 FL
26	1		*REAR SPARE TYRE PANEL	Repair	681.75 F	*- FL
27	1		*REAR SPARE TYRE PANEL TOP COVER	Torn	289.95 F	*185.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	2		*REAR SPARE TYRE PANEL TOP SPONGE	Deformed	480.20 F	*480.20 FL
29	1		*REAR SPARE TYRE PANEL & END PANEL SEALANT	Not Necessary	450.00 F	*- FL
30	1		*REAR EXHAUST	Bent	781.45 F	*538.00 FL
31	2		*REAR EXHAUST MOUNTING	Not Necessary	57.00 F	*- FL
32	1		*REAR CENTER EXHAUST	Not Necessary	787.20 F	*- FL
33	1		*REAR WINDSCREEN MOULDING	Not Necessary	132.10 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	12,872.45	5,390.75
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	1,297.69
Total Parts (S\$)	12,872.45	4,093.06

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	50.00
2	TO REMOVE & REFIT REAR & CENTER EXHAUST	New	380.00	80.00
3	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	0.00
4	GUM	New	50.00	0.00
5	TO CHECK WIRING	New	60.00	30.00
6	TOWING FEE	New	100.00	0.00
7	TUFF KOTE	New	100.00	80.00
8	PANEL BEATING	New	1,800.00	1,400.00
9	SPRAY PAINTING	New	1,600.00	1,500.00
10	TO REMOVE AND REFIT UPHOLSTERY	New	200.00	80.00
Gross Labour Cost (S\$)			4,510.00	3,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >