

CN MOTORS PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-41 Autobay@Kaki Bukit, Singapore 417883
Email: admin@cnmotorspl.com
Tel: 6509 5545 Fax: 6509 5567
UEN: 202026492W GST Reg No: 202026492W

Admin LKLC
TII

Blk 1 Kaki Bukit Ave 6
01-43
Singapore 417883

13/04/2021

Accident date: 13/04/2021

Estimated repair cost for vehicle no: SLE468R TOYOTA VIOS E AUTO 07'

CHASSIS: MR053HY9305041456

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid Buckled.		\$590.10 ✓
2	2	Rear Boot Lid Hinge New	\$123.05	\$246.10 ✓
3	1	Rear Boot Lid Emblem Logo New		\$42.50 ✓
4	1	Rear Boot Lid Centre Moulding New		\$172.85 ✓
5	1	Rear Boot Lid Number Plate Gap		\$50.00 ✓
6	2	Rear Boot Lid Number Plate Lamp New	\$83.50	\$167.00 ✓
7	1	Rear Boot Lid Inner Lock Dented		\$182.25 ✓
8	1	Rear Boot Lid Inner Rubber Lt		\$161.40 ✓
9	1	Rear Boot Lid Top Spoiler New		\$550.00 ✓
10	2	Rear Tail Lamp Cracked	\$281.45	\$562.90 ✓
11	4	Rear Tail Lamp Clip New	\$8.00	\$32.00 ✓
12	2	Rear Tail Lamp Panel Dented.	\$189.90	\$379.80 ✓
13	2	Rear Tail Lamp Lower Bracket New	\$121.25	\$242.50 ✓
14	1	Rear Bumper Distorted		\$496.10 ✓
15	8	Rear Bumper Clip New	\$6.50	\$52.00 30
16	2	Rear Bumper Side Retainer New	\$121.25	\$242.50 78
17	1	Rear Bumper Reverse Sensor (Special Nett) Dented		\$350.00 2w/sv ✓
18	2	Rear Bumper Side Reflector Cracked.	\$182.25	\$364.50 ✓
19	2	Rear Bumper Mud Shield Gap	\$234.00	\$468.00 ✓
20	12	Rear Bumper Mud Shield Clip New	\$8.00	\$96.00 ✓
21	2	Rear Fender Repair	\$981.75	\$1,963.50 ✓
22	2	Rear Fender Inner Trim Board Gap	\$314.40	\$628.80 ✓
23	16	Rear Fender Inner Trim Board Clip New	\$6.50	\$104.00 ✓
24	1	Rear End Panel Distorted		\$781.50 ✓
25	1	Rear End Panel Top Garnish Deformed		\$286.50 ✓
26	1	Rear Spare Tyre Panel Repair		\$681.75 ✓
27	1	Rear Spare Tyre Panel Top Cover Torn		\$289.95 ✓

185

28	2	Rear Spare Tyre Panel Top Sponge <i>del</i>	\$240.10	\$480.20 ✓
29	1	Rear Spare Tyre Panel & End Panel Sealant <i>not nec</i>		\$450.00 X
30	1	Rear Exhaust <i>best</i>		\$781.45 538
31	2	Rear Exhaust Mounting <i>new</i>	\$28.50	\$57.00 X
32	1	Rear Center Exhaust <i>not nec</i>		\$787.20 X
33	1	Rear Windscreen Moulding <i>not nec</i>		\$132.10 X

5190.75

Subtotal :- \$12,577.85

3893.06 S.N. 2W.
5126.18

Labour charges

To remove & refit reverse sensor	\$100.00 50
To remove & refit rear & center exhaust	\$380.00 80
To remove & refit rear windscreen	\$120.00 X
Gum	\$50.00 X
To check wiring	\$60.00 30
Towing fee	\$100.00 X
Tuff kote	\$100.00 80
Panel beating	\$1,800.00 1400.
Spray painting	\$1,600.00 1500.

To remove and refit upholstery 200
80

Subtotal :- \$4,310.00

Total:- \$16,887.85

Weld: 7313.06

H/S: 5.8K

08 Days

5.8K

08 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: