

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21004732/EGA3Q2**Date:** 14/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993649
Claimant Vehicle No :	SHA1972M	Insured Vehicle No :	PC8631X
Date of Loss:	10/04/2021	Nature of Claim:	TP
		Claim No:	4026616314SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA1972M		
Make & Model:	HYUNDAI AE IONIQ HEV DCT, 1.6 (A)	Engine No:	G4LEJU167562
Reg. Date:	01/02/2019 (Man. Year: 2018)	Chassis No:	KMHC851CVKU133783
Colour:	Blue	Odometer:	117060 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,257.32	2,257.32	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,480.00	910.00	570.00	38.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,737.32	3,167.32	570.00	15.25
+ GST 7.00/7.00% (S\$)	261.61	221.71	39.90	15.25
Nett Amount (S\$)	3,998.93	3,389.03	609.90	15.25
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$125.19/day) (S\$)		375.57		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		3,922.09		
Global Sum Settlement (S\$)		3,900.00		

INSPECTION

Date of Assignment:	14/04/2021	
Date Inspected:	14/04/2021	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Broken	430.90 FL	*430.90 FL
2	1		*FRT BUMPER CTR UPR MOULDING	Cut	368.50 FL	*368.50 FL
3	1		*HEADLAMP RH	Cut	1,995.65 FL	*1,995.65 FL
4	1		*FRT FENDER BLUE-DRIVE RH	Necessary	26.60 FL	*26.60 FL
					Sub Total (\$\$)	2,821.65
					- List Item Discount on L Items 20.00/20.00% (\$\$)	564.33
					Total Parts (\$\$)	2,257.32

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING -FRT FENDER RH	New	800.00	350.00
2	SPRAYPAINT CHARGE	New	600.00	500.00
3	CHECK ALL LIGHTING	New	40.00	30.00
4	TUFF COAT ON AFFECTED PARTS	New	40.00	30.00
Gross Labour Cost (\$\$)			1,480.00	910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >