

[Service Requests](#)[Messages](#)[Claims](#)

# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

## General Details

Involving

TPVD UNKNOWN UNKNOWN (SJJ1313Y)

Date of Loss

13 April 2021

Time of Loss

Loss Description

YQ2897E (INSD) C/W SJJ1313Y (TP)

Comment

## Workshop Details

Total Rebate  
Amount

0

Nett Loss Amount

\$0.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (TP)

Days of work  
completion \*

20



Service Requests

Messages

Claims



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

## Vehicle & Driver Details

Vehicle Registration# SJJ1313Y

Registration State SINGAPORE

Mileage 98197

Purchase Date DD/MM/YYYY

Registration Date \* 18/07/2017

Age of Vehicle 3

CATEGORY

POLICY  
INFORMATION

ASSESSMENT INFORMATION

Manufacturing  
Year

2017

## Driver Details

CATEGORY



FNOL INFORMATION

POST SURVEY  
INFORMATION


Driver Name

YAP BOON  
KHENG

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Make	TPVD UNKNOWN	<input type="text" value="HONDA"/>
Model	UNKNOWN	<input type="text" value="FREED HYBRID 1.5G AI"/>
Type		<input type="text" value=""/>
Type of Paint		<input type="text" value=""/>
Chassis No		<input type="text" value="GB71029929"/>
Engine No		<input type="text" value="LED5555867"/>
Engine Capacity		<input type="text" value="1496"/>
Sum Insured		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Date of Birth	1 January 1999	<input type="text" value="DD/MM/YYYY"/> 
Age	22	
Occupation	Unknown	<input type="text" value=""/>
Education Qualification	Other	<input type="text" value=""/>
Driving Experience	0	
Driver License #		<input type="text" value=""/>
License Type		<input type="text" value=""/>
License Issue Date		<input type="text" value="DD/MM/YYYY"/> 

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Market Value		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Expiration Date		<input type="text" value="DD/MM/YYYY"/> 
Address	SG, Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text" value="v"/>
Gender	Unknown	<input type="text" value="v"/>
Marital status	Unknown	<input type="text" value="v"/>
Identification #	TBC	<input type="text"/>



Service Requests

Messages

Claims



## Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

### Detailed Assessment

Inspection Date \*

14/04/2021



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/  
Unnamed Driver Excess

0

### Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake  
(Serviceable)

Yes

No

Handbrake  
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Other Excess

0

Tyre Condition

Age of Tyres

Front Tyre Size

205/55R16

Front left side

PIRELLI8mm

Front right side

PIRELLI8mm

Spare wheel

Rear Tyre Size

205/55R16

Rear left side

PIRELLI8mm

Rear right side

PIRELLI8mm



Service Requests

Messages

Claims



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

## Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

0

Salvage%

0

Discount%

20

Settlement%

100

## Paint Labour/Material Ratio

Paint Labour Ratio

20

Cash Loss

Yes

No

Paint Material Ratio

80

Part Supplied by AXA

Yes

No

Save



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour











Miscellaneous









Summary










Parts











Add		Approve		Deny		Submit All							
EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		REAR TAILGATE	Bent	0	1265.4	No	0	20	0	0	1012.32
	0	1		REAR TAILGATE LOGO	Necessary	0	58	No	0	20	0	0	46.4
	0	1		REAR TAILGATE EMBLEM 'FREED'	Necessary	0	68	No	0	20	0	0	54.4
	0	1		REAR TAILGATE EMBLEM 'HYBRID'	Necessary	0	68	No	0	20	0	0	54.4
	0	1		REAR TAILGATE LOCK	Damaged	0	186.2	No	0	20	0	0	148.96
	0	1		REAR TAILGATE RUBBER	Cut	0	168.5	No	0	20	0	0	134.8








EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		REAR TAILGATE INNER HANDLE	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR TAILGATE OUTER HANDLE CHROME	Cracked	0	204.8	No	0	20	0	0	163.84
	0	1		REAR TAILGATE INNER BOARD	Serviceable	0	0	No	0	0	0	0	0
	0	1		TAILLAMP LH	Cut	0	580.4	No	0	20	0	0	464.32
	0	1		TAILLAMP RH	Cracked	0	580.4	No	0	20	0	0	464.32
	0	1		TAILLAMP PANEL LH	Repair	0	0	No	0	0	0	0	0
	0	1		TAILLAMP PANEL RH	Repair	0	0	No	0	0	0	0	0
	0	1		REAR END PANEL INNER GARNISH	Dented	0	98.2	No	0	20	0	0	78.56
	0	1		REAR END PANEL	Bent	0	480	No	0	20	0	0	384
	0	1		REAR BUMPER	Bent	0	759	No	0	20	0	0	607.2

EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		REAR BUMPER TOWING COVER	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR BUMPER SIDE RETAINER LH	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR BUMPER SIDE RETAINER RH	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR BUMPER BRACKET LH	Damaged	0	48	No	0	20	0	0	38.4
	0	1		REAR BUMPER BRACKET RH	Damaged	0	48	No	0	20	0	0	38.4
	0	1		REAR BUMPER REFLECTOR RH	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR BUMPER REFLECTOR LH	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR NUMBER PLATE LAMP	Serviceable	0	0	No	0	0	0	0	0

EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		REAR EXHAUST SILENCER	Repair	0	0	No	0	0	0	0	0
	0	1		REAR EXHAUST SILENCER MOUNTINGS	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR EXHAUST PIPE CENTRE	Repair	0	0	No	0	0	0	0	0
	0	1		REAR EXHAUST COVER	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR TAILGATE LAMP RH	Cracked	0	391.6	No	0	20	0	0	313.28
	0	1		REAR TAILGATE LAMP LH	Cracked	0	391.6	No	0	20	0	0	313.28
	0	1		REAR KEYLESS SENSOR	Serviceable	0	0	No	0	0	0	0	0
	0	1		SPARE TYRE LOWER COVER	Serviceable	0	0	No	0	0	0	0	0
	0	1		TAIL GATE WINDSCREEN GLASS	Damaged	0	1064.7	No	0	20	0	0	851.76

EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		TAILGATE WINDSCREEN GLASS MOULDING	Necessary	0	91.1	No	0	20	0	0	72.88
	0	1		TAILGATE DAMPER RH	Serviceable	0	0	No	0	0	0	0	0
	0	1		TAILGATE DAMPER LH	Serviceable	0	0	No	0	0	0	0	0
	0	1		TAILGATE WIPER	Cut	0	68	No	0	20	0	0	54.4
	0	1		WIPER ARM	Serviceable	0	0	No	0	0	0	0	0
	0	1		WIPER MOTOR	Damaged	0	378.9	No	0	20	0	0	303.12
	0	1		THRID BRAKE LIGHT	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR FENDER INNER TRIM BOARD LH	Cracked	0	468	No	0	20	0	0	374.4
	0	1		REAR FENDER INNER TRIM BOARD RH	Cracked	0	468	No	0	20	0	0	374.4
	0	1		REAR FENDER INNER TOP COVER LH	Serviceable	0	0	No	0	0	0	0	0

EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		REAR FENDER INNER TOP COVER RH	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR FLOOR PANEL CARPET	Deformed	0	422.5	No	0	20	0	0	338
	0	1		REAR FLOOR PANEL	Repair	0	0	No	0	0	0	0	0
	0	1		REAR END PANEL INNER	Serviceable	0	0	No	0	0	0	0	0
	0	1		SPARE TYRE PANEL INSULATOR PAD	Deformed	0	306	No	0	20	0	0	244.8







#### Labour











Add

Approve

Deny

Submit All

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		STRAIGHTEN & PANEL BEAT ACCIDENT AREAS	0	900	0	0	Reviewing		
	0		SPRAY PAINT ON ACCIDENT AREAS	0	1000	0	0	Reviewing		
	0		CHECK & REPAIR WIRING SYSTEM	0	20	0	0	Reviewing		

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		R&R TRIMS, INNER GARNISH TO ASSIST REPAIR	0	80	0	0	Reviewing		
	0		R&R REVERSE CAMERA	0	50	0	0	Reviewing		
	0		R&R REAR WINDSCREEN GLASS	0	120	0	0	Reviewing		
	0		R&R REAR TAILGATE COMPONENTS	0	60	0	0	Reviewing		
	0		RESPRAY KOTE TUFF ON AFFECTED AREA	0	60	0	0	Reviewing		



Service Requests

Messages

Claims



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour





Miscellaneous

## Summary

Add		Approve		Deny		Submit All	
EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	DAYS OF REPAIR : 8 DAYS	Reviewing	0	0		
	0	REAR WINDSCREEN SEALANT	Reviewing	0	40	NECESSARY	
	0	REAR WINDSCREEN SEAL	Reviewing	0	30	NECESSARY	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	REAR WINDSCREEN PRIMER AND CLEANER	Reviewing	0	30	NECESSARY	
	0	REAR WINDSCREEN SOLAR FILM	Deny	0	0	NOT NECESSARY	
	0	REVERSE CAMERA	Deny	0	0	SERVICEABLE	
	0	REVERSE SENSOR	Reviewing	0	200	SHORTED	
	0	REAR CAR CAMERA	Deny	0	0	SERVICEABLE	
	0	REAR BUMPER CLIPS	Reviewing	0	50	NECESSARY	



EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	REAR END PANEL SEALANT	Reviewing	0	30	NECESSARY	
	0	REAR NO PLATE	Reviewing	0	45	DENTED	

[Service Requests](#)[Messages](#)[Claims](#)

# Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)

Summary

Estimated Claim Amount	\$0.00	Adjusted Claim Amount	\$9,645.64
------------------------	--------	-----------------------	------------

CATEGORY	ESTIMATE	ADJUSTED
Spare Parts	\$0.00	\$6,930.64
Labour	\$0.00	\$2,290.00
Miscellaneous	\$0.00	\$425.00

Submit for Review



Service Requests

Messages

Claims



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

## Summary

Add

Approve

Deny

Submit All

EDIT

SR  
NO

NAME

ACTION

ESTIMATED  
AMOUNT

ADJUSTED  
AMOUNT

COMMENT

REMOVE



0

FINAL  
LUMP  
SUM

Reviewing

0

7650





Service Requests

Messages

Claims



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount	\$0.00	Adjusted Claim Amount	\$7,650.00
------------------------	--------	-----------------------	------------

CATEGORY	ESTIMATE	ADJUSTED
Miscellaneous	\$0.00	\$7,650.00

Submit for Review