

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21004741/EQF3E2

Date: 01/06/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00066142009
Claimant Vehicle No: SJA7375Z Insured Vehicle No: GBC2203D
Date of Loss: 13/04/2021 Nature of Claim: TP Claim No: SNM21D202130/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJA7375Z**
Make & Model: KIA SORENTO, 2.2 (A) Engine No: D4HBJH205584
Reg. Date: 23/09/2019 (Man. Year: 2018) Chassis No: KNAPH81BMK5523944
Colour: Grey Odometer: 41502 km
Engine Capacity: 2199 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55Z R19 Rear Tyre Size: 235/55ZR19
Front Left Side: Falken 5 mm Rear Left Side: Falken 5 mm
Front Right Side: Falken 5 mm Rear Right Side: Falken 5 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------|------------------|------------------|-----------------|--------------|
| Parts | 7,300.00 | 4,736.00 | 2,564.00 | 35.12 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 9,540.00 | 5,640.00 | 3,900.00 | 40.88 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 16,840.00 | 10,376.00 | 6,464.00 | 38.38 |
| + GST 7.00/7.00% (S\$) | 1,178.80 | 726.32 | 452.48 | 38.38 |
| Nett Amount (S\$) | 18,018.80 | 11,102.32 | 6,916.48 | 38.38 |

INSPECTION

Date of Assignment: 14/04/2021
Date Inspected: 15/04/2021 Inspected At: Cycle & Carriage Fulco Motor Dealer Pte Ltd (HQ)
330 Ubi Road 3
Singapore 408650
Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|--|---|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 01 Jun 2021) |
| Parts: | M1-SUV | KIA SORENTO 2.2 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SJA7375Z) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-----------------------|---------------|-------------|--------------|
| 1 | 1 | | *EMBLEM-KIA | Necessary | 69.00 FS | *69.00 FS |
| 2 | 1 | | *EMBLEM-SORENTO | Necessary | 28.00 FS | *28.00 FS |
| 3 | 1 | | *EMBLEM - ECO DYNAMIC | Necessary | 37.00 FS | *37.00 FS |
| 4 | 1 | | *GLASS ASSY - TAILGAT | Necessary | 690.00 FS | *690.00 FS |
| 5 | 4 | | *PAD-WINDSHIELD | Necessary | 68.00 FS | *68.00 FS |
| 6 | 6 | | *PAD-W/SHLD GLASS | Necessary | 12.00 FS | *12.00 FS |
| 7 | 2 | | *STOPPER-RR WINDOW GL | Necessary | 8.00 FS | *8.00 FS |
| 8 | 1 | | *PANEL ASSY-TAIL GATE | Dented | 1,445.00 FS | *1,445.00 FS |
| 9 | 1 | | *LH INR LAMP ASSY-REA | Not Necessary | 827.00 FS | *- FS |
| 10 | 1 | | *LH OTR LAMP ASSY-REA | Broken | 493.00 FS | *493.00 FS |
| 11 | 1 | | *UPR COVER-RR BUMPER | Dented | 605.00 FS | *605.00 FS |
| 12 | 1 | | *LWR COVER-REAR BUM | Cut | 565.00 FS | *565.00 FS |
| 13 | 1 | | *SKID PLATE-REAR BU | Cut | 103.00 FS | *103.00 FS |
| 14 | 10 | | *FASTENER - BUMPER | Necessary | 20.00 FS | *20.00 FS |
| 15 | 1 | | *LH BRACKER ASSY - RE | Broken | 22.00 FS | *22.00 FS |
| 16 | 1 | | *RH BRACKET ASSY - RE | Not Necessary | 22.00 FS | *- FS |
| 17 | 1 | | *LH COVER-BLANKING RR | Cut | 44.00 FS | *44.00 FS |
| 18 | 1 | | *LH LAMP ASSY-REAR FO | Broken | 129.00 FS | *129.00 FS |
| 19 | 1 | | *RH COVER-BLANKING RR | Not Necessary | 44.00 FS | *- FS |
| 20 | 1 | | *RH LAMP ASSY-REAR FO | Not Necessary | 129.00 FS | *- FS |
| 21 | 4 | | *ULTRASONIC SENSOR-S. | Not Necessary | 748.00 FS | *- FS |
| 22 | 2 | | *OTR ULTRASONIC SENSO | Not Necessary | 374.00 FS | *- FS |
| 23 | 1 | | *UNDER COVER ASSY-RR | Not Necessary | 30.00 FS | *- FS |
| 24 | 1 | | *LH SIDE GARNISH ASSY | Crushed | 49.00 FS | *49.00 FS |
| 25 | 1 | | *WIRING HARNESS-R.P.A | Not Necessary | 357.00 FS | *- FS |
| 26 | 1 | | *RAIL ASSY-REAR BUMPE | Bent | 341.00 FS | *341.00 FS |
| 27 | 1 | | *ANTENNA ASSY-SMARTKE | Not Necessary | 33.00 FS | *- FS |
| 28 | 1 | | *CAP-RR HOOK | Crushed | 8.00 FS | *8.00 FS |

F=Franchise part. S=SpcNett.

| | | |
|---------------------------|-----------------|-----------------|
| Total Parts (\$\$) | 7,300.00 | 4,736.00 |
|---------------------------|-----------------|-----------------|

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | DIAGNOSTIC / SCANNING | New | 250.00 | 250.00 |
| 2 | TO CHECK ALL LIGHTING / WIRING SYSTEM ON REAR ACCIDENT | New | 100.00 | 80.00 |
| 3 | TO REPLACE TAILGATE GLASS | New | 300.00 | 300.00 |
| 4 | TO INSTALL RIKECOOL SOLAR FILM ON NEW TAILGATE GLASS | New | 220.00 | 220.00 |
| 5 | TO APPLY SELANT KIT IN NEW TAILGATE GLASS | New | 100.00 | 100.00 |
| 6 | TO TRANSFER TAILGATE COMPONENTS & MECHANISM PARTS | New | 640.00 | 320.00 |
| 7 | TO REMOVE & RE-INSTALL ALL CARPETS / TRIMMING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS | New | 640.00 | 0.00 |
| 8 | TO APPLY SEALANT KIT ON NEW & REPAIR PANELS | New | 200.00 | 100.00 |
| 9 | TO REPLACE TAILGATE, UPR & LWR REAR BUMPER, SKID PLATE, BRACKETS, CLIPS, FOG LAMP & COVER, SENSORS, GARNISH, ETC - TO LHR OTR FENDER & REPAIR REAR END PANEL STRAIGHTEN, REFORM, ALIGN REAR ACCIDENT AFFECTED AREAS | New | 3,840.00 | 1,920.00 |
| 10 | SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS | New | 2,750.00 | 2,200.00 |
| 11 | CERAMIC COATING (OWNER PURCHASED) | New | 500.00 | 150.00 |
| Gross Labour Cost (\$\$) | | | 9,540.00 | 5,640.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >