



CYCLE & CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111	Cust No/Name Reg No/Reg Date Date In/Mileage Chassis No Engine No Make/Model Colour/Trim	/Mr Boey Teck Meng / 23/09/2019 SJA7375Z / 41310 KNAPH81BMK5523944 D4HBJH205584 KIA/SORENTO 2.2 A SR D EGO KLG / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Qty	Unit Price	Disc%	Amount
F0000018	Credit	14/04/2021/ 11:34	DS	303 / Renemer	10198				250.00
Description of Goods / Services									
S	MIPNT88088	DIAGNOSTIC/SCANNING							80 100.00
S	MIPNT88088	TO CHECK ALL LIGHTING/WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS							300.00
S	MIPNT88088	TO REPLACE TAILGATE GLASS							220.00
S	MIPNT88088	TO INSTALL RIKECOOL SOLAR FILM ON NEW TAILGATE GLASS							100.00
S	MIPNT88088	TO APPLY SELANT KIT IN NEW TAILGATE GLASS							320 640.00
S	MIPNT88088	TO TRANSFER TAILGATE COMPONENTS & MECHANISM PARTS							1 640.00
S	MIPNT88088	TO REMOVE & RE-INSTALL ALL CARPETS/TRIMMING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS							100 200.00
S	MIPNT88088	TO APPLY SEALANT KIT ON NEW & REPAIR PANELS							1920 3840.00
S	MIPNT88088	TO REPLACE TAILGATE,UPR & LWR REAR BUMPER,SKID PLATE,BRACKETS,CLIPS, FOG LAMP & COVER,SENSORS,GARNISH,ETC							3 640
S	MIPNT88088	-TO LHR OTR FENDER & REPAIR REAR END PANEL STRAIGHTEN,REFORM,ALIGN ON REAR ACCIDENT AFFECTED AREAS							2200 2750.00
S	MIPNT98088	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS							150 500.00
S	MIPNT88088	CERAMIC COATING (OWNER PURCHASED)							1.00 69.00 0.00 69.00
M	KS 86320 C5 100	EMBLEM-KIA							1.00 28.00 0.00 28.00
M	KS 86310 C5 010	EMBLEM-SORENTO							1.00 37.00 0.00 37.00
M	KS 86333 C5 000	EMBLEM - ECO DYNAMIC							1.00 690.00 0.00 690.00
M	KS 87110 C5 000	GLASS ASSY - TAILGAT							4.00 17.00 0.00 68.00
M	KS 86114 2L 000	PAD-WINDSHIELD							

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111	Cust No/Name /Mr Boey Teck Meng Reg No/Reg Date SJA7375Z / 23/09/2019 Date In/Mileage 13/04/2021/ 41310 Chassis No KNAPH81BMK5523944 Engine No D4HBJH205584 Make/Model KIA/SORENTO 2.2 A SR D EGD Colour/Trim KLG / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000018	Credit	14/04/2021/ 11:34	DS	303 / Renemer	10198

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M KS 86114 3D 000 PAD-W/SHLD GLASS <i>MC</i>	6.00	2.00	0.00	12.00
M KS 87115 C5 000 STOPPER-RR WINDOW GL <i>MC</i>	2.00	4.00	0.00	8.00
M KS 73700 C5 121 PANEL ASSY-TAIL GATE <i>DD</i>	1.00	1445.00	0.00	1445.00
M KS 92403 C5 600 LH INR LAMP ASSY-REA <i>X NI</i>	1.00	827.00	0.00	827.00
M KS 92401 C5 600 LH OTR LAMP ASSY-REA <i>BR</i>	1.00	493.00	0.00	493.00
M KS 86611 C5 510 UPR COVER-RR BUMPER <i>DD</i>	1.00	605.00	0.00	605.00
M KS 86612 C5 500 LWR COVER - REAR BUM <i>CHT (QAK)</i>	1.00	565.00	0.00	565.00
M KS 86665 C5 510 SKID PLATE - REAR BU <i>CHT (SIL)</i>	1.00	103.00	0.00	103.00
M KS 0G032 50 037A FASTENER- BUMPER <i>MC</i>	10.00	2.00	0.00	20.00
M KS 86661 C5 000 LH BRACKET ASSY - RE <i>DR</i>	1.00	22.00	0.00	22.00
M KS 86662 C5 000 RH BRACKET ASSY - RE <i>X NI</i>	1.00	22.00	0.00	22.00
M KS 86653 C5 500 LH COVER-BLANKING RR <i>CHT</i>	1.00	44.00	0.00	44.00
M KS 92405 C5 510 LH LAMP ASSY-REAR FO <i>DR</i>	1.00	129.00	0.00	129.00
M KS 86654 C5 500 RH COVER-BLANKING RR <i>X NI</i>	1.00	44.00	0.00	44.00
M KS 92406 C5 510 RH LAMP ASSY-REAR FO <i>X NI</i>	1.00	129.00	0.00	129.00
M KS 96890 C5 500B 4U ULTRASONIC SENSOR-S. <i>X NI</i>	4.00	187.00	0.00	748.00
M KS 96890 C5 200 OTR ULTRASONIC SENSO <i>X NI</i>	2.00	187.00	0.00	374.00
M KS 86690 C5 500 UNDER COVER ASSY-RR <i>X NI</i>	1.00	30.00	0.00	30.00
M KS 87741 C5 000 LH SIDE GARNISH ASSY <i>CR4</i>	1.00	49.00	0.00	49.00
M KS 91885 C5 130 WIRING HARNESS-R.P.A <i>X NI</i>	1.00	357.00	0.00	357.00
M KS 86630 C5 510 RAIL ASSY-REAR BUMPE <i>BT</i>	1.00	341.00	0.00	341.00
M KS 95420 C6 500 ANTENNA ASSY-SMARTKE <i>X NI</i>	1.00	33.00	0.00	33.00
M KS 86667 C5 500 CAP-RR HOOK <i>CR4</i>	1.00	8.00	0.00	8.00

Z NOTES

ACCIDENT ON 13/04/2021 ALONG LOYANG AVENUE FILTERING TO TPE

OWNER CLAIMING THIRD PARTY

REQUIRED REPLACEMENT CAR

TP#: GBC2203D

TP INS: CHINA TAIPING

Steve (LKK) ML PL
15/4/21, 11.00am
5 dgs
P/P
My BL dy

LKK Auto Consultants hence notify the insurer of the following:

Confirm & accepted by before/after spray painting

- damaged part(s) during resurvey
- all prices are subject to confirmation
- survey is on a "Without Prejudice" basis
- any modification(s) is allowed
- supplementary item(s) must be resurveyed and
- subject to final approval from Insurance Company

Authorized signatory and company stamp

Parts	7,300.00
Labour	0.00
Standard Menu	0.00
Specialist Job	9,540.00
Others(Lub,etc)	0.00
Sundry	0.00
Total(w/o GST)	16,840.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.