

## CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD **EUNOS LINK SERVICE CENTRE**



330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

## **ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info			
CHINA TAIPING INSURANCE (SINGAPORE)	Cust No/Name	/Mr Boey Teck Meng		
3 Anson Road #16-00	Reg No/Reg Date	SJA7375Z / 23/09/2019		
Springleaf Tower	Date In/Mileage	19/04/2021/ 41902		
Singapore 079909 Attn: Claims Dept.	Chassis No	KNAPH81BMK5523944		
	Engine No	D4HBJH205584		
Contact No 63896111	Make/Model	KIA/SORENTO 2.2 A SR D EGD		
	Colour/Trim	KLG / WK		

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No		
0000018	Credit	27/04/2021/ 10:36	DS	303 / Renemer		10198		
		Description of Go	ods / Service	es	Qty	Unit Price	Disc%	Amount
MIPNT880								250.00
DIAGNOST		NG						
S MIPNT880								80.00
		HTING/WIRING SYSTE	ON REAR A	CCIDENT				
AFFECTED								200.0
MIPNT880		ATE CLACE						300.0
S MIPNT880		ATE GLASS						220.0
		OOL SOLAR FILM ON	NEW TATICAT	F GLASS				220.0
S MIPNT880		OUL SOLAR TILM ON	ILW INILUMI	L GLASS				100.0
		CIT IN NEW TAILGAT	E GLASS	П	П			20010
MIPNT880	88		0	ARTS M	200			320.0
TO TRANS	FER TAIL	GATE COMPONENTS &	MECHANISM P	ARTS		]		
						7		100.0
TO APPLY	SEALANT	KIT ON NEW & REPA	IR PANELS					
MIPNT880								1920.0
				D PLATE, BRACKETS, CI	LIPS,		12.0	
		,SENSORS,GARNISH,E	тс					
		END PANEL	OIDENT AFF	CTED ADEAC				
		A,ALIGN ON REAR AC	CIDENI AFFE	CIED AKEAS				2200.0
S MIPNT980		N REAR ACCIDENT AF	FECTED AREA	2				2200.0
		JMPER, LHR OTR FEND						
S MIPNT880		orn Erry Erric Oric Teno	EN INCHES	, , , , , , , , , , , , , , , , , , , ,				150.0
CERAMIC								
	URCHASED	)						
X KS 86320		EMBLEM-KI	Α		1.00	69.00	0.00	69.0
X KS 86310	C5 010	EMBLEM-SO	RENTO		1.00	28.00	0.00	28.0
X KS 86333			ECO DYNAMIO		1.00	37.00		37.0
X KS 87110			Y - TAILGA		1.00	690.00		690.0 68.0
M KS 86114		PAD-WINDS			4.00	17.00 2.00	0.00	12.0
M KS 86114		PAD-W/SHL			6.00 2.00	4.00	0.00	8.0
M KS 87115	C5 000	STOPPER-R	R WINDOW GI		2.00	4.00	0.00	0.0

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



## CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD **EUNOS LINK SERVICE CENTRE**



330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

## **ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info		
CHINA TAIPING INSURANCE (SINGAPORE)	Cust No/Name	/Mr Boey Teck Meng	
3 Anson Road #16-00	Reg No/Reg Date	SJA7375Z / 23/09/2019	
Springleaf Tower	Date In/Mileage	19/04/2021/ 41902	
Singapore 079909	Chassis No	KNAPH81BMK5523944	
Attn: Claims Dept.	Engine No	D4HBJH205584	
Contact No 63896111	Make/Model	KIA/SORENTO 2.2 A SR D EGD	
	Colour/Trim	KLG / WK	

Credit	27/04/2021/ 10:36	DC					
	27/01/2021/ 10100	DS	303 / Renemer		10198		
	Description of Good	s / Services		Qty	<b>Unit Price</b>	Disc%	Amount
AIMING THE RENTAL 2203D TION (TO	UPR COVER-R LWR COVER - SKID PLATE FASTERNER- LH BRACKET LH COVER-BL LH LAMP ASS LH SIDE GAR RAIL ASSY-R CAP-RR HOOK HIRD PARTY  TP INS: CHINA TA	ASSY-REA R BUMPER REAR BUM - REAR BU BUMPER ASSY - RE ANKING RR Y-REAR FO NISH ASSY EAR BUMPE AVENUE FIL	Imag	1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	1445.00 493.00 605.00 565.00 103.00 22.00 44.00 129.00 49.00 341.00 8.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	1445.00 493.00 605.00 565.00 103.00 20.00 44.00 129.00 49.00 341.00 8.00
Confirm & accepted by				Parts Labour Standard Menu Specialist Job Others(Lub,etc) Sundry Total(w/o GST)			4,736.0 0.0 0.0 5,640.0 0.0 10,376.0
	C5 510 C5 500 C5 510 50 037A C5 000 C5 500 C5 510 C5 500 C5 500 C5 500 C5 510 C5 500 C5 600 C5 6000 C5 600 C5 600 C5 600 C5 600 C5 600 C5 600 C5 600 C5 600 C5 6000 C5 600 C5 600 C5 600 C5 600 C5 600 C5 600 C5 600 C5 600 C5 6000 C5 600 C5 60	C5 600 LH OTR LAMP C5 510 UPR COVER-R C5 500 LWR COVER - C5 510 SKID PLATE 50 037A FASTERNER- C5 000 LH BRACKET C5 500 LH COVER-BL C5 510 LH LAMP ASS C5 000 LH SIDE GAR C5 510 RAIL ASSY-R C5 500 CAP-RR HOOK ON 13/04/2021 ALONG LOYANG AIMING THIRD PARTY RENTAL 2203D TP INS: CHINA TA TION (TOTAL 5 WORKING DAYS) N TO: MR. STEVE CHEN	C5 600 LH OTR LAMP ASSY-REA C5 510 UPR COVER-RR BUMPER C5 500 LWR COVER - REAR BUM C5 510 SKID PLATE - REAR BU 50 037A FASTERNER- BUMPER C5 000 LH BRACKET ASSY - RE C5 500 LH COVER-BLANKING RR C5 510 LH LAMP ASSY-REAR FO C5 000 LH SIDE GARNISH ASSY C5 510 RAIL ASSY-REAR BUMPE C5 500 CAP-RR HOOK C5 500 CAP-RR HOOK C5 500 TO TINS: CHINA TAIPING	C5 500 LH OTR LAMP ASSY-REA C5 510 UPR COVER-RR BUMPER C5 500 LWR COVER - REAR BUM C5 510 SKID PLATE - REAR BU 50 037A FASTERNER- BUMPER C5 000 LH BRACKET ASSY - RE C5 500 LH COVER-BLANKING RR C5 510 LH LAMP ASSY-REAR FO C5 000 LH SIDE GARNISH ASSY C5 510 RAIL ASSY-REAR BUMPE C5 500 CAP-RR HOOK ON 13/04/2021 ALONG LOYANG AVENUE FILTERING TO TPE AIMING THIRD PARTY RENTAL C2203D TP INS: CHINA TAIPING TION (TOTAL 5 WORKING DAYS) N TO: MR. STEVE CHEN	C5 500	C5 600 LH OTR LAMP ASSY-REA 1.00 493.00 C5 510 UPR COVER-RR BUMPER 1.00 605.00 C5 500 LWR COVER - REAR BUM 1.00 565.00 C5 510 SKID PLATE - REAR BUM 1.00 103.00 50 037A FASTERNER- BUMPER 10.00 2.00 C5 000 LH BRACKET ASSY - RE 1.00 22.00 C5 000 LH COVER-BLANKING RR 1.00 44.00 C5 510 LH LAMP ASSY-REAR FO 1.00 129.00 C5 000 LH SIDE GARNISH ASSY 1.00 49.00 C5 510 RAIL ASSY-REAR BUMPE 1.00 341.00 C5 500 CAP-RR-HOVE PLITERING TO THE TRING TO THE TRIN	C5 600 LH OTR LAMP ASSY-REA 1.00 493.00 0.00 C5 510 UPR COVER-RR BUMPER 1.00 605.00 0.00 C5 510 SKID PLATE - REAR BUM 1.00 103.00 0.00 C5 510 SKID PLATE - REAR BU 1.00 103.00 0.00 C5 50 037A FASTERNER- BUMPER 10.00 2.00 0.00 C5 500 LH BRACKET ASSY - RE 1.00 22.00 0.00 C5 500 LH COVER-BLANKING RR 1.00 44.00 0.00 C5 510 LH LAMP ASSY-REAR FO 1.00 129.00 0.00 C5 510 LH SIDE GARNISH ASSY 1.00 49.00 0.00 C5 510 RAIL ASSY-REAR BUMPE 1.00 49.00 0.00 C5 500 CAP-RR-HOOK OF ARL ASSY-REAR BUMPE 1.00 341.00 0.00 C6 500 CAP-RR-HOOK OF ARL ASSY 1.00 49.00 0.00 C7 500 CAP-RR-HOOK OF ARL ASSY 1.00 49.00 0.00 C7 500 CAP-RR-HOOK OF ARL ASSY 1.00 A9.00 0.00 C7 500 CAP-RR-HOOK OF ARL ASSY 1.00 A9.00 0.00 C7 500 CAP-RR-HOOK OF ARL ASSY 1.00 A9.00 0.00 C7 500 CAP-RR-HOOK OF ARL ASSY 1.00 A9.00 0.00 C7 500 CAP-RR-HOOK OF ARL ASSY 1.00 A9.00 0.00 C7 500 CAP-RR-HOOK OF ARL ASSY 1.00 A9.00 0.00 C7 500 CAP-RR-HOOK OF ARL ASSY 1.00 A9.00 0.00 C7 500 CAP-RR-HOOK OF ARL ASSY 1.00 A9.00 0.00 C7 500 CAP-RR-HOOK OF ARL ASSY 1.00 A9.00 0.00 C7 500 CAP-RR-HOOK OF ARL ASSY 1.00 A9.00 0.00 C7 500 CAP-RR-HOOK OF ARL ASSY 1.00 A9.00 0.00 C7 500 CAP-RR-HOOK OF ARL ASSY 1.00 A9.00 0.00 C7 500 CAP-RR-HOOK OF ARL ASSY 1.00 A9.00 0.00 C7 500 CAP-RR-HOOK OF ARL ASSY 1.00 A9.00 0.00 C7 500 CAP-RR-HOOK OF ARL ASSY 1.00 A9.00 0.00 C7 500 CAP-RR-HOOK OF ARL ASSY 1.00 A9.00 0.00 C7 500 CAP-RR-HOOK OF ARL ASSY 1.00 CAP-RR-HOOK OF ARL AS

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.