



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJT 9899R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	CRACKED	1,320.00	1,320.00
1	GRILLER RHS	CRACKED	255.00	255.00
1	GRILLER LHS	CRACKED	255.00	255.00
1	LOGO (FRONT)	NECESSARY	79.00	79.00
1	COVERING	CRACKED	125.00	125.00
1	PLATE (METAL)	BENT	340.00	340.00
2	FRONT HEADLAMP @\$2650.00	BROKEN	5,300.00	5,300.00
1	DERFORMATION ELEMENT (F) RHS	BENT	135.00	135.00
2	HEADLAMP BRACKET LHS/RHS @\$16.00	NECESSARY	32.00	32.00
1	FRONT LED MODULE CORNERING LIGH (LHS) (ADDITIONAL)	NOT WORKING	260.00	260.00
			8,101.00	8,101.00
	<u>LABOUR</u>			
	LABOUR CHARGE FOR REPLACING PARTS.		850.00	550.00
	RESPRAY FRONT BUMPER & REAR.		580.00	380.00
	LABOUR TO REMOVE AND INSTALL / REPLACE. (ADDITIONAL)		120.00	60.00
			1,550.00	990.00
	GRAND TOTAL		9,651.00	9,091.00
	COST OF REPAIRS			9,091.00

Report Ref No. CS/UOI21004742/Gvf3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.