



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 868C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	CUT	2,920.00	1,224.60
1	FRONT BUMPER L/H SIDE GRILLE	SERVICEABLE	259.00	-
1	FRONT BUMPER L/H FOG LAMP	SCRATCHED	647.00	647.00
1	FRONT BUMPER L/H SIDE RETAINER	NECESSARY	290.00	290.00
1	FRONT BUMPER R/H SIDE RETAINER	NECESSARY	290.00	290.00
1	L/H FRONT FENDER (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 10% DISCOUNT		-	-245.16
			4,406.00	2,206.44
LABOUR				
	TO PANEL BEAT AND RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS. INCLUSIVE OF THE REPAIR OF L/H FRONT FENDER.		1,000.00	400.00
	TO CHECK WIRING AND REWIRE.		60.00	30.00
	TO PERFORM 4 WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	TO PERFORM CAR WRAP ON AFFECTED AREA.		700.00	400.00
	TO PUTTY AND SPRAY-PAINT OF AFFECTED AREAS.		800.00	400.00
			2,680.00	1,230.00
GRAND TOTAL			7,086.00	3,436.44
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,750.00

Report Ref No. CS1/ASM21004752/Vvy3e2

THEVAN THOMAS KARTHIKESAVAN

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.