

CS1/ASm21004752/Vuy3



TY5 CONSULTANCY

(Registration No.: 53129875C)

Address : 50 Chin Swee Road #09-04, Thong Chai Building, Singapore 169874

Contact : +65 8788 5345 | Email Address : admin@ty5group.com.sg

Our Services : Automotive Surveying | Vehicle Valuation
Motor Claims Investigation | Evaluation & Consultation

Reference : TY5/TA/10010/0868/TP/0421
Date : 05 May 2021
Vehicle no : SLM 868C

To: Li Bing Xuan Desmond
c/o 8 Kaki Bukit Ave 4
#03-47, Premier @ Kaki Bukit
Singapore 415875

VEHICLE INSPECTION REPORT

Name of Workshop : Lush Automotive Pte Ltd
Place of inspection : 8 Kaki Bukit Ave 4 #03-47, Premier @ Kaki Bukit, Singapore 415875
Date of Accident : 08 April 2021
Date of Inspection : 11 April 2021

VEHICLE PARTICULAR

Registration No. : SLM 868C
Make / Model : Porsche Macan S 3.0 AT 4WD
Year of Registration : 2015
Class / Type : SUV
Chassis Frame No. : WP1ZZZ95ZF1B66995
Engine No. : 018245
Odometer Reading : 68,744 KM
Colour : Blue

VEHICLE CONDITION

General Condition : Very Good
Paintwork : Very Good
Steering : Serviceable
Foot/ Parking Brake : Serviceable

TYRE CONDITION

	Size	Thread Balance
Front L/H :	RADAR 235 / 60 ZR18	9mm
Front R/H :	RADAR 235 / 60 ZR18	9mm
Rear L/H :	RADAR 235 / 60 ZR18	9mm
Rear R/H :	RADAR 235 / 60 ZR18	9mm

* The above is an estimate of the remaining life of the tyre thread in percentages

COST OF REPAIR

	Repairer SS	Adjuster SS
Parts	\$ 4,406.00	\$ 3,965.40
Labour	\$ 2,680.00	\$ 2,150.00
	<u>\$ 7,086.00</u>	<u>\$ 6,115.40</u>

TY5 Recommendation

Lump Sum Repair :
\$ 4,900.00

Estimated Repair Duration :

4

working days (excluding Sat, Sun & Public Holidays)

NOTE : The information contained in these documents may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited.



TY5 CONSULTANCY

(Registration No.: 53429875C)

Address : 50 Chin Swee Road #09-04, Thong Chai Building, Singapore 169874

Contact : +65 8788 5345 | Email Address : admin@ty5group.com.sg

*Our Services : Automotive Surveying | Vehicle Valuation
Motor Claims Investigation | Evaluation & Consultation*

Reference : TY5/TA/10010/0868/TP/04.21
Date : 05 May 2021
Vehicle no : SLM 868C

ASSESSMENT SCHEDULE

<u>SN</u>	<u>Qty</u>	<u>Descriptions</u>	<u>Conditions</u>	<u>Repairer's Estimate</u>	<u>Surveyor's Revised</u>
<u>LIST ITEMS:-</u>					
1	1 pc	front bumper	deformed	\$ 2,920.00	\$ 2,920.00
2	1 pc	front bumper l/h side grille	scratched	\$ 259.00	\$ 259.00 <i>cut</i>
3	1 pc	front bumper l/h fog lamp	scratched	\$ 647.00	\$ 647.00 <i>Src</i>
4	1 pc	front bumper l/h side retainer	necessary	\$ 290.00	\$ 290.00 ✓
5	1 pc	front bumper r/h side retainer	necessary	\$ 290.00	\$ 290.00 ✓
6	1 pc	l/h front fender	damaged		
				repair	repair
				\$ 4,406.00	\$ 4,106.00
		Less	10%		\$ 410.60
				\$ 4,406.00	\$ 3,965.40

Total \$ 4,406.00 \$ 3,965.40



TY5 CONSULTANCY

(Registration No.: 53129875C)

Address : 50 Chin Swee Road #09-01, Thong Chai Building, Singapore 169874

Contact : +65 8788 5345 | Email Address : admin@ty5group.com.sg

Our Services : *Automotive Surveying* | *Vehicle Valuation*
Motor Claims Investigation | *Evaluation & Consultation*

Reference : TY5/TA/10010/0868/TP/04.21
 Date : 05 May 2021
 Vehicle no : SLM 868C

ASSESSMENT SCHEDULE

<u>SN</u>	<u>Qty</u>	<u>Descriptions</u>	<u>Conditions</u>	<u>Repairer's Estimate</u>	<u>Surveyor's Revised</u>
		B/F		\$ 4,406.00	\$ 3,965.40
7		To panel beat and renewal of all necessary damaged body parts		\$ 1,000.00	\$ 800.00 400
8		To check wiring and rewire		\$ 60.00	\$ 50.00 30
9		To perform 4 wheel alignment		\$ 120.00	\$ 100.00 xnn
10		To perform car wrap on affected area.		\$ 700.00	\$ 600.00 400
11		To putty and spray-paint of affected areas		\$ 800.00	\$ 600.00 400
				<u>\$ 2,680.00</u>	<u>\$ 2,150.00</u>

Total \$ 7,086.00 \$ 6,115.40



TY5 CONSULTANCY

(Registration No.: 53429875C)

Address : 50 Chin Swee Road #09-01, Thong Chai Building, Singapore 169871

Contact : +65 8788 5345 | Email Address : admin@ty5group.com.sg

Our Services : *Automotive Surveying* | *Vehicle Valuation*
Motor Claims Investigation | *Evaluation & Consultation*


Reference : TY5/TA/10010/0868/TP/04.21

Date : 05 May 2021

Vehicle no : SLM 868C

ASSESSMENT SUMMARY

Damages sustained were consistent with the subject vehicle being involved in a collision with another vehicle and the impact of the collision was delivered **Diagonally** to the LH Side from rear to front; left to right; portion of the vehicle.



(Please refer to the list and survey photographs as attached for more information)

ASSESSMENT RECOMMENDATIONS

COST OF REPAIR

	Repairer S\$	Adjuster S\$
Parts	\$ 4,406.00	\$ 3,965.40
Labour	\$ 2,680.00	\$ 2,150.00
	<u>\$ 7,086.00</u>	<u>\$ 6,115.40</u>

TY5 Recommendation

Contract Lump Sum of \$ 4,900.00 **3950**

Estimated Repair Duration : 4 working days ✓
(excluding Sat, Sun & Public Holidays)

Enclosed No. Of Photograph : 28
(at the time of static inspection)

Our attached assessment schedule has been checked thoroughly by us against the actual damages sustained on the vehicle, and we recommend the replacement of parts and repair accordingly. We have adjusted the cost and the repairer has agreed to undertake the repair at the recommended sum to a acceptable quality and standards. We have not given authorization and instruction to the repairer to proceed with the repairs.

The survey was done on a **Without Prejudice Basis** and we are reverting the matter to you for a decision.

We thank you for engaging our services and we enclosed herewith our invoice no. 10010

TY5 CONSULTANCY

TERRENCE HONG

AUTOMOTIVE SURVEYOR

NOTE : *This revised estimate was from a visual inspection. Should there be any discrepancy or unseen items not listed in this survey, kindly notify the company via email only and follow up with a phone call, within Fourteen (14) days from the date hereof. Otherwise this revised amount shall be treated as valid.*