



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 4870M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	COVER-RR BUMPER	CRUSHED	459.40	459.40
10	BUMPER COVER CLIP REAR	NECESSARY	22.00	22.00
1	PANEL ASSY-QUARTER OUTER	TO REPAIR SEE LABOUR	1,768.30	-
1	BRACKET ASSY-RR BUMPER SI	BROKEN	55.80	55.80
	LESS 20% DISCOUNT		-461.10	-107.44
			1,844.40	429.76
	<b><u>LABOUR</u></b>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF PANEL ASSY-QUARTER OUTER.		1,100.00	700.00
	SPRAYPAINT CHARGE.		600.00	500.00
	TUFF COAT ON AFFECTED PARTS.		50.00	30.00
	REMOVE/REFIX UPHOLSTERY ASST REPAIR.	NOT NECESSARY	120.00	-
	REMOVE/REFIX REVERSE SENSOR.		80.00	30.00
			1,950.00	1,260.00
<b>GRAND TOTAL</b>			<b>3,794.40</b>	<b>1,689.76</b>
<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>				<b>1,689.76</b>

Report Ref No. NS/INC21004753/Evcn2

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.