



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 378E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	LH WING MIRROR ASSY	CRACKED	680.00	680.00
1	LH FRONT FENDER	TO REPAIR SEE LABOUR	550.00	-
1	LH FRONT FENDER INNER SHIELD	SERVICEABLE	100.00	-
8	LH FRONT FENDER INNER SHIELD CLIPS @\$3.50	NOT NECESSARY	28.00	-
1	LH FRONT BUMPER SIDE RETAINER	SERVICEABLE	30.00	-
	LESS 20% DISCOUNT		-277.60	-136.00
			1,110.40	544.00
<b><u>SPECIAL NETT ITEMS</u></b>				
1	LH FRONT DOOR COMPANY ADVERTISEMENT STICKER (SN)	NECESSARY	400.00	100.00
			400.00	100.00
<b><u>LABOUR</u></b>				
	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW AFFECTED PARTS. INCLUSIVE OF THE REPAIR OF LH FRONT FENDER.		650.00	250.00
	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.		950.00	660.00
			1,600.00	910.00
<b>GRAND TOTAL</b>			<b>3,110.40</b>	<b>1,554.00</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,200.00</b>

Report Ref No. CS/SMR21004754/Kuf3e2

**KONG SENG CHEONG**

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.