



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 8576K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR FENDER RH	BENT	1,245.80	974.30
1	REAR WINDSCREEN MOULDING	NECESSARY	154.80	154.80
1	TAIL LAMP RH	CRACKED	485.70	452.00
	LESS 25% DISCOUNT		-471.58	-395.28
			1,414.72	1,185.82
<u>SPECIAL NETT ITEMS</u>				
1	REAR WINDSCREEN GLASS SEALANT (SN)	NECESSARY	50.00	50.00
			50.00	50.00
<u>LABOUR</u>				
	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE 'PARTS REPAIR' COLUMN INCLUSIVE OF REPLACEMENT PARTS.		675.00	500.00
	PUTTY & SPRAY PAINTING TO ADJACENT PANELS. JOB ALLOWANCE. PAINT / MATERIAL.		250.00	250.00
	APPLY RUST PROOFING ON THE ADJACENT PANELS.		20.00	20.00
	WIRING AND BULB CHECKING.		36.00	30.00
	REMOVE AND REAR WINDSCREEN GLASS (2-MAN JOB).		157.50	120.00
			1,138.50	920.00
GRAND TOTAL			2,603.22	2,155.82
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,700.00

Report Ref No. CS3/LPC21002968/T1qf3e2-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.