Upc paper survey

No.25 Kaki Bukit Road 4

#06-46 Synergy @KB Singapore 41780

Hotline: 6385 1171



Practicing Management Consultant (PMC) of SBACC
Approved Training Organisation (ATO) of Workforce Singapore

Our reference:

21-7488

Date:

15/3/2021

c/o Freesion Autodrive 25 Kaki Bukit Road 4 Synergy @ KB #03-33 Singapore 417800

**Dear Sirs** 

RE:

Road Traffic Accident on 4/3/2021

Mcqueen Rentals Pte Ltd

In accordance with your instructions received in this office or

8/3/2021

, we made arrangements to

examine the vehicle on

8/3/2021

at above-mentioned address. The following data was

recorded:

#### Vehicle details

Make	Toyota	Registration	SKZ8576K
Model	Corolla	Chassis	NRE1610010108
Colour	White	Gearbox	Auto
Odometer	293405km	Paintwork	Good
Steering	In order	Brakes	In order
Condition	Good		

#### Tyre Depths

Front left	185/60R15	80% Kapsen
Front right	185/60R15	80% Kapsen
Rear left	185/60R15	80% Kapsen
Rear right	185/60R15	80% Kapsen

Status	REPAIRABLE			
Magnitude	Medium			
Legal status	Unroadworthy			

### Impact Direction & Area of Damage:



Following our examination of the accident damage, we have calculated repair times and method, which are detailed on page 2 & 3. We would recommend a sum of \$2,603.23 and 4 working days for repair, which is sufficiently lower than the pre accident value to render the vehicle an economically and physically reliable proposition.

- Impact Analysis Consulting Pte Ltd
   Impact Analysis Academy Pte Ltd
   IA Racking Solutions Pte Ltd
- IA Accounting & Consultancy Pte Ltd
   Infoknights International Services (Philippines)
   IABN Pte Ltd www.iaconsultingsg.com



Practicing Management Consultant (PMC) of SBACC Approved Training Organisation (ATO) of Workforce Singapore

Our reference

21-7488

Date

15/3/2021

Page

2

Section A: Damaged Parts Assessment

-	dioni in Dania Boar				
Part's Description	Qty	Condition As inspected	Repairer's Estimate	Our Adjustment	
List Items:					bt/
Rear fender rh	1	deep-cut/yield	1,245.80	1245.80	974.30.01
Rear windsceen moulding	1	necessary	154.80	154.80	974.30.bt
Tail lamp rh	1	broken	485.70	485.70	452 cm1/
	Sub- Total	costs	1886.30	1886.30	
	Percentage discount :	25%	471.58	471.58	1581.10
	Sub-Total costs for parts		1414.73	1414.73	1581.10
Special Nett Items:					
Rear windscreen glass sealant	1	necessary	50.00	50.00	/
	Sub-Total costs for parts		50.00	50.00	V nel
Parts Repair					
*	*	*	0.00	0.00	
	Sub- Total	costs	0.00	0.00	
	Total costs fo	or parts	1464.73	1464.73	

No.25 Kaki Bukit Road 4

#06-46 Synergy @KB Singapore 41780 Hotline: 6385 1171

<sup>■</sup> Impact Analysis Consulting Pte Ltd ■ Impact Analysis Academy Pte Ltd ■ IA Racking Solutions Pte Ltd

■ Impact Analysis Academy Pte Ltd ■ IA Racking Solutions Pte Ltd

■ Impact Analysis Academy Pte Ltd ■ IA Racking Solutions Pte Ltd

■ Impact Analysis Academy Pte Ltd ■ Impact Analysis Academy Pte Ltd

■ Impact Analysis Academy Pte Ltd



Practicing Management Consultant (PMC) of SBACC
Approved Training Organisation (ATO) of Workforce Singapore

Our reference

21-7488

Date

15/3/2021

Page

3

## Section B: Labour Cost Calculation

	Но	urly rate	Manhr. Req.		Total
To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mentioned on the 'Parts Repair' column inclusive of replacement parts.	\$	45.00	15	\$	675.00
Putty & Spray painting to adjacent panels. Job allowance. Paint / material.	Sub-contract work.		\$	250.00	
Apply rust proofing on the adjacent panels.	Sub-contract work. \$ 20.0		20.00		
Wiring and bulb checking	\$	45.00	0.8	\$	36.00
Remove and rear windscreen glass (2-man job)	\$	45.00	3.5	\$	157.50
		Total la	bour cost	\$	1,138.50

Manhour rate and the number of manhours required for each repairing task are formulated based on individual workshop's operating cost and in-house@ IA Research Guidelines respectively.

42

2155.82.

No.25 Kaki Bukit Road 4

#06-46 Synergy @KB Singapore 41780 Hotline: **6385 1171** 

 <sup>■</sup> Impact Analysis Consulting Pte Ltd ■ Impact Analysis Academy Pte Ltd ■ IA Racking Solutions Pte Ltd

 <sup>■</sup> IA Accounting & Consultancy Pte Ltd
 ■ Infoknights International Services (Philippines)
 ■ IABN Pte Ltd www.iaconsultingsg.com



Practicing Management Consultant (PMC) of SBACC
Approved Training Organisation (ATO) of Workforce Singapore

Our reference

21-7488

Date

15/3/2021

# Section C: Summary Table of Total Repair Cost

Desc	cription	Cost		
Damaged Parts Assessment (See section A)		\$1,464.73		
Part	-by-Part			
Further discount	0%	\$0.00		(185-8
	nded cost of placement	\$1,464.73	(1)	50
	t Calculation ection B)	\$1,138.50	(2)	2155
	epair Cost to hundred)	\$2,603.23	(1) + (2)	459 17

No.25 Kaki Bukit Road 4

#06-46 Synergy @KB Singapore 41780 Hotline: 6385 1171

We would recommend a sum of \$2,603.23 and 4 working days for repair. No further items will be approved without our expressed written agreement. Any significant additional items will be subject to a supplementary report.

Mechanical Engineer, Accident Expert Witness, Licensed Appraiser (Automobile)

B.Eng. (Hons, NUS)

Diploma.Mechanical Engineering

NTC-2 Automovite Technology

Sr.MIES, Institution of Engineers, Singapore (#20100091)

MATAI, Maryland Association of Traffic Accident Investigators

IAARS, International Association of Accident Reconstruction Specialists

PMC of Singapore Business Advisors & Consultants Council

ACTA certified Trainer, Singapore

SPRING- Recognised Certification for Management Consultants

- Impact Analysis Consulting Pte Ltd
   Impact Analysis Academy Pte Ltd
   IA Racking Solutions Pte Ltd
- IA Accounting & Consultancy Pte Ltd Infoknights International Services (Philippines) IABN Pte Ltd www.iaconsultingsg.com