

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21004757/EQF3E2
Date: 20/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070075740
Claimant Vehicle No : SMV1817J **Insured Vehicle No :** YP8554K
Date of Loss: 14/04/2021 Nature of Claim: TP Claim No: 1699091010SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMV1817J**
Make & Model: KIA CERATO, 1.6 SUNROOF (A) Engine No: G4FGKH754925
Reg. Date: 21/09/2020 (Man. Year: 2020) Chassis No: KNAF5416ML5086978
Colour: Grey Odometer: 14121 km
Engine Capacity: 1591 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
Front Left Side: Nexen 5 mm Rear Left Side: Nexen 5 mm
Front Right Side: Nexen 5 mm Rear Right Side: Nexen 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 15/04/2021
Date Inspected: 15/04/2021 Inspected At: Hock Eng Automobile Workshop (HQ)
BLK 3012 BEDOK INDUSTRIAL
PARK E #01-2034
SINGAPORE 489978
Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	0.00 F	*- F
2	1		*REAR BUMPER LOWER	Broken	0.00 F	*- F
3	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
4	2		*REAR BUMPER SIDE RETAINER	Broken	0.00 F	*- F
5	1		*REAR BUMPER REINFORCEMENT	* Check	0.00 F	*- F
6	1		*REAR BUMPER SIDE GARNISH RH	Cut	0.00 F	*- F
7	1		*REAR BUMPER RH LAMP	Cut	0.00 F	*- F
8	1		*REVERSE	Shorted	0.00 F	*- F
9	1		*REAR END PANEL	Repair	0.00 F	*- F
10	1		*REAR TAILLAMP RH	Cut	0.00 F	*- F
11	1		*BOOTLID	Dented	0.00 F	*- F
12	4		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
13	1		*BOOTLID REFLECTOR CENTRE	* Check	0.00 F	*- F
14	1		*BOOTLID LAMP RH	Broken	0.00 F	*- F
15	1		*BOOTLID LOCK	Bent	0.00 F	*- F
16	1		*BOOTLID RUBBER	* Check	0.00 F	*- F
17	1		*REAR RH FENDER	Repair	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >