



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGP 2760J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT FENDER LH	TO REPAIR SEE LABOUR	786.20	-
1	FRONT FENDER INNER SHIELD LH	TORN	210.10	166.10
1	FRONT SHOCK ABSORBER LH	NOT NECESSARY	347.10	-
1	FRONT SHOCK ABSORBER TOP MOUNTING LH	NOT NECESSARY	122.40	-
1	FRONT LOWER ARM LH	NOT NECESSARY	410.30	-
1	FRONT KNUCKLE ARM LH	NOT NECESSARY	485.20	-
1	FRONT KNUCKLE ARM BEARING LH	NOT NECESSARY	260.80	-
1	FRONT DRIVESHAFT LH	NOT NECESSARY	953.90	-
1	FRONT ANTI-ROLL BAR	NOT NECESSARY	296.50	-
1	FRONT ANTI-ROLL BAR LINK LH	NOT NECESSARY	125.40	-
1	STEERING RACK AND PINION	NOT NECESSARY	1,082.50	-
1	TIE ROD END LH	BENT	172.60	172.60
1	HEADLAMP LH	CRACKED	776.90	776.90
1	HEADLAMP LOWER BRACKET LH	NO SUCH PARTS	112.00	-
1	FRONT BUMPER	DISTORTED	665.50	665.40
2	FRONT BUMPER SIDE RETAINER @\$104.00	N/S CRACKED	208.00	32.50
1	BONNET (NPA)	NOT NECESSARY	-	-
	LESS 20% DISCOUNT		-1,403.08	-362.70
			5,612.32	1,450.80
<u>SPECIAL NETT ITEMS</u>				
1	SUNDRIES (SN)	NOT NECESSARY	60.00	-
1	SET FRONT BUMPER CLIPS (SN)	NOT NECESSARY	100.00	-
1	SET FRONT FENDER INNER SHIELD CLIPS LH (SN)	NOT NECESSARY	60.00	-
1	FRONT TYRE LH (SN)	SERVICEABLE	380.00	-
1	FRONT ALLOY RIM LH (SN)	TO REPAIR SEE LABOUR	850.00	-
			1,450.00	-

Report Ref No. CS/SMR21004761/Uuf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING AND STRENGTHEN PARTS ON ACCIDENT AREA. INCLUSIVE OF THE REPAIR OF FRONT FENDER LH AND FRONT ALLOY RIM LH.		1,000.00	400.00
	CHECK WIRING SYSTEM AFTER DISCONNECT AND CONNECT.		80.00	20.00
	R&R LH FRONT TYRE AND BALANCING.	NOT NECESSARY	100.00	-
	R&R LH FRONT UNDERCARRIAGE.		480.00	100.00
	TO CONDUCT WHEEL ALIGNMENT.		150.00	60.00
	TO APPLY UNDERCOATING FOR RUST ROOFING.	NOT NECESSARY	200.00	-
	SPRAY PAINTING ON ACCIDENT AREA.		1,000.00	400.00
			3,010.00	980.00
GRAND TOTAL			10,072.32	2,430.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,500.00

Report Ref No. CS/SMR21004761/Uuf3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.